

Block

Lot

Qual

Permit #

Permit Date

Cert of Occ Date
or
Cert of Appr Date

Type of Permit

Description of work

Location
Owner

Assessor
Inspected

History File

Building Permits

by Block & Lot

Web Version

Single Line Report: History (All)

Borough Of Milford

JUN 29,2009

11:17AM

David M Gill, CTA
Municipal Assessor

Software Developer: David M Gill, CTA (609) 466-1878

Run: JUN 29,2009 11:17AM

Borough Of Milford
Building Permits by Block / Lot Web Version History

Page: 1

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
Block	1									
1	2		1020-1999-007	APR 21,1999	MAY 5,1999	MAINTENANCE:(roofing,etc)		191 WATER STREET BULLINGHAM, ROY E S		H Not Assessable
1	2		1020-1999-021	JUN 4,1999	SEP 1,2005	BATHROOM	Replace Bathroom Fixtures	191 WATER STREET BULLINGHAM, ROY E S		H Not Assessable
1	2		1020-1999-021+A	JUN 9,1999		MAINTENANCE:(roofing,etc)		191 WATER STREET BULLINGHAM, ROY E S		H Not Assessable
1	2		1020-2005-045	AUG 22,2005	AUG 31,2005	ELECTRICAL		191 WATER STREET BULLINGHAM, ROY E S		H Not Assessable
1	2		1020-2006-033	JUN 20,2006		WATER HEATER		191 WATER STREET BULLINGHAM, ROY E S		H Not Assessable
1	4		1020-1999-029	JUL 6,1999	DEC 2,1999	ELECTRICAL	Trailer Power	171 WATER STREET DURNAN, TERRY J & JAMES I		H Not Assessable
1	4		1020-1999-042	SEP 28,1999	MAY 29,2003	HEATING		171 WATER STREET CLARK, PAUL H		H Not Assessable
1	4		1020-2004-008	FEB 17,2004	APR 20,2004	ELECTRICAL	Service Upgrade	171 WATER STREET CLARK, PAUL H		H Not Assessable
1	4		1020-2004-008+A	MAR 22,2004		COMMERCIAL BUILDING	Temporary Office Trailer	171 WATER STREET CLARK, PAUL H		H Not Assessable
1	4		1020-2004-088	APR 20,2004		ELECTRICAL		171 WATER STREET CLARK, PAUL H		H Not Assessable
1	4		1020-2005-053	AUG 6,2005	JUN 1,2006	TANK INSTALLED INTERIOR		171 WATER STREET CLARK, PAUL H		H Not Assessable
1	4		1020-2005-054	AUG 6,2005		TANK REMOVAL		171 WATER STREET CLARK, PAUL H		H Not Assessable
1	4		1020-2007-066	OCT 10,2007	FEB 11,2008	ROOFING		171 WATER STREET CLARK, PAUL H		H Not Assessable
1	4		1020-2008-054	SEP 19,2008	DEC 2,2008	ROOFING		171 WATER STREET CLARK, PAUL H		H Not Assessable
1	7		1020-2002-019	APR 2,2002	MAR 4,2003	ROOFING / RE-ROOFING	Roofing	151 WATER STREET MILFORD-HOLLAND RESCUE		H Not Assessable
1	7		1020-2003-018	APR 17,2003	OCT 28,2004	TANK INSTALLED INTERIOR		151 WATER STREET MILFORD-HOLLAND RESCUE		H Not Assessable
1	7		1020-2003-019	APR 17,2003	JAN 10,2007	TANK REMOVAL		151 WATER STREET MILFORD-HOLLAND RESCUE		H Not Assessable
1	7		1020-2003-037	JUN 26,2003	JUL 20,2006	PLUMBING WORK		151 WATER STREET MILFORD-HOLLAND RESCUE		H Not Assessable
1	7		1020-2003-049	JUL 18,2003	MAY 25,2005	ELECTRICAL		151 WATER STREET MILFORD-HOLLAND RESCUE		H Not Assessable
1	10		1020-2002-018	JUN 26,2002	APR 17,2003	SHEETROCKING		131 MOUNT NEBO ROAD ALWARD, EDWARD		H Not Assessable
1	11		1020-1995-030	JUL 11,1995	SEP 30,1995	WOOD DECK / CONCR. PATIO		119 HONEYSUCKLE LANE BANTEL, BRIAN R & SYDNEY	SEP 27,1995	H
1	11		1020-1997-100	AUG 21,1997	SEP 22,1998	MAINTENANCE:(roofing,etc)		119 HONEYSUCKLE LANE BANTEL, BRIAN R & SYDNEY		H
1	11		1020-1998-060	OCT 6,1998	JUL 2,1999	MAINTENANCE:(roofing,etc)		119 HONEYSUCKLE LANE BANTEL, BRIAN R & SYDNEY		H Not Assessable

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
1	11		1020-2003-078	MAR 12,2003		PLUMBING WORK		119 HONEYSUCKLE LANE MADSEN, NANCY		H Not Assessable
1	11		1020-2002-078	NOV 4,2002	JUN 18,2003	BASEMENT FINISHED	Finish Basement And 2nd Floor Bath	119 HONEYSUCKLE LANE MADSEN, NANCY & HANS	SEP 6,2005	H Assessable
1	11		1020-2005-047	AUG 26,2005	JUL 21,2006	ELECTRICAL		119 HONEYSUCKLE LANE MADSEN, NANCY & HANS		H Not Assessable
1	12		1020-1993-003	JUL 2,1993	SEP 27,1993	WOOD DECK / CONCR. PATIO	WOOD DECK ON FRONT OF HOUSE	113 HONEYSUCKLE LANE GORDON, ANNALIESE T		H
1	12		1020-1996-019	APR 19,1996	SEP 27,1996	MAINT: (Roofing, etc)		113 HONEYSUCKLE LANE GORDON, ANNALIESE T	SEP 27,1996	H
1	12		1020-1999-009	APR 23,1999	MAY 18,1999	RADON SYSTEM		113 HONEYSUCKLE LANE GORDON, ANNALIESE T		H Not Assessable
1	12		1020-2001-024	APR 11,2001	OCT 21,2003	PORCH: ENCLOSED / OPEN		113 HONEYSUCKLE LANE LYNCH, MICHAEL D & KELLY		H Assessable
1	12		1020-2002-024	APR 26,2002	FEB 13,2003	WOOD DECK	Wood Deck	113 HONEYSUCKLE LANE LYNCH, MICHAEL D & KELLY		H Assessable
1	12		1020-2002-053	JUL 23,2002	APR 4,2003	PATIO		113 HONEYSUCKLE LANE LYNCH, MICHAEL D & KELLY		H Not Assessable
1	13		1020-1991-011+B	FEB 8,1991	OCT 24,1991	POLE BARN	POLE BARN	83 HONEYSUCKLE LANE OSBORNE, ROBERT T & FRAI		H
1	13		1020-1991-011+C	FEB 8,1991	OCT 24,1991	FOR RECORD ONLY !!!!	DETACHED GARAGE	83 HONEYSUCKLE LANE OSBORNE, ROBERT T & FRAI		H
1	13		1020-1994-039	SEP 20,1994	AUG 30,1995	ADDITIONS: MAJOR / MINOR	addition.	83 HONEYSUCKLE LANE OSBORNE, ROBERT T & FRAI		H
1	13		1020-1996-011	OCT 21,1996	OCT 21,1996	Tank Installed Interior		83 HONEYSUCKLE LANE OSBORNE, ROBERT T & FRAI	SEP 8,1997	H
1	13		1020-1996-011+A	MAR 27,1996	MAR 27,1996	TANK REMOVAL	Installation Of 2/330 Gal Oil Tanks	83 HONEYSUCKLE LANE OSBORNE, ROBERT T & FRAI		H
1	13		1020-1996-061	NOV 20,1996	DEC 30,1997	ADDITIONS: MAJOR / MINOR	Build Shed Roof 24 X16 On Side	83 HONEYSUCKLE LANE OSBORNE, ROBERT T & FRAI	SEP 23,1998	H Assessable
1	13		1020-1998-019	AUG 1,1998	AUG 19,1998	POOL: ABOVE GROUND		83 HONEYSUCKLE LANE OSBORNE, ROBERT T & FRAI		H Not Assessable
1	13		1020-2008-005	JAN 30,2008	FEB 11,2008	ELECTRICAL		83 HONEYSUCKLE LANE OSBORNE, ROBERT T & FRAI		H Not Assessable
1	13.01		1020-1999-041	SEP 27,1999	MAR 15,2000	MAINTENANCE:(roofing,etc)		162 MOUNT NEBO ROAD WILSON, THOMAS J & BREND		H Not Assessable
1	14		1020-1992-003+G	JUL 21,1992	JUL 21,1992	HEATING	Install OHW Boiler	107 HONEYSUCKLE LANE LAUBER, JEANNE E		H
1	14		1020-1996-023	APR 30,1996	APR 30,1996	ELECTRICAL	Electric Upgrade	107 HONEYSUCKLE LANE LAUBER, JEANNE E	APR 30,1996	H
1	15		1020-1995-027+A	JUN 9,1995	NOV 14,1995	DEMOLITION OF BUILDING	Demolition Of Structure	103 HONEYSUCKLE LANE COCHRAN, JAMES E & LISA	SEP 28,1996	H
1	15		1020-1995-054	OCT 2,1995	DEC 4,1998	GARAGES: ATTACH / DETACH	Also Deck On Rear Of House	103 HONEYSUCKLE LANE COCHRAN, JAMES E & LISA	SEP 14,1999	H Assessable
1	15		1020-1996-054	SEP 6,1996	DEC 26,1996	ELECTRICAL	Electric To Garage	103 HONEYSUCKLE LANE COCHRAN, JAMES E & LISA	SEP 8,1997	H
1	15		1020-1998-016	OCT 1,1998	OCT 27,1998	WOOD DECK / CONCR PATIO		103 HONEYSUCKLE LANE COCHRAN, JAMES E & LISA	SEP 14,1999	H Assessable

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
1	15		1020-2003-079	NOV 6,2003	MAY 18,2006	RENOVATIONS: MAJOR/SMALL	Entire House Renovation	103 HONEYSUCKLE LANE COCHRAN, JAMES E & LISA		H Assessable
1	16		1020-1994-005	FEB 4,1994	MAR 17,1994	ELECTRICAL	Electrical upgrade	97 HONEYSUCKLE LANE HOPTA, DAVID T & SUSAN M	SEP 26,1995	H
1	16		1020-1996-041	JUL 23,1996	JUL 23,1996	Tank Installed Interior	Installation Of 275 Gal Tank	97 HONEYSUCKLE LANE HOPTA, DAVID T & SUSAN M	JUL 1,1996	H
1	16		1020-1996-041+A	OCT 21,1996	OCT 21,1996	Tank Installed Interior		97 HONEYSUCKLE LANE HOPTA, DAVID T & SUSAN M	SEP 8,1997	H
1	16		1020-2001-067	SEP 25,2001	JUL 10,2003	ALTERATIONS	Alteratios To Front Porch	97 HONEYSUCKLE LANE HOPTA, DAVID T & SUSAN M		H Assessable
1	16		1020-2003-067+C	MAR 15,2003		ADDITIONS: MAJOR / MINOR	Can't Make Permit Out?	97 HONEYSUCKLE LANE HOPTA, DAVID T & SUSAN M		H Assessable
1	17		1020-1994-019	MAY 10,1994	SEP 26,1995	HEATING	Replacement of hot water heater	93 HONEYSUCKLE LANE PURSELL, VERNA B	SEP 26,1995	H
1	17		1020-1996-028	MAY 15,1996	AUG 22,2000	RADON SYSTEM		93 HONEYSUCKLE LANE PURSELL, VERNA B		H
1	17		1020-2006-059	NOV 1,2006	JAN 29,2007	ROOFING		93 HONEYSUCKLE LANE PURSELL, VERNA B		H Not Assessable
1	18		1020-1991-015	NOV 1,1991	SEP 18,1992	RENOVATION; SMALL	INSTALL TUB / LAVATORY	89 HONEYSUCKLE LANE GODOWN, EARL		H
1	18		1020-1991-015+B	NOV 1,1991	SEP 18,1992	RENOVATION; SMALL	INSTALL TUB / LAVATORY	89 HONEYSUCKLE LANE GODOWN, EARL		H
1	18		1020-2000-044	OCT 27,2000	DEC 8,2000	RENOVATIONS: MAJOR/SMALL	Rebuild Existing Sunroom	89 HONEYSUCKLE LANE GODOWN JR, ROBERT L	SEP 27,2001	H Assessable
1	18		1020-2000-049	OCT 30,2000	JUL 13,2001	ELECTRICAL		89 HONEYSUCKLE LANE GODOWN JR, ROBERT L		H Not Assessable
1	18		1020-2001-044	JUN 14,2001	AUG 16,2001	WOOD DECK / CONCR PATIO		89 HONEYSUCKLE LANE GODOWN JR, ROBERT L	SEP 27,2001	H Assessable
1	18		1020-2002-061+A	OCT 16,2002		MAINTENANCE:(roofing,etc)		89 HONEYSUCKLE LANE GODOWN JR, ROBERT L		H Not Assessable
1	18		1020-2007-006	FEB 6,2007	FEB 26,2007	RADON SYSTEM		89 HONEYSUCKLE LANE SUMMERER, DAVID M		H Not Assessable
1	18.01		1020-1995-049	SEP 8,1995	MAY 18,1999	GARAGES: ATTACH / DETACH	SIZE 24 / 30	77 HONEYSUCKLE LANE GODOWN, EARL S & RUTH E	SEP 28,1996	H Assessable
1	18.01		1020-1995-049+A	NOV 6,1995	SEP 27,1996	ELECTRICAL	Electric For Garage	77 HONEYSUCKLE LANE GODOWN, EARL S & RUTH E		H
1	18.01		1020-1996-020	APR 26,1996	JUL 30,1996	RENOVATIONS: MAJOR/SMALL	Remodel Garage To Room 12/20	77 HONEYSUCKLE LANE GODOWN, EARL S & RUTH E	SEP 28,1996	H
1	18.01		1020-2003-064	SEP 5,2003	OCT 7,2003	HEATING		77 HONEYSUCKLE LANE GODOWN, EARL S		H Not Assessable
1	19		1020-1996-016	APR 16,1996	MAY 1,1996	ELECTRICAL	100 Amp Service	81 HONEYSUCKLE LANE PHELPS, R B	SEP 27,1996	H
1	19		1020-2006-055	OCT 13,2006	OCT 19,2006	WATER SERVICE		81 HONEYSUCKLE LANE PHELPS, R B		H Not Assessable
1	20		1020-2001-081	NOV 29,2001	FEB 4,2002	SIDING: VINYL / WOOD		73 HONEYSUCKLE LANE CARVER, HORACE E JR & ES'	SEP 28,2002	H Assessable
1	21		1020-1994-024	JUN 3,1994	MAY 1,1996	ELECTRICAL	.	59 HONEYSUCKLE LANE CARLTON, JOHN & ANN MARI	SEP 26,1995	H

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
1	21		1020-1994-901	DEC 24,1994	SEP 26,1995	ASSESSMENT DATA REVIEW---	Per MLS remodeled kitchen, bath,	59 HONEYSUCKLE LANE STEM, FREDERICK/ GROTENI	SEP 26,1995	H
1	21		1020-1998-076	NOV 20,1998	JAN 11,1999	HEATING		59 HONEYSUCKLE LANE CARLTON, JOHN & ANN MARI		H Not Assessable
1	21		1020-2003-003	JAN 15,2003	APR 15,2005	RADON SYSTEM		59 HONEYSUCKLE LANE CARLTON, JOHN & ANN MARI		H Not Assessable
1	22		1020-2000-009	APR 11,2000		TANK INSTALLED INTERIOR		11 HONEYSUCKLE LANE PHILKILL, STEVEN & JANET		H Not Assessable
1	23		1020-2001-070	OCT 10,2001	JUL 6,2005	ELECTRICAL		59 BRIDGE STREET HANSON, KIMBERLY PAIGE		H Not Assessable
1	25		1020-1992-001+B	MAY 7,1992	SEP 18,1992	COMMERCIAL BUILDING	NEW FROZEN YOGURT STORE	57 BRIDGE STREET PHILKILL, STEVEN & JANET		H
1	25		1020-1992-001+C	APR 21,1992	SEP 18,1992	COMMERCIAL BUILDING	ELECT FOR RETAIL ICE CREAM	57 BRIDGE STREET THIES, WILBUR H C/O PHIL		H
1	25		1020-1992-001+E	SEP 22,1992		COMMERCIAL BUILDING	Hanging sign	57 BRIDGE STREET THIES, WILBUR H C/O PHIL		H
1	25		1020-1999-019+A	FEB 18,1999	FEB 19,1999	RENOVATIONS: MAJOR/SMALL	Change Of Use	57 BRIDGE STREET PHILKILL, STEVEN & JANET	SEP 14,1999	H Not Assessable
1	26		1020-1995-007	FEB 10,1995	SEP 27,1995	PLUMBING WORK	Beauty salon sinks	55 BRIDGE STREET HAHN, R DOUGLAS MD	SEP 27,1995	H
1	26		1020-1995-007+A	MAR 10,1995	FEB 28,1995	MAINTENANCE:(roofing,etc)	Sign for store beauty salon	55 BRIDGE STREET HAHN, R DOUGLAS MD	SEP 27,1995	H
1	26		1020-2008-045	JUL 28,2008	SEP 26,2008	WATER SERVICE	Replace Water Service	55 BRIDGE STREET HAHN MD, R DOUGLAS		H Not Assessable
1	27		1020-1992-003+H	SEP 4,1992		PLUMBING WORK	Install a Lav w/ vac breaker	53 BRIDGE STREET FLECK, REINE C TRUSTEE		H
1	27		1020-1992-003+I	AUG 11,1992		RENOVATIONS: MAJOR/SMALL	Electric outlets for store	53 BRIDGE STREET FLECK, REINE C TRUSTEE		H
1	27		1020-1992-003+L	SEP 15,1992		COMMERCIAL BUILDING	Install sign for building	53 BRIDGE STREET FLECK, REINE C TRUSTEE		H
1	28		1020-2002-039	JUN 28,2002		RENOVATIONS: MAJOR/SMALL		49 BRIDGE STREET HUGHES, ALLEN G & DEBOR/		H Assessable
1	28		1020-2004-040+A	MAY 21,2004	AUG 10,2004	ELECTRICAL		49 BRIDGE STREET HUGHES, ALLEN G & DEBOR/		H Not Assessable
1	29		1020-1992-004+E	OCT 20,1992	SEP 24,1993	ADDITIONS: MAJOR / MINOR	Check to see fencing	45 BRIDGE STREET MILFORD PRESBYTERIAN CH		H
1	29		1020-1993-005+C	OCT 29,1993	JUN 22,1994	RECORD ONLY !!!!	Electric service	45 BRIDGE STREET MILFORD PRESBYTERIAN CH		H
1	29		1020-1994-001+B	MAR 29,1994	MAR 29,1994	NOT ASSESSABLE IMPRVMENT	Fire surpression system	45 BRIDGE STREET MILFORD PRESBYTERIAN CH		H
1	31		1020-1999-027	JUN 17,1999		ALTERATIONS		14 CHURCH STREET LARSEN, ARNE & NEOMA	SEP 27,2000	H Not Assessable
1	31		1020-1999-052	DEC 9,1999	FEB 4,2002	FIREPLACE / WOODSTOVE		14 CHURCH STREET LARSEN, ARNE & NEOMA	SEP 27,2000	H Not Assessable
1	31		1020-2000-024	JUN 8,2000	AUG 18,2000	WOOD DECK / CONCR PATIO		14 CHURCH STREET LARSEN, ARNE & NEOMA	SEP 27,2000	H Assessable
1	31		1020-2001-062+A	AUG 8,2001		WOOD STOVE (PELLET)	Pellet Wood Stove	14 CHURCH STREET LARSEN, ARNE & NEOMA		H Not Assessable

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
1	31		1020-2006-057	OCT 6,2006	NOV 2,2006	TANK REMOVAL		14 CHURCH STREET LARSEN, ARNE & NEOMA		H Not Assessable
1	31		1020-2005-052	SEP 15,2005		TANK INSTALLED INTERIOR		14 CHURCH STREET LARSEN, ARNE & NEOMA		H Not Assessable
1	32		1020-2006-025	MAY 3,2006	SEP 5,2006	SIDING: VINYL / WOOD	Re-Roofing & Siding	18 CHURCH STREET CANTILINA, JOHN S & ALLIS	SEP 12,2006	H Not Assessable
1	32		1020-2007-059	SEP 20,2007		TANK REMOVAL		18 CHURCH STREET CANTILINA, JOHN S & ALLIS		H Not Assessable
1	32		1020-2008-046	AUG 15,2008		HEATING	Replace Steam Boiler	18 CHURCH STREET CANTILINA, JOHN S & ALLIS		H Not Assessable
1	33		1020-2007-051	AUG 20,2007	JAN 7,2009	ROOFING	.	24 CHURCH STREET MARTINO, ALMA C & CARMEN		H Not Assessable
1	34		1020-1992-002+C	JUN 5,1992	JAN 20,1993	RENOVATIONS: MAJOR/SMALL	Renovation to 1 Family Dwelling	29 CHURCH STREET GORDON, ELLEN J		H
1	34		1020-2001-062	AUG 8,2001	SEP 24,2001	WOOD DECK / CONCR PATIO		29 CHURCH STREET GORDON, ELLEN J		H Assessable
1	36		1020-1995-004	JAN 20,1995	MAR 2,1995	HEATING	.	38 CHURCH STREET GALLAGHER, C MICHAEL & SI	SEP 26,1995	H
1	36		1020-2003-010+A	MAR 12,2003	MAY 16,2003	MAINTENANCE:(roofing,etc)		38 CHURCH STREET VAN NEST, GREGORY J & KA'		H Not Assessable
1	36		1020-2006-052	OCT 3,2006	OCT 25,2006	PORCH: ENCLOSED / OPEN		38 CHURCH STREET VAN NEST, GREGORY J & KA'	AUG 28,2007	H Assessable
1	37		1020-1993-0 +F	FEB 19,1993	SEP 28,1993	RENOVATIONS: MAJOR/SMALL	Complete renovation of new kitchen	48 CHURCH STREET UNITED CHURCH OF CHRIST		H
1	37		1020-1993-0 +I	MAR 28,1993		ELECTRICAL	Sub panel in kitchen	48 CHURCH STREET UNITED CHURCH OF CHRIST		H
1	37		1020-1996-005	FEB 20,1996	FEB 20,1996	ELECTRICAL	New Circuit Breaker Panel At Exist.	48 CHURCH STREET UNITED CHURCH OF CHRIST		H
1	37		1020-2001-015	MAR 9,2001	APR 2,2003	AIR CONDITIONING		48 CHURCH STREET UNITED CHURCH OF CHRIST		H Assessable
1	38		1020-2008-024	MAY 14,2008		ELECTRICAL		56 CHURCH STREET LARSEN, ARNE NEOMA & JO		H Not Assessable
1	39		1020-2001-003	JAN 8,2001	JAN 25,2001	TANK INSTALLED INTERIOR		60 SPRING GARDEN STREET MULVEY MICHAEL / EXLEY JI		H Not Assessable
1	39		1020-2002-082	OCT 6,2002	FEB 4,2003	RENOVATIONS: MAJOR/SMALL	Replace 1st Floor Joist System	60 SPRING GARDEN STREET ROSE, ROBERT B & REBECC/		H Assessable
1	39		1020-2003-070	NOV 21,2003		HEATING		60 SPRING GARDEN STREET ROSE, ROBERT B & REBECC/		H Not Assessable
1	39		1020-2003-070+A	SEP 26,2003		RENOVATIONS: MAJOR/SMALL		60 SPRING GARDEN STREET ROSE, ROBERT B & REBECC/		H Assessable
1	39		1020-2005-041	AUG 1,2005	SEP 6,2006	ROOFING		60 SPRING GARDEN STREET ROSE, ROBERT B & REBECC/		H Not Assessable
1	39		1020-2008-003+A	FEB 5,2008		AIR CONDITIONING		60 SPRING GARDEN STREET ROSE, ROBERT B & REBECC/	SEP 4,2008	X Assessable
1	40		1020-1993-003+B	AUG 2,1993	AUG 23,1994	SHEDS: LARGE / SMALL	Storage shed and privacy fence	78 SPRING GARDEN STREET PRZYWARA, PATRICIA A		H
1	40		1020-1996-051	DEC 10,1996	SEP 8,1997	TANK REMOVAL	Removal Of 275 Gallon Tank	78 SPRING GARDEN STREET PRZYWARA, PATRICIA A	SEP 8,1997	H

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
1	40		1020-1996-051+A	OCT 8,1996	SEP 8,1997	Tank Installed Interior	275 Gallon Oil Tank	78 SPRING GARDEN STREET PRZYWARA, PATRICIA A	SEP 8,1997	H
1	40		1020-1997-035	JUL 10,1997	DEC 30,1997	ADDITIONS: MAJOR / MINOR	Family Room, Etc	78 SPRING GARDEN STREET PRZYWARA, PATRICIA A	SEP 23,1998	H Assessable
1	40		1020-2005-056	OCT 5,2005	DEC 5,2006	HEATING		78 SPRING GARDEN STREET PRZYWARA, PATRICIA A		H Not Assessable
1	41		1020-1993-006+A	DEC 28,1993	MAR 17,1994	HEATING	replac boiler	86 SPRING GARDEN STREET UNITED CHURCH OF CHRIST		H
1	41		1020-1995-045	SEP 5,1995	SEP 5,1996	PORCH: ENCLOSED / OPEN	.	86 SPRING GARDEN STREET UNITED CHURCH OF CHRIST	SEP 27,1996	H
1	41		1020-2008-032	JUN 11,2008		BATHROOM	Renovation Of Existing Bathroom	86 SPRING GARDEN STREET UNITED CHURCH OF CHRIST		H Not Assessable
1	42		1020-1998-051	AUG 6,1998	JAN 14,1999	MAINTENANCE:(roofing,etc)		92 SPRING GARDEN STREET SIGRIST, JOHN R		H Not Assessable
1	42		1020-2001-076	OCT 19,2001	FEB 13,2003	ROOFING / RE-ROOFING		92 SPRING GARDEN STREET SIGRIST, JOHN R		H Not Assessable
1	42		1020-2003-031	JUN 2,2003	DEC 2,2003	MAINTENANCE:(roofing,etc)		92 SPRING GARDEN STREET SIGRIST, JOHN R		H Not Assessable
1	42		1020-2003-083	NOV 21,2003		PORCH: ENCLOSED / OPEN	Size: _____ X _____	92 SPRING GARDEN STREET SIGRIST, JOHN R		Assessable
1	42		1020-2004-078	NOV 12,2004	FEB 3,2005	HEATING		92 SPRING GARDEN STREET SIGRIST, JOHN R		H Not Assessable
1	43		1020-1995-019	MAY 12,1995	MAR 9,2001	MAINTENANCE:(roofing,etc)	.	96 SPRING GARDEN STREET WISMER, BETTY JANE	SEP 26,1995	H Not Assessable
1	43		1020-1998-055	AUG 18,1998	SEP 29,1998	HEATING		96 SPRING GARDEN STREET WISMER, BETTY JANE		H Not Assessable
1	45		1020-1997-055	SEP 30,1997	SEP 30,1997	MAINTENANCE:(roofing,etc)		106 SPRING GARDEN STREET MYSZKA RICHARD R & MARIE		H
1	45		1020-1998-057	OCT 1,1998	OCT 21,1998	ELECTRICAL		106 SPRING GARDEN STREET MATTHEWS, MARK J		H Not Assessable
1	45		1020-1998-059	OCT 1,1998	OCT 27,1998	FIREPLACE / WOODSTOVE		106 SPRING GARDEN STREET MATTHEWS, MARK J	SEP 14,1999	H Not Assessable
1	45		1020-1998-057+A	SEP 11,1998		ELECTRICAL		106 SPRING GARDEN STREET MATTHEWS, MARK J		H Not Assessable
1	45		1020-2001-049	JUN 29,2001	SEP 10,2002	RENOVATIONS: MAJOR/SMALL	Repair Porch	106 SPRING GARDEN STREET MATTHEWS, MARK J		H Not Assessable
1	45		1020-2004-039	MAY 21,2004	JUL 7,2004	SIDING: VINYL / WOOD		106 SPRING GARDEN STREET MATTHEWS, MARK J	SEP 3,2004	H Assessable
1	45		1020-2005-003	JAN 13,2005		TANK INSTALLED INTERIOR		106 SPRING GARDEN STREET MATTHEWS, MARK J		H Not Assessable
1	45		1020-2005-004+A	JAN 13,2005	JUL 20,2005	TANK REMOVAL		106 SPRING GARDEN STREET MATTHEWS, MARK J		H Not Assessable
1	45		1020-2005-0003	JAN 13,2005		TANK INSTALLED INTERIOR		106 SPRING GARDEN STREET MATTHEWS, MARK J		H Not Assessable
1	45		1020-2005-004	JAN 13,2005	JUL 20,2005	TANK REMOVAL		106 SPRING GARDEN STREET MATTHEWS, MARK J		H Not Assessable
1	46.01		1020-2004-005	JAN 20,2004	SEP 1,2006	ELECTRICAL		100 SPRING GARDEN STREET KANE, TERESA M		H Not Assessable

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
1	46.01		1020-2007-003	FEB 21,2007	MAR 8,2007	ELECTRICAL	Electric For Bathroom Remodel	100 SPRING GARDEN STREET KANE, TERESA M	AUG 28,2007	H Not Assessable
1	48		1020-2007-023	APR 18,2007	JUN 25,2007	ELECTRICAL	Service Upgrade	144 SPRING GARDEN STREET LARKIN, MARY ANN		H Not Assessable
1	49		1020-1996-012	OCT 21,1996	OCT 21,1996	Tank Installed Interior		301 FAWNWOOD DRIVE STEM, JOHN E & JEWELL D	SEP 8,1997	H
1	49		1020-1996-012+A	APR 2,1996	APR 2,1996	TANK REMOVAL	Removal 1000 Gallon Tank	301 FAWNWOOD DRIVE STEM, JOHN E & JEWELL D		H
1	50		1020-2003-039	JUN 30,2003		PLUMBING WORK		303 FAWNWOOD DRIVE BERRY, THOMAS & JACQUEL		H Not Assessable
1	50		1020-2003-036	JUN 16,2003	NOV 23,2005	POOLS INGROUND: F / G / V	Gunite / Vinyl / Size ???	303 FAWNWOOD DRIVE BERRY, THOMAS & JACQUEL		H Assessable
1	50		1020-2003-045	JUL 7,2003	JAN 15,2004	TANK REMOVAL		303 FAWNWOOD DRIVE BERRY, THOMAS & JACQUEL		H Not Assessable
1	50		1020-2003-085	DEC 21,2003		HEATING	Replace Heating	303 FAWNWOOD DRIVE BERRY, THOMAS & JACQUEL		H Not Assessable
1	50		1020-2003-090	DEC 22,2003		FIRE / SMOKE DETECTOR	Hook Up Of Automatic Sprinkler	303 FAWNWOOD DRIVE BERRY, THOMAS & JACQUEL		H Not Assessable
1	50		1020-2004-041	JUN 7,2004	APR 3,2006	ROOFING		303 FAWNWOOD DRIVE BERRY, THOMAS & JACQUEL		H Not Assessable
1	50		1020-2004-033	MAY 12,2004		DEMOLITION OF BUILDING	Demolition Of Garage	303 FAWNWOOD DRIVE BERRY, THOMAS & JACQUEL	SEP 13,2005	H Not Assessable
1	50		1020-2004-034	MAY 12,2004		ELECTRICAL		303 FAWNWOOD DRIVE BERRY, THOMAS & JACQUEL		H Not Assessable
1	50		1020-2004-061	AUG 27,2004		RENOVATIONS: MAJOR/SMALL	Renov / Alter Of What?? Must Be Com	303 FAWNWOOD DRIVE BERRY, THOMAS & JACQUEL	SEP 6,2006	H Assessable
1	50		1020-2004-061+A	SEP 1,2004		PLUMBING WORK		303 FAWNWOOD DRIVE BERRY, THOMAS & JACQUEL		H Not Assessable
1	50		1020-2004-061+B	SEP 28,2004		ELECTRICAL		303 FAWNWOOD DRIVE BERRY, THOMAS & JACQUEL		H Not Assessable
1	50		1020-2004-080	NOV 16,2004		RENOVATIONS: MAJOR/SMALL		303 FAWNWOOD DRIVE BERRY, THOMAS & JACQUEL	SEP 6,2006	H Assessable
1	51		1020-2002-008	JAN 30,2002	MAR 13,2002	TANK INSTALLED INTERIOR		305 FAWNWOOD DRIVE REISS, ZENAIDE N		H Not Assessable
1	51		1020-2002-009	JAN 30,2002	MAR 1,2002	TANK REMOVAL		305 FAWNWOOD DRIVE REISS, ZENAIDE N		H Not Assessable
1	53		1020-1992-011	AUG 6,1992	AUG 6,1992	SHEDS: LARGE / SMALL	24 x 34 bldg	171 MOUNT NEBO ROAD WOOLAVER, S BRENT		H
1	53		1020-1999-006	APR 15,1999	DEC 8,2004	RENOVATIONS: MAJOR/SMALL	2nd Floor And Bath	171 MOUNT NEBO ROAD MURPHY, BRIAN D		H Assessable
1	53		1020-2003-067+A	SEP 17,2003	JAN 6,2004	MAINTENANCE:(roofing,etc)		171 MOUNT NEBO ROAD MURPHY, BRIAN D		H Not Assessable
1	53		1020-2004-068	SEP 23,2004	JAN 21,2005	BASEMENT FINISHED		171 MOUNT NEBO ROAD MURPHY, BRIAN D	SEP 13,2005	H Assessable
1	54		1020-1993-006	SEP 17,1993		ASSESSMENT DATA REVIEW---	Install 2 275 gallon oil tanks	308 FAWNWOOD DRIVE MAYES, EMMA D		H
1	54		1020-2007-012	MAR 19,2007	FEB 11,2008	RADON SYSTEM		308 FAWNWOOD DRIVE LYSAGHT, EDWARD M & AIDA		H Not Assessable

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
1	54		1020-2007-022	APR 12,2007	APR 17,2007	ELECTRICAL		308 FAWNWOOD DRIVE LYSAGHT, EDWARD M & AIDA		H Not Assessable
1	56		1020-1999-004	MAR 29,1999	SEP 23,1999	WOOD DECK / CONCR PATIO		175 MOUNT NEBO ROAD MURPHY, JOSEPH H	SEP 14,1999	H Assessable
1	56		1020-2001-001	JAN 3,2001	DEC 27,2001	HEATING		175 MOUNT NEBO ROAD MURPHY, JOSEPH H		H Not Assessable
1	57		1020-2003-076	OCT 31,2003	JAN 6,2004	RENOVATIONS: MAJOR/SMALL	Complete House W/ Fin Bsmt	312 FAWNWOOD DRIVE BABBIT, DAVID R & ELIZABE	SEP 13,2005	H Assessable
1	57		1020-2003-060	AUG 27,2003		TANK INSTALLED INTERIOR	2 275 Gal Tanks	312 FAWNWOOD DRIVE OSBORNE, ROBERT & FRANC		H Not Assessable
1	57		1020-2003-066	SEP 9,2003		HEATING	Heating And Air Condition	312 FAWNWOOD DRIVE OSBORNE, ROBERT & FRANC		H Assessable
1	57		1020-2003-071	OCT 2,2003	OCT 15,2003	SIDING: VINYL / WOOD		312 FAWNWOOD DRIVE OSBORNE, ROBERT & FRANC		H Assessable
1	57		1020-2003-076+B	OCT 30,2003	JAN 6,2004	ELECTRICAL		312 FAWNWOOD DRIVE OSBORNE, ROBERT & FRANC		H Not Assessable
1	59		1020-2000-012	APR 18,2000	MAY 11,2000	RADON SYSTEM		322 FAWNWOOD DRIVE ARMSTRONG, JANICE		H Not Assessable
1	59		1020-2008-020	MAY 9,2008		TANK INSTALLED INTERIOR	Tank Installed	322 FAWNWOOD DRIVE ARMSTRONG, JANICE		H Not Assessable
1	59		1020-2008-021	MAY 9,2008		TANK REMOVAL		322 FAWNWOOD DRIVE ARMSTRONG, JANICE		H Not Assessable
1	60		1020-1996-029	MAY 12,1996	AUG 30,1996	PATIO	Patio Of Concrete	176 MOUNT NEBO ROAD HALLORAN, RICHARD F & LOI	SEP 28,1996	H
1	60		1020-1997-047	AUG 11,1997	APR 7,1999	RADON SYSTEM	Install On Sub Slab Ventilation	176 MOUNT NEBO ROAD HALLORAN, RICHARD F & LOI		H Not Assessable
1	60		1020-1999-047+A	MAR 30,1999		RADON SYSTEM		176 MOUNT NEBO ROAD HALLORAN, RICHARD F & LOI		H Not Assessable
1	60		1020-2001-086	DEC 19,2001	APR 15,2005	ELECTRICAL		176 MOUNT NEBO ROAD BUCKLEY, TODD C & CYNTHI		H Not Assessable
1	60		1020-2005-017	MAY 2,2005	APR 6,2006	PORCH: ENCLOSED / OPEN		176 MOUNT NEBO ROAD BUCKLEY, TODD C & CYNTHI	AUG 28,2007	H Not Assessable
1	60.01		1020-1998-043	JUL 21,1998	JAN 21,1999	TANK INSTALLED INTERIOR		166 MOUNT NEBO ROAD BURLEY, HUGH & CHERYL L		H Not Assessable
1	60.01		1020-1998-056	AUG 26,1998	JAN 26,1999	ADDITIONS: MAJOR / MINOR	1 Story W/ Basement Garage	166 MOUNT NEBO ROAD BURLEY, HUGH & CHERYL L		H Assessable
1	60.01		1020-2008-064	MAY 1,2008		WATER SERVICE	Water Service Repair	166 MOUNT NEBO ROAD BURLEY, HUGH & CHERYL L		H Not Assessable
1	60.01		1020-2009-004	FEB 9,2009	FEB 18,2009	HOT WATER HEATER	Hot Water Boiler / Low Water Cut Of	166 MOUNT NEBO ROAD BURLEY, HUGH & CHERYL L		H Not Assessable
1	61		1020-1996-015	APR 16,1996	JUN 30,1996	PATIO	20 X 22 W/ Cement And Flagstone	307 FAWNWOOD DRIVE STEM, JOHN D & REGINA H	SEP 28,1996	H
Block 2										
2	2		1020-1995-050	SEP 14,1995	DEC 30,1996	RENOVATIONS: MAJOR/SMALL	EXISTING STRUCTURE W/ NEW DECK	197 YORK ROAD URQUIDI RAFAEL L/ DAVENPC	SEP 28,1996	H
2	3		1020-1997-039	JUL 15,1997	OCT 1,1998	SIDING: VINYL / WOOD	Vinyl Siding	213 YORK ROAD POOL, JOHN D & MARY	SEP 23,1998	H Not Assessable

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
2	4		1020-1993-0 +E	FEB 9,1993	FEB 17,1994	MAINTENANCE:(roofing,etc)	Roofing & ??	203 YORK ROAD RULE, RAYMOND E JR & LIND		H
2	4		1020-1993-003+D	AUG 3,1993	AUG 1,1993	ELECTRICAL	.	203 YORK ROAD BUSCHMAN, JOHN E / CARBC		H
2	4		1020-1997-063	DEC 16,1997	SEP 22,1998	ELECTRICAL	Correct Code Violations	203 YORK ROAD BUSCHMANN JOHN E / MICH		H
2	5		1020-1993-006+B	NOV 24,1993		ELECTRICAL	HW relay	168-198 PRESTON ROAD PINE CREST VILLAGE ASSOC		H
2	5		1020-1997-062	DEC 1,1997	SEP 23,1998	WOOD DECK / CONCR PATIO	2 Story Deck On Apt Bldg	168-198 PRESTON ROAD PINE CREST VILLAGE ASSOC	SEP 23,1998	H
2	5		1020-1998-013	MAR 23,1998	JUN 22,1998	ADDITIONS: MAJOR / MINOR	Repair/ Renovate Wood Decks	168-198 PRESTON ROAD PINE CREST VILLAGE ASSOC		H Not Assessable
2	5		1020-1998-044	JUL 22,1998	JUL 22,1998	WOOD DECK / CONCR PATIO		168-198 PRESTON ROAD PINE CREST VILLAGE ASSOC		H
2	5		1020-1998-078	DEC 7,1998	DEC 29,1998	PLUMBING WORK		168-198 PRESTON ROAD PINE CREST VILLAGE ASSOC		H Not Assessable
2	5		1020-2001-051	JUL 6,2001	FEB 13,2003	WOOD DECK / CONCR PATIO	Repair To Wood Decks	168-198 PRESTON ROAD PINE CREST VILLAGE ASSOC		H Not Assessable
2	5		1020-2001-054+A	JUL 20,2001	AUG 1,2001	WATER SERVICE		168-198 PRESTON ROAD PINE CREST VILLAGE ASSOC		H Not Assessable
2	5		1020-2003-038+A	JUN 27,2003		RENOVATIONS: MAJOR/SMALL	Repair Renovate Balconys	168-198 PRESTON ROAD PINE CREST VILLAGE ASSOC		H Assessable
2	5		1020-2003-082	NOV 19,2003		RENOVATIONS: MAJOR/SMALL	Replacement Of Rear Balconies	168-198 PRESTON ROAD PINE CREST VILLAGE ASSOC		H Not Assessable
2	6		1020-1999-031	JUL 14,1999	SEP 9,1999	WOOD DECK / CONCR PATIO		152 PARK LANE HOVEY, DONALD		H Assessable
2	6		1020-2006-028	MAY 19,2006	AUG 4,2006	SHEDS: LARGE / SMALL		152 PARK LANE HOVEY, BARBARA ANN		H Not Assessable
2	6.01		1020-2004-054	AUG 13,2004	OCT 28,2004	TANK INSTALLED INTERIOR		179 YORK ROAD CYPHERS, ARTHUR C & KATH		H Not Assessable
2	6.01		1020-2003-058	AUG 21,2003	SEP 9,2003	TANK INSTALLED INTERIOR		179 YORK ROAD CYPHERS, ARTHUR C & KATH		H Not Assessable
2	6.01		1020-2006-037	JUL 14,2006	OCT 24,2006	SIDING: VINYL / WOOD		179 YORK ROAD CYPHERS, ARTHUR C & KATH	AUG 28,2007	H Assessable
2	6.02		1020-1997-045	JUL 28,1997	AUG 30,2009	AIR CONDITIONING	Overhead	169 YORK ROAD SHALLOP, JANET	SEP 9,1997	H
2	6.02		1020-1997-045+A	JUL 29,1997	SEP 8,1997	ELECTRICAL		169 YORK ROAD SHALLOP, JANET	SEP 8,1997	H
2	6.02		1020-1998-068	NOV 2,1998	DEC 16,1998	MAINTENANCE:(roofing,etc)		169 YORK ROAD SHALLOP, JANET		H Not Assessable
2	6.02		1020-1998-068+A	NOV 2,1998		MAINTENANCE:(roofing,etc)		169 YORK ROAD SHALLOP, JANET		H Not Assessable
2	7		1020-2004-075	NOV 1,2004	APR 6,2006	WOOD DECK / CONCR PATIO	Wood Deck 14 X 27	148 PARK LANE PETRO, GREGG	SEP 13,2005	H Assessable
2	7		1020-2005-035	JUL 6,2005	AUG 10,2005	ROOFING		148 PARK LANE PETRO, GREGG		H Not Assessable
2	7		1020-2006-900	APR 19,2006		PENALTY		148 PARK LANE PETRO, GREGG		H Not Assessable

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
2	7.01		1020-1992-0 +A	MAR 27,1992	SEP 18,1992	RENOVATION; SMALL	REFRAME 1/2 OF SHED ROOF	119 YORK ROAD BOROUGH OF MILFORD		H
2	7.01		1020-1992-0 +F	MAR 27,1992	SEP 18,1992	RENOVATION; SMALL	REFRAME 1/2 OF SHED ROOF	119 YORK ROAD BOROUGH OF MILFORD		H
2	7.01		1020-1994-001+I	APR 23,1994		MAINTENANCE:(roofing,etc)	security fence	119 YORK ROAD BOROUGH OF MILFORD		H
2	7.01		1020-1997-043	JUL 28,1997	SEP 8,1997	MAINTENANCE:(roofing,etc)		119 YORK ROAD BOROUGH OF MILFORD	SEP 8,1997	H
2	7.01		1020-1999-023	JUN 9,1999	DEC 21,1999	NEW NON-RESIDENTIAL BLDG		119 YORK ROAD BOROUGH OF MILFORD		H Not Assessable
2	8		1020-1996-014	APR 15,1996	APR 15,1996	RADON SYSTEM	Radon Mitigation System	146 PARK ROAD RACHAL, ALFRED & DEBRA C		H
2	8		1020-1996-042	AUG 2,1996	SEP 30,1996	AIR CONDITIONING		146 PARK ROAD ASHMEN, WILLIAM C & HILAR	SEP 28,1996	H
2	8		1020-2001-058	JUL 25,2001	AUG 1,2001	TANK REMOVAL	Tank Removal / Replaced	146 PARK ROAD MARTINEAU, JOHN A & LAUR,		H Not Assessable
2	9		1020-2002-013	FEB 25,2002		RENOVATIONS: MAJOR/SMALL		154 PARK LANE PEREZ, ARMAND R & JILL A		H Not Assessable
2	9		1020-2002-013+A	MAR 22,2002		RENOVATIONS: MAJOR/SMALL		154 PARK LANE PEREZ, ARMAND R & JILL A		H Assessable
2	9		1020-2002-013+B	MAR 27,2002		FIRE / SMOKE DETECTOR		154 PARK LANE PEREZ, ARMAND R & JILL A		H Not Assessable
2	9		1020-2003-042	JUL 7,2003	SEP 1,2006	PLUMBING WORK		154 PARK LANE PEREZ, ARMAND R & JILL A		H Not Assessable
2	10		1020-1995-057	OCT 31,1995	FEB 13,1996	HEATING		160 PRESTON ROAD SINKBEIL, RICHARD		H
2	10		1020-2004-052	AUG 6,2004	OCT 18,2004	WATER SERVICE		160 PRESTON ROAD SINKBEIL, RICHARD		H Not Assessable
Block	3									
3	1		1020-1996-043	AUG 5,1996	NOV 20,1996	SIDING: VINYL / WOOD	Misc: Shingles, Siding, New Front	159 PRESTON ROAD FLECK, MARIE M	SEP 28,1996	H
3	1		1020-1997-034	JUL 1,1997	SEP 8,1997	HEATING		159 PRESTON ROAD FLECK, MARIE M	SEP 8,1997	H
3	1		1020-2009-018	JUN 1,2009		ELECTRICAL	Service Upgrade	159 PRESTON ROAD MONTANYE, DANIEL C & SAR.		H Not Assessable
3	2		1020-1993-001+E	MAR 9,1993	SEP 28,1993	RENOVATIONS: MAJOR/SMALL	Remodel Kitchen	155 PRESTON ROAD GODOWN, ROBERT L JR		H
3	2		1020-1993-001+F	MAY 18,1993	SEP 28,1993	RENOVATIONS: MAJOR/SMALL	MAJOR RENOVATIONS IN HOUSE	155 PRESTON ROAD GODOWN, ROBERT L JR		H
3	3		1020-1994-001	APR 4,1994		MAINTENANCE:(roofing,etc)	Repair collapsed roof	149 PRESTON ROAD RODWELLER, CARL E JR & C,		H
3	3		1020-1994-003+A	AUG 4,1994		MAINTENANCE:(roofing,etc)		149 PRESTON ROAD RODWELLER, CARL E JR & C,		H
3	3		1020-1994-031	JUL 19,1994	MAY 18,1999	PORCH: ENCLOSED / OPEN		149 PRESTON ROAD RODWELLER, CARL E JR & C,	SEP 28,1996	H Assessable
3	3		1020-2004-037	MAY 12,2004	SEP 7,2004	WOOD DECK / CONCR PATIO	Second Story	149 PRESTON ROAD JONES, CONSTANCE M	SEP 13,2005	H Assessable

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
3	4		1020-2003-054	OCT 27,2003	SEP 10,2003	HEATING		145 PRESTON ROAD MURRAY III, JOHN J		H Not Assessable
3	4		1020-2005-008	FEB 18,2005	JUL 22,2005	SIDING: VINYL / WOOD		145 PRESTON ROAD VASTOLA, LOUIS A & DENISE	SEP 13,2005	H Assessable
3	5		1020-1995-042	AUG 22,1995	SEP 9,1997	GARAGES: ATTACH / DETACH	Size: 24 x 30	141 PRESTON ROAD HEUER, LARRY E & FRANCES	SEP 9,1997	H
3	6		1020-2001-082	NOV 29,2001	JAN 24,2002	ROOFING / RE-ROOFING		130-132 WATER STREET CORNELIUS, RICHARD C & T/		H Not Assessable
3	6.01		1020-1998-020	AUG 1,1998		RENOVATIONS: MAJOR/SMALL		111, 121 PRESTON ROAD ADAMS, CHRISTINE	SEP 14,1999	H Not Assessable
3	6.01		1020-2001-025	APR 6,2001	DEC 10,2001	PORCH: ENCLOSED / OPEN	Replace Front Porch	111-121 PRESTON ROAD ADAMS, CHRISTINE	SEP 27,2001	H Assessable
3	7		1020-2000-051+B	NOV 6,2000		RADON SYSTEM		131 PRESTON ROAD LORENZI, MICHAEL J & LETT		H Not Assessable
Block	3.01									
3.01	1		1020-1995-028	JUN 13,1995	DEC 30,1995	ALTERATIONS	Install York Condenser	158 PRESTON ROAD MILLER, ROBERT C	SEP 28,1996	H
3.01	1		1020-1995-061	DEC 12,1995	SEP 9,1997	ELECTRICAL	Install Wiring For Bathroom In Bsmt	158 PRESTON ROAD MILLER, ROBERT C	SEP 9,1997	H
3.01	1		1020-2002-017	MAR 14,2002		PATIO ROOM (SUNROOM)	12 X 13 On Wood Deck	158 PRESTON ROAD MILLER, ROBERT C	SEP 28,2002	H Assessable
3.01	1		1020-2002-017+A	APR 9,2002		PLUMBING REPAIR		158 PRESTON ROAD MILLER, ROBERT C		H Not Assessable
3.01	1		1020-2002-017+B	APR 11,2002		PROPANE TANK INSTALLED		158 PRESTON ROAD MILLER, ROBERT C		H Not Assessable
3.01	1		1020-2005-067	NOV 15,2005	MAY 31,2006	HOT WATER HEATER		158 PRESTON ROAD MILLER, ROBERT C		H Not Assessable
3.01	2		1020-1996-048	SEP 5,1996	DEC 30,1996	SIDING: VINYL / WOOD		150 PRESTON ROAD ROBINSON, JUNE R	SEP 9,1997	H Assessable
3.01	3		1020-2000-022	JUN 1,2000	JUL 10,2003	POOL: ABOVE GROUND		148 PRESTON ROAD DRZEWOSZEWSKI, STEPHEN		H Not Assessable
3.01	5		1020-1992-003+D	SEP 8,1992	DEC 22,1992	ADDITIONS: MAJOR / MINOR	Bathroom addition on rear of resid.	138 PRESTON ROAD KESSEL, MICHAEL JR & MARJ		H
3.01	5		1020-2005-002	JAN 4,2005	NOV 29,2005	ROOFING		138 PRESTON ROAD KESSEL, MICHAEL JR & MARJ		H Not Assessable
3.01	5		1020-2005-005	JAN 4,2005		ROOFING		138 PRESTON ROAD KESSEL, MICHAEL JR & MARJ		H Not Assessable
3.01	6		1020-2001-017	MAR 12,2001	APR 20,2001	HEATING	Complete HWBB Heating System	145 PARK LANE GALLOS, JAMES A & MARGAF	SEP 27,2001	H Assessable
3.01	6		1020-2003-065	SEP 5,2003	MAY 23,2005	MAINTENANCE:(roofing,etc)		145 PARK LANE GALLOS, JAMES A & MARGAF		H Not Assessable
3.01	7		1020-2002-069	OCT 18,2002	FEB 24,2003	MAINTENANCE:(roofing,etc)		147 PARK LANE YOUNGKEN, ESTHER J		H Not Assessable
3.01	8		1020-1993-005+D	OCT 1,1993	FEB 24,1995	ASSESSMENT DATA REVIEW---	Re-roofing	149 PARK LANE BUSH, RUNKLE F		H
3.01	8		1020-2007-043+A	AUG 20,2007		ELECTRICAL		149 PARK LANE BUSH, RUNKLE F		H Not Assessable

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
3.01	8		1020-2007-043	JUL 16,2007	SEP 24,2007	AIR CONDITIONING		149 PARK LANE BUSH, RUNKLE F	SEP 4,2008	X Assessable
3.01	8		1020-2007-149	SEP 13,2007		PENALTY		149 PARK LANE BUSH, RUNKLE F		H Not Assessable
3.01	8		1020-2007-150	SEP 13,2007		PENALTY		149 PARK LANE BUSH, RUNKLE F		H Not Assessable
3.01	9		1020-2006-001	JAN 4,2006	SEP 5,2006	MISC ITEMS	Front Porch Steps. Windows Sliding	153 PARK LANE DEEMER, GARY & RENEE		H Not Assessable
3.01	9		1020-2005-075	DEC 19,2005	JUN 23,2006	ELECTRICAL		153 PARK LANE DEEMER, GARY & RENEE		H Not Assessable
3.01	9		1020-2006-041	AUG 8,2006	SEP 5,2006	SIDING: VINYL / WOOD		153 PARK LANE DEEMER, GARY & RENEE	AUG 28,2007	H Assessable
3.01	9		1020-2006-043	AUG 11,2006	SEP 5,2006	ROOFING		153 PARK LANE DEEMER, GARY & RENEE		H Not Assessable
Block	4									
4	8		1020-2004-024+A	APR 26,2004	SEP 20,2004	ELECTRICAL		89 HONEYSUCKLE LANE GODOWN JR, ROBERT L		H Not Assessable
4	9		1020-1991-014+B	SEP 17,1991	MAR 30,1992	ADDITION: MINOR	SIDING + NEW PORCH	97 WATER STREET BEANE, CAROL		H
4	9		1020-1995-060	NOV 27,1995	DEC 12,1995	MAINT: (Roofing, etc)		97 WATER STREET BEANE, CAROL		H
4	9		1020-1999-037+A	AUG 10,1999		HEATING		97 WATER STREET BEANE, CAROL		H Not Assessable
4	9		1020-2007-005	FEB 5,2007	MAY 21,2007	DEMOLITION OF BUILDING		97 WATER STREET BEANE, CAROL	AUG 28,2007	H Assessable
4	11		1020-1995-055	OCT 3,1995	APR 15,1997	HEATING		89 WATER STREET SHERIDAN JR, ORMOND P		H
4	11		1020-2007-024	APR 24,2007	MAY 15,2007	SHED: LARGE		89 WATER STREET GREENE, ROGER	AUG 28,2007	H Assessable
4	12		1020-1993-004	AUG 17,1993	SEP 27,1994	SHEDS: LARGE / SMALL	small: 8 x 16	85 WATER STREET CORRADO, PAUL L & DARCY		H
4	12		1020-1994-001+F	MAY 6,1994	SEP 27,1994	MAINTENANCE:(roofing,etc)	Re-roofing	85 WATER STREET CORRADO, PAUL L & DARCY		H
4	12		1020-1994-040	SEP 16,1994	SEP 21,1994	ELECTRICAL		85 WATER STREET CORRADO, PAUL L & DARCY	SEP 26,1995	H
4	12		1020-2005-023	MAY 26,2005	JUL 22,2005	BATHROOM		85 WATER STREET CORRADO, PAUL L & DARCY	SEP 12,2006	H Assessable
4	16		1020-1998-057+B	OCT 1,1998	OCT 21,1998	SIDING: VINYL / WOOD		67 WATER STREET ST EDWARDS CHURCH		H Not Assessable
4	16		1020-2003-017	APR 17,2003	APR 14,2003	HEATING	Heater Replacement	67 WATER STREET ST EDWARDS CHURCH		H Not Assessable
4	18		1020-1998-040	JUL 8,1998	JUL 8,1998	TANK INSTALLED INTERIOR		WATER STREET ST EDWARDS CHURCH		H
4	18		1020-1998-064	OCT 16,1998	FEB 5,1999	TANK REMOVAL		WATER STREET ST EDWARDS CHURCH		H Not Assessable
4	18		2005-1020-0005	JAN 20,2005		PLUMBING WORK		WATER STREET ST EDWARDS CHURCH		H Not Assessable

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
4	18		1020-2005-005+B	JAN 20,2005		PLUMBING WORK		WATER STREET ST EDWARDS CHURCH		H Not Assessable
4	19		1020-1996-060	NOV 12,1996	DEC 2,1996	HEATING	Installation Of Thermo Pride	49 WATER STREET MAYERS, GERARD E & BETTE	SEP 8,1997	H
4	19		1020-1997-032	OCT 1,1997	OCT 26,1998	WOOD DECK / CONCR PATIO		49 WATER STREET MAYERS, GERARD E & BETTE	SEP 14,1999	H Assessable
4	19		1020-1999-005	APR 8,1999	DEC 6,1999	RENOVATIONS: MAJOR/SMALL	Sheetrock Hallway W/ Firerated	49 WATER STREET MAYERS, GERARD E & BETTE		H Not Assessable
4	20		1020-1997-013	APR 14,1997	MAY 2,1997	ELECTRICAL		47 WATER STREET BELLIS, ARLENE	SEP 8,1997	H
4	20		1020-1997-019	APR 25,1997	JUL 16,1997	MAINTENANCE:(roofing,etc)	Removing Slate, Re-Roof	47 WATER STREET BELLIS, ARLENE	SEP 8,1997	H
4	21		1020-2001-060	AUG 1,2001	SEP 24,2001	RENOVATIONS: MAJOR/SMALL	Reinforce Beam In Basment	41 WATER STREET MONINGHOFF, GERALD		H Not Assessable
4	21		1020-2005-025	SEP 7,2005	FEB 18,2009	TANK INSTALLED INTERIOR	Abv Grd Tank 330 Gal	41 WATER STREET LAVAN JR, JAMES		H Not Assessable
4	22		1020-1996-064	DEC 18,1996	SEP 8,1997	MAINTENANCE:(roofing,etc)	Leaking Roof Needs To Repaired	35 WATER STREET MONINGHOFF, SCOTT S	SEP 8,1997	H
4	22		1020-2005-026	JUN 7,2005		TANK REMOVAL		35 WATER STREET MONINGHOFF, SCOTT S		H Not Assessable
4	22		1020-2005-077	DEC 27,2005	MAY 19,2006	HEATING		35 WATER STREET MONINGHOFF, SCOTT S		H Not Assessable
4	22		1020-2005-077+A	MAR 16,2005	MAR 16,2006	HOT WATER HEATER		35 WATER STREET MONINGHOFF, SCOTT S		H Not Assessable
4	22		1020-2007-002	FEB 1,2007	MAY 15,2007	WOOD DECK		35 WATER STREET MONINGHOFF, SCOTT S	AUG 28,2007	H Assessable
4	23		1020-1991-004	JUN 4,1991	SEP 18,1992	RENOVATION; MAJOR	REPLACE FIXTURE /PIPING	33 WATER STREET THYGESEN PER & DIANA / E		H
4	23		1020-1994-055	NOV 18,1994	JAN 27,1995	HEATING	HWBB	33 WATER STREET THYGESEN PER & DIANA / E	SEP 26,1995	H
4	23		1020-1997-040	JUL 22,1997	SEP 8,1997	HEATING	Propane Boiler	33 WATER STREET THYGESEN PER & DIANA / E	SEP 8,1997	H
4	24		1020-1994-053	NOV 10,1994	JUN 30,1995	WOOD DECK / CONCR. PATIO	14 x 22	31 WATER STREET PATTERSON, DONALD & JO A	SEP 26,1995	H
4	24		1020-1998-052	AUG 12,1998	OCT 21,1998	SIDING: VINYL / WOOD		31 WATER STREET PATTERSON, DONALD & JO A	SEP 14,1999	H Not Assessable
4	24		1020-2003-041	JUL 1,2003	OCT 5,2005	POOL: ABOVE GROUND		31 WATER STREET UGHETTA, KEVIN A & AMY D		H Not Assessable
4	24		1020-2005-051	SEP 14,2005		ELECTRICAL		31 WATER STREET UGHETTA, KEVIN A & AMY D		H Not Assessable
4	27		1020-1993-003+C	JUL 30,1993	SEP 2,1993	ELECTRICAL	NO OTHER NOTE THAN ELECTRICAL	27 WATER STREET PATRICK, WILLARD T		H
4	27		1020-2001-030	APR 26,2001	FEB 22,2002	TANK REMOVAL		27 WATER STREET STOUFFER, CRAIG		H Not Assessable
4	28		1020-1996-065	DEC 19,1996	SEP 8,1997	RENOVATIONS: MAJOR/SMALL	Hood Exhaust System	21 WATER STREET MILFORD FIRE COMPANY	SEP 8,1997	H
4	28		1020-1999-019	JUN 3,1999	AUG 16,1999	AIR CONDITIONING		21 WATER STREET MILFORD FIRE COMPANY		H Not Assessable

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
4	28		1020-1999-013	JUN 1,1999	JUN 14,1999	TANK INSTALLED INTERIOR		21 WATER STREET MILFORD FIRE COMPANY		H Not Assessable
4	28		1020-2005-010	MAR 4,2005		ELECTRICAL		21 WATER STREET MILFORD FIRE COMPANY		H Not Assessable
4	28		1020-2005-010+C	APR 28,2005		ELECTRICAL		21 WATER STREET MILFORD FIRE COMPANY		H Not Assessable
4	28		1020-2007-036	JUN 28,2007	FEB 19,2008	GENERATOR		21 WATER STREET MILFORD FIRE COMPANY		H Not Assessable
4	29		1020-2001-028	APR 18,2001	MAY 22,2001	MAINTENANCE:(roofing,etc)		14 CREEK ROAD KERL, N PETER		H Not Assessable
4	31		1020-1994-035	SEP 9,1994	OCT 21,1994	MAINTENANCE:(roofing,etc)		11 WATER STREET KERL, N PETER	SEP 26,1995	H
4	31		1020-2000-030	JUN 28,2000	JUL 13,2000	MAINTENANCE:(roofing,etc)		11 WATER STREET KERL, N PETER		H Not Assessable
4	31		1020-2001-006	FEB 7,2001	FEB 26,2001	ELECTRICAL	Install Light Fixtures	11 WATER STREET KERL, N PETER		H Not Assessable
4	31		1020-2002-054	JUL 26,2002		HEATING		11 WATER STREET KERL, N PETER		H Not Assessable
4	31		1020-2003-025	MAY 6,2003	AUG 4,2003	RENOVATIONS: MAJOR/SMALL	Tenant Fit Up For Curves For	11 WATER STREET KERL, N PETER		H Assessable
4	31		1020-2003-025+A	JUN 23,2003		AIR CONDITIONING	Wrong Block And Lot	11 WATER STREET KERL, N PETER		H Assessable
4	32		1020-1992-900	JAN 24,1992	SEP 18,1992	HEATING	BOILER REPLACEMENT	67 BRIDGE STREET DIXON, WILLIAM JR & KELLY		H
4	32		1020-2001-009	FEB 16,2001	MAR 8,2001	ELECTRICAL		67 BRIDGE STREET DIXON, WILLIAM JR & KELLY		H Not Assessable
4	32		1020-2002-084	DEC 9,2002	MAY 13,2003	SIDING: VINYL / WOOD		67 BRIDGE STREET DIXON, WILLIAM JR & KELLY		H Assessable
4	34		1020-1994-023	MAY 25,1994	MAR 30,1995	RENOVATIONS: MAJOR/SMALL	Major renovation including	21 BRIDGE STREET HALL, DAVID & GLORIA A	SEP 27,1994	H
4	34		1020-1994-041	SEP 23,1994	MAR 30,1995	HEATING		21 BRIDGE STREET HALL, DAVID & GLORIA A	SEP 27,1995	H
4	34		1020-1994-043	OCT 3,1994	MAR 31,1995	RENOVATIONS: MAJOR/SMALL	renovate/rebuild existing structure	21 BRIDGE STREET HALL, DAVID & GLORIA A	SEP 27,1995	H
4	34		1020-1995-043	APR 21,1995	MAR 31,1995	ASSESSMENT DATA REVIEW---	states plumbing, fire protection	21 BRIDGE STREET HALL, DAVID & GLORIA A	SEP 27,1995	H
4	34		1020-1998-077	NOV 23,1998	JAN 13,1999	HEATING		21 BRIDGE STREET HALL, DAVID & GLORIA A		H Not Assessable
4	34		1020-1998-073	NOV 9,1998	JAN 10,2002	MAINTENANCE:(roofing,etc)		21 BRIDGE STREET HALL, DAVID & GLORIA A		H Not Assessable
4	34		1020-2002-033	JUN 12,2002	APR 2,2003	ELECTRICAL		61 BRIDGE STREET HALL, DAVID & GLORIA A		H Not Assessable
4	34		1020-2002-033+A	DEC 12,2002		ELECTRICAL	Replace Fire Damaged Wires	61 BRIDGE STREET HALL, DAVID & GLORIA A		H Not Assessable
4	34		1020-2007-072	DEC 4,2007		FIRE DETECTOR		61 BRIDGE STREET HALL, DAVID & GLORIA A		H Not Assessable

Block **5**

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
5	1		1020-2009-020	JUN 4,2009		ELECTRICAL	.	96 WATER STREET A & L OIL COMPANY		H Not Assessable
5	3		1020-1991-013+A	JUL 19,1991	SEP 18,1992	COMMERCIAL BUILDING	CONVERT SPACE TO OFFICE	92 WATER STREET OTOOLE, HENRY M		H
5	3		1020-2002-052	JUL 23,2002	FEB 24,2003	SIDING: VINYL / WOOD		92 WATER STREET OTOOLE, HENRY M	SEP 22,2003	H Not Assessable
5	3		1020-2004-050	JUL 27,2004	JAN 30,2009	ELECTRICAL	.	92 WATER STREET MISE EN PLACE REAL ESTAT		H Not Assessable
5	3		1020-2005-050	AUG 6,2005		ADDITIONS: MAJOR / MINOR		92 WATER STREET MISE EN PLACE REAL ESTAT	SEP 12,2006	H Assessable
5	3		1020-2004-083	NOV 23,2004	JAN 30,2009	FIRE DETECTOR	.	92 WATER STREET MISE EN PLACE REAL ESTAT		H Not Assessable
5	3		1020-2005-004+B	FEB 15,2005	JUL 20,2005	HEATING		92 WATER STREET MISE EN PLACE REAL ESTAT		H Not Assessable
5	3		1020-2004-0050	FEB 28,2004		SIGN		92 WATER STREET MISE EN PLACE REAL ESTAT		H Not Assessable
5	3		1020-2007-065	OCT 5,2007	OCT 27,2008	ELECTRICAL	.	92 WATER STREET MISE EN PLACE REAL ESTAT		H Not Assessable
5	3		1020-2007-065+A	OCT 12,2007	OCT 27,2008	ELECTRICAL	.	92 WATER STREET MISE EN PLACE REAL ESTAT		H Not Assessable
5	4		1020-2000-052	NOV 17,2000	JAN 22,2001	MAINTENANCE:(roofing,etc)		103 MILL STREET FOUSE, ROBERT G & DEBOR.		H Not Assessable
5	4		1020-2003-014+A	APR 2,2003	MAY 19,2003	RENOVATIONS: MAJOR/SMALL	Bathroom Renovation	103 MILL STREET FOUSE, ROBERT G & DEBOR.	SEP 13,2005	H Assessable
5	4		1020-2004-077	NOV 12,2004	MAR 1,2005	ADDITIONS: MAJOR / MINOR		103 MILL STREET FOUSE, ROBERT G & DEBOR.	SEP 13,2005	H Assessable
5	4		1020-2004-079	NOV 16,2004	DEC 10,2004	ELECTRICAL		103 MILL STREET FOUSE, ROBERT G & DEBOR.		H Not Assessable
5	4		1020-2006-012	FEB 21,2006	NOV 21,2006	RENOVATIONS: MAJOR/SMALL	Remove Existing Room Replace	103 MILL STREET FOUSE, ROBERT G & DEBOR.	SEP 12,2006	H Assessable
5	4		1020-2006-011	FEB 25,2006	MAR 28,2006	DEMOLITION OF BUILDING		103 MILL STREET FOUSE, ROBERT G & DEBOR.		H Not Assessable
5	4		1020-2006-012+A	APR 7,2006		SIDING: VINYL / WOOD		103 MILL STREET FOUSE, ROBERT G & DEBOR.	SEP 12,2006	H Assessable
5	5		1020-1992-004	NOV 11,1992		HEATING	Replace O H W Boiler	90 WATER STREET LECH, STANLEY & LAURA		H
5	5		1020-2004-019	SEP 1,2004	SEP 21,2005	SIDING: VINYL / WOOD		90 WATER STREET MASTRAN, LAUREL	SEP 12,2006	H Assessable
5	5		1020-2004-032	MAY 5,2004	JUN 25,2004	TANK INSTALLED INTERIOR		90 WATER STREET SCHADE, CHARLES B		H Not Assessable
5	6.01		1020-1995-039	AUG 8,1995		MAINTENANCE:(roofing,etc)	.	97 MILL STREET CAVITCH, KELLI ANN / COSG		H
5	6.01		1020-1995-039+A	AUG 8,1995	JUL 25,1996	RENOVATIONS: MAJOR/SMALL	Interior renovations: 2nd fllor	97 MILL STREET CAVITCH, KELLI ANN / COSG	SEP 28,1996	H
5	6.01		1020-1996-039	JUL 12,1996	JUL 12,1996	ELECTRICAL		97 MILL STREET CAVITCH, KELLI ANN / COSG		H
5	7		1020-1994-013	APR 8,1994	FEB 24,1995	MAINTENANCE:(roofing,etc)	??? can't make permit out	79 MILL STREET PURSELL, EARL	SEP 26,1995	H

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
5	8		1020-1998-026	JUN 11,1998	MAY 13,2003	ALTERATIONS	1st Floor Apartment??	74 WATER STREET WOLVEN, EDWARD E & HEAT	SEP 14,1999	H Not Assessable
5	8		1020-1998-027	JUN 11,1998	MAY 13,2003	ELECTRICAL		74 WATER STREET WOLVEN, EDWARD E & HEAT		H
5	8		1020-1998-028	JUN 11,1998	JUN 11,1998	MAINTENANCE:(roofing,etc)		74 WATER STREET WOLVEN, EDWARD E & HEAT		H
5	8.01		1020-1992-002	JUN 17,1992	JUL 30,1992	AIR CONDITIONING	Add A/C System to presnet furnace	73 MILL STREET JOHNSON, CARL A & PAULINE		H
5	8.01		1020-2007-031	JUN 14,2007	JUL 5,2007	ROOFING		73 MILL STREET JOHNSON, KENNETH W & BR		H Not Assessable
5	10		1020-1995-062	DEC 12,1995	APR 15,1996	TANK REMOVAL	Replace Basement Home Heating	WATER STREET ST EDWARDS CHURCH		H
5	10		1020-1996-018	APR 18,1996	MAR 20,1997	MAINT: (Roofing, etc)		WATER STREET ST EDWARDS CHURCH		H
5	10		1020-1997-052	SEP 17,1997	SEP 22,1998	MAINTENANCE:(roofing,etc)		WATER STREET ST EDWARDS CHURCH		H
Block 6										
6	1		1020-1993-005+I	OCT 4,1993	OCT 29,1993	ELECTRICAL	Change fuse panel to breaker panel	WATER STREET ST EDWARDS CHURCH		H
6	1		1020-1998-014	MAR 23,1998	MAY 7,1998	ADDITIONS: MAJOR / MINOR	Install Wood Door/	WATER STREET ST EDWARDS CHURCH		H
Block 7										
7	1		1020-1993-004+C	AUG 3,1993	SEP 27,1994	HEATING	Replace DHW Boiler	210 YORK ROAD SUTTON, ROBERT R		H
7	1		1020-1999-034	JUL 28,1999	MAR 1,2000	MAINTENANCE:(roofing,etc)		210 YORK ROAD SUTTON, ROBERT R		H Not Assessable
7	6		1020-2000-018	MAY 24,2000	OCT 27,2000	ELECTRICAL		371 MILFORD-MT PLEA ROAD HUNTERDON MED CTR C/O F		H Not Assessable
7	6		1020-2002-005	JAN 14,2002		TANK REMOVAL		371 MILFORD-MT PLEA ROAD HUNTERDON MED CTR C/O G		H Not Assessable
7	6.01		1020-1993-0 +D	JAN 22,1993	APR 18,1995	ADDITIONS: MAJOR / MINOR	Review kitchen	401 MILFORD-MT PLEA ROAD WEST HUNTERDON VETERAI		H
7	6.01		1020-2000-051	JUL 3,2000	DEC 26,2000	FIRE / SMOKE DETECTOR		401 MILFORD-MT PLEA ROAD GRACE FELLOWSHIP EVANG		H Not Assessable
7	6.01		1020-1999-051	DEC 8,1999	MAY 14,2003	ALTERATIONS	Interior Partitions/ Lavatory	401 MILFORD-MT PLEA ROAD GRACE FELLOWSHIP EVANG		H Not Assessable
7	6.01		1020-2000-051+A	MAR 13,2000		PLUMBING WORK		401 MILFORD-MT PLEA ROAD GRACE FELLOWSHIP EVANG		H Not Assessable
7	6.01		1020-2001-068	SEP 25,2001	FEB 13,2003	ROOFING / RE-ROOFING		401 MILFORD-MT PLEA ROAD GRACE FELLOWSHIP EVANG		H Not Assessable
7	6.01		1020-2002-086	DEC 13,2002	MAY 13,2003	AIR CONDITIONING	Remove And Replac Hvac	401 MILFORD-MT PLEA ROAD GRACE FELLOWSHIP EVANG		H Assessable
7	6.01		1020-2006-056	OCT 16,2006		ELECTRICAL	Conduit Sign Light	401 MILFORD-MT PLEA ROAD GRACE FELLOWSHIP EVANG		H Not Assessable
7	6.01		1020-2008-035	JUN 20,2008	FEB 6,2009	RENOVATIONS: MAJOR/SMALL	Bathroom Fixtures Replaced	401 MILFORD-MT PLEA ROAD GRACE FELLOWSHIP EVANG		H Not Assessable

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
7	6.01		1020-2009-005	FEB 10,2009		SIGN	Install New Sign	401 MILFORD-MT PLEA ROAD GRACE FELLOWSHIP EVANG		H Not Assessable
7	7		1020-2000-008	MAR 30,2000	JUL 5,2000	TANK INSTALLED INTERIOR		377 MILFORD-MT PLEA ROAD BEIDELMAN, MARY C		H Not Assessable
7	7		1020-2003-028	MAY 13,2003	APR 12,2006	MAINTENANCE:(roofing,etc)	Permit Not Clearly Legitable	377 MILFORD-MT PLEA ROAD BEIDELMAN, MARY C		H Not Assessable
7	8		1020-1995-027	JUN 12,1995	DEC 30,1996	AIR CONDITIONING	Air Conditioning W/ Ductwork	10 PHYLLIS LANE BUCK SR, ANTHONY P SR	SEP 28,1996	H
7	8		1020-1997-038	JUL 15,1997	SEP 8,1997	HEATING	Repl Boiler	10 PHYLLIS LANE BUCK SR, ANTHONY P SR	SEP 8,1997	H
7	9		1020-2005-076+A	NOV 13,2005	FEB 23,2007	NEW----RESIDENCE		349 MILFORD-MT PLEA ROAD MEYER, CHARLES S JR & MIS	AUG 28,2007	X Assessable
7	9		1020-2007-044	JUL 9,2007		BURGLAR ALARM		349 MILFORD-MT PLEA ROAD MEYER, CHARLES S JR & MIS		H Not Assessable
7	12		1020-1992-004+B	OCT 27,1992	DEC 11,1992	ELECTRICAL	New 200 amp service	331 MILFORD-MT PLEA ROAD CAMPBELL, DONALD G		H
7	12		1020-1997-028	MAY 21,1997	SEP 8,1997	TANK REMOVAL		331 MILFORD-MT PLEA ROAD CAMPBELL, DONALD G	SEP 8,1997	H
7	12		1020-1997-028+A	JUN 26,1997	SEP 8,1997	Tank Installed Interior	275 Gallon	331 MILFORD-MT PLEA ROAD CAMPBELL, DONALD G	SEP 8,1997	H
7	13		1020-1993-005+B	NOV 12,1993	AUG 11,1994	ADDITIONS: MAJOR / MINOR	2nd floor dormer on bak of house	303 MILFORD-MT PLEA ROAD ROUNSAVILLE, RONALD		H
7	13		1020-1993-005+K	NOV 19,1993	AUG 11,1994	ELECTRICAL	electrical on addition	303 MILFORD-MT PLEA ROAD ROUNSAVILLE, RONALD		H
7	13		1020-2000-057	DEC 6,2000	JAN 26,2001	RADON SYSTEM		303 MILFORD-MT PLEA ROAD ROUNSAVILLE, RONALD		H Not Assessable
7	13		1020-2002-061	SEP 18,2002	FEB 4,2003	ELECTRICAL		303 MILFORD-MT PLEA ROAD ROUNSAVILLE, RONALD		H Not Assessable
7	13		1020-2006-060	NOV 8,2006	APR 20,2007	ADDITIONS: MAJOR / MINOR	Remove Existing Deck, Fram New Floo	303 MILFORD-MT PLEA ROAD ROUNSAVILLE, RONALD	AUG 28,2007	X Assessable
7	14		1020-2002-032	JUN 12,2002	FEB 24,2003	MAINTENANCE:(roofing,etc)		301 MILFORD-MT PLEA ROAD BASTOW, DAVID P		H Not Assessable
7	14		1020-2008-049	SEP 10,2008	SEP 26,2008	HEATING	Replace Boiler	301 MILFORD-MT PLEA ROAD BASTOW, DAVID P		H Not Assessable
7	15		1020-2001-045	JUN 19,2001	MAY 1,2003	MAINTENANCE:(roofing,etc)		MILFORD-MT PLEA ROAD RILEY, CHRISTOPHER		H Not Assessable
7	15		1020-2007-901	DEC 11,2007		NEW----RESIDENCE	House To Come This Is For Coah	MILFORD-MT PLEA ROAD RILEY, CHRISTOPHER		
7	15.01		1020-2001-040	JUN 5,2001	AUG 1,2001	HEATING		231 MILFORD-MT PLEA ROAD CONRY, MICHAEL F & DAWN		H Not Assessable
7	15.02		1020-2005-066	NOV 9,2005		HOT WATER HEATER		233 MILFORD-MT PLEA ROAD PONGRACZ, DANIEL & MONIC		H Not Assessable
7	16		1020-1998-065	OCT 16,1998	MAY 5,1999	ELECTRICAL		229 MILFORD-MT PLEA ROAD BUSSARD, MARY S		H Not Assessable
7	16		1020-1999-037	JUN 1,1999	JUN 14,1999	ELECTRICAL		229 MILFORD-MT PLEA ROAD BUSSARD, MARY S		H Not Assessable
7	16		1020-2000-015	MAY 9,2000	JAN 26,2001	SHEDS: LARGE / SMALL		229 MILFORD-MT PLEA ROAD BUSSARD, MARY S	SEP 27,2000	H Not Assessable

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
7	16		1020-2006-045	AUG 24,2006	OCT 23,2007	HOT WATER HEATER		229 MILFORD-MT PLEA ROAD BUSSARD, MARY S		H Not Assessable
7	17		1020-2008-016	APR 21,2008	MAY 8,2008	ROOFING		227 MILFORD-MT PLEA ROAD PARKER MARVIN D / AMANDA		H Not Assessable
7	20		1020-1999-032	JUL 15,1999	AUG 11,1999	POOL: ABOVE GROUND		12 VALLEY VIEW AVENUE ROSSETTI, MARY M		H Not Assessable
7	20		1020-2000-013	APR 25,2000	AUG 23,2000	TANK INSTALLED INTERIOR		12 VALLEY VIEW AVENUE ROSSETTI, DAVID J JR & MA		H Not Assessable
7	20		1020-2003-032	JUN 5,2003	JAN 14,2004	RADON SYSTEM		12 VALLEY VIEW AVENUE MOYER, CHRISTOPHER D		H Not Assessable
7	20		1020-2005-059	OCT 13,2005	JAN 5,2006	ROOFING		12 VALLEY VIEW AVENUE MOYER, CHRISTOPHER D		H Not Assessable
7	23		1020-2001-052	JUN 28,2001	JAN 11,2002	PROPANE TANK INSTALLED		36 VALLEY VIEW AVENUE ZIEGLER, ALICE M		H Not Assessable
7	23		1020-2003-023	MAY 2,2003	SEP 28,2006	ADDITIONS: MAJOR / MINOR	Partial Release Bldg Only	36 VALLEY VIEW AVENUE ZIEGLER, ALICE M	SEP 13,2005	H Assessable
7	23		1020-2003-023+A	JUN 26,2003	JUL 10,2003	ELECTRICAL		36 VALLEY VIEW AVENUE ZIEGLER, ALICE M		H Not Assessable
7	23		1020-2003-056	AUG 15,2003	MAR 10,2004	HEATING	Propane Tank	36 VALLEY VIEW AVENUE ZIEGLER, ALICE M		H Not Assessable
7	23		1020-2004-001	JAN 5,2004	MAR 16,2004	HEATING		36 VALLEY VIEW AVENUE ZIEGLER, ALICE M		H Not Assessable
7	23		1020-2009-021	JUN 5,2009		RENOVATIONS: MAJOR/SMALL	1st Floor Bathroom, 2nd Floor Dorme	36 VALLEY VIEW AVENUE ZIEGLER, ALICE M		Assessable
7	24		1020-1992-0 +E	JAN 3,1992	MAY 6,1992	GARAGE: DETACHED	20 X 40 GARAGE	44 VALLEY VIEW AVENUE FLEMING, NICHOLAS & MILDR		H
7	24		1020-2000-045	SEP 29,2000	APR 20,2001	ADDITIONS: MAJOR / MINOR		44 VALLEY VIEW AVENUE FLEMING, NICHOLAS & MILDR	SEP 27,2001	H Assessable
7	24		1020-2003-023+B	JUL 28,2003		PLUMBING WORK		44 VALLEY VIEW AVENUE FLEMING, NICHOLAS & MILDR		H Not Assessable
7	25		1020-1995-033	JUL 24,1995	SEP 25,1995	MAINTENANCE:(roofing,etc)	.	76 MILL STREET ZIEGLER, MARIE	SEP 26,1995	H
7	26.01		1020-2002-030	MAY 31,2002	MAR 4,2003	DEMOLITION OF BUILDING	Demolition Of Water Tank 20 X 40	VALLEY VIEW AVENUE BOROUGH OF MILFORD		H Not Assessable
7	27		1020-1994-001+A	APR 23,1994	FEB 24,1995	MAINTENANCE:(roofing,etc)	Re-roofing	104 MILL STREET TINSMAN, CHARLES		H
7	27		1020-2005-073	DEC 13,2005	DEC 19,2005	ELECTRICAL		104 MILL STREET ZIMMERMAN, TIMOTHY		H Not Assessable
7	29		1020-1992-039	OCT 8,1992	SEP 26,1995	HEATING	Replace oil fire warm air floor	116-118 YORK ROAD ZILICK, MICHAEL III & GER	SEP 26,1995	H
7	29		1020-1996-049	NOV 25,1996	DEC 30,1996	RENOVATIONS: MAJOR/SMALL		116-118 YORK ROAD ZILICK, MICHAEL III & GER	SEP 9,1997	H
7	29		1020-1996-049+A	SEP 16,1996	DEC 30,1996	RENOVATIONS: MAJOR/SMALL	Windows/Siding/Porch Roof	116-118 YORK ROAD ZILICK, MICHAEL III & GER	SEP 9,1997	H
7	29		1020-1996-049+B	DEC 2,1996	SEP 8,1997	ELECTRICAL	Replace Service Cable, Upgrade	116-118 YORK ROAD ZILICK, MICHAEL III & GER	SEP 8,1997	H
7	29		1020-1996-903	SEP 5,1996	DEC 30,1996	RENOVATIONS: MAJOR/SMALL	Total Renovations	116-118 YORK ROAD ZILICK, MICHAEL III & GER	SEP 9,1997	H

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
7	30		1020-1997-021	MAY 6,1997	SEP 8,1997	MAINTENANCE:(roofing,etc)		122 YORK ROAD KRAUSE, RICHARD D & BREN	SEP 8,1997	H
7	30		1020-2000-059	DEC 15,2000	JAN 10,2001	ELECTRICAL		122 YORK ROAD KRAUSE RICHARD D / BREND		H Not Assessable
7	30		1020-2001-064	AUG 28,2001	NOV 9,2001	HEATING	Replace Oil Boiler	122 YORK ROAD KRAUSE RICHARD D / BREND		H Not Assessable
7	30		1020-2007-071	NOV 29,2007	JAN 7,2009	SHED: SMALL (< 200 SF)	.	122 YORK ROAD KRAUSE RICHARD D / BREND		H Not Assessable
7	31		1020-1992-0 +C	JAN 17,1992	SEP 18,1992	HEATING	REPLACING HEATING SYSTEM	130 YORK ROAD HENDRICKS, JOSEPH		H
7	31		1020-1994-029	JUL 1,1994	DEC 8,1998	RENOVATIONS: MAJOR/SMALL	Replace damage porch, wood	130 YORK ROAD HENDRICKS, JOSEPH	SEP 26,1995	H Not Assessable
7	31		1020-1998-060+A	SEP 25,1998		MAINTENANCE:(roofing,etc)		130 YORK ROAD HENDRICKS, JOSEPH		H Not Assessable
7	32		1020-2006-050+A	SEP 19,2006	OCT 24,2006	FIREPLACE / WOODSTOVE		136 YORK ROAD HALL, JUDIT		H Not Assessable
7	32		1020-2007-060	SEP 28,2007		HEATING	Boiler, Chimey Liner	136 YORK ROAD HALL, JUDIT	SEP 4,2008	H Assessable
7	33		1020-1993-0	JAN 18,1993	FEB 24,1993	ELECTRICAL	Service upgrade 60 amp to 200 amp	140 YORK ROAD ROHRBAUGH, JOE / LOCKE, J		H
7	33		1020-1996-001	JAN 2,1996		HEATING	Replace Furnace With	140 YORK ROAD ROHRBAUGH, JOE / LOCKE, J		H
7	33		1020-1998-054	AUG 24,1998	SEP 17,1998	SIDING: VINYL / WOOD		140 YORK ROAD ROHRBAUGH JOE / LOCKE JE	SEP 14,1999	H Not Assessable
7	34		1020-1998-062	OCT 15,1998	JUL 2,1999	SIDING: VINYL / WOOD		150 YORK ROAD KULLMAN, FERDINAND	SEP 14,1999	H Assessable
7	34		1020-2000-026	JUN 21,2000	DEC 5,2000	WOOD DECK / CONCR PATIO	Replace Porch Floors??	150 YORK ROAD KULLMAN, FERDINAND	SEP 27,2000	H Not Assessable
7	34		1020-2008-075	APR 18,2008		ADDITIONS: MAJOR / MINOR	Sheetrock Home Office?	150 YORK ROAD KULLMAN, FERDINAND	SEP 4,2008	H Assessable
7	35		1020-1989-012	JUL 16,1989	JUL 16,1993	POOL: ABOVE GROUND	LOOK FOR DECK	156 YORK ROAD LAFEVRE, TERRANCE		H
7	35		1020-1992-003+F	SEP 25,1992	NOV 23,1992	HEATING	Replace O H W Heater	156 YORK ROAD LAFEVRE, TERRANCE		H
7	35		1020-1995-035	SEP 6,1995	SEP 6,1995	MAINTENANCE:(roofing,etc)	.	156 YORK ROAD LAFEVRE, TERRANCE		H
7	35		1020-1996-013	APR 10,1996	SEP 28,1996	PLUMBING WORK	Remodel Bathroom	156 YORK ROAD LAFEVRE, TERRANCE	SEP 28,1996	H
7	35		1020-1996-013+A	MAY 3,1996	MAY 2,1997	PLUMBING WORK		156 YORK ROAD LAFEVRE, TERRANCE		H
7	35		1020-2008-056	OCT 14,2008		TANK REMOVAL	Remove Oil Tank From Basement 275 G	156 YORK ROAD LAFEVRE, TERRANCE		H Not Assessable
7	35		1020-2008-057	OCT 14,2008	DEC 3,2008	TANK INSTALLED INTERIOR	Install Oil Tank In Basement	156 YORK ROAD LAFEVRE, TERRANCE		H Not Assessable
7	36		1020-1996-052	OCT 11,1996	SEP 8,1997	MAINTENANCE:(roofing,etc)		160 YORK ROAD BOROUGH OF MILFORD	SEP 8,1997	H
7	37		1020-1994-003+C	AUG 2,1994		RENOVATIONS: MAJOR/SMALL	.	170 YORK ROAD MILFORD BORO BOARD OF E		H

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
7	37		1020-1994-003+E	SEP 28,1994	OCT 26,1994	ELECTRICAL	.	170 YORK ROAD MILFORD BORO BOARD OF E		H
7	37		1020-2001-066	SEP 21,2001	NOV 20,2001	MAINTENANCE:(roofing,etc)		170 YORK ROAD MILFORD BORO BOARD OF E		H Not Assessable
7	40		1020-2002-006+D	DEC 2,2002		RENOVATIONS: MAJOR/SMALL	Remodel Kitchen	17 PHYLLIS LANE COSOVER, CHARLES M		H Assessable
7	41		1020-1994-001+C	APR 14,1994	AUG 25,1994	NEW---RESIDENCE	Single family dwelling	21 PHYLLIS LANE MAGDA, DAVID & CAROLINE		H
7	41		1020-1994-001+H	JUL 29,1994	AUG 30,1994	WOOD DECK / CONCR. PATIO	Deck: 220	21 PHYLLIS LANE PATENAUE, JOHN C & ROSE		H
7	41		1020-1994-910+1	SEP 27,1994	JUN 30,1995	AIR CONDITIONING	Patio to be built under wood deck	21 PHYLLIS LANE PATENAUE, JOHN C & ROSE	SEP 26,1995	H
Block	7.01									
7.01	1		1020-2000-048	OCT 25,2000	DEC 8,2000	MAINTENANCE:(roofing,etc)		12 PHYLLIS LANE GRIFFITH, JAMES W	NOV 1,2001	H Not Assessable
7.01	2		1020-1997-022	MAY 6,1997	NOV 24,1998	MAINTENANCE:(roofing,etc)		14 PHYLLIS LANE SHOUDT, FRANK L III & EIL	SEP 8,1997	H Not Assessable
7.01	2		1020-1999-012	MAY 11,1999	FEB 2,2000	SIDING: VINYL / WOOD		14 PHYLLIS LANE SHOUDT, FRANK L III & EIL	SEP 14,1999	H Assessable
7.01	3		1020-1998-045	JUL 14,1998	JAN 21,1999	WOOD DECK / CONCR PATIO	22 X 30	16 PHYLLIS LANE DIPPLE, EUGENE	SEP 23,1998	H Assessable
7.01	3		1020-2003-043	JUL 7,2003	AUG 26,2003	TANK INSTALLED INTERIOR		16 PHYLLIS LANE DIPPLE, EUGENE		H Not Assessable
7.01	4		1020-1996-055	OCT 23,1996	DEC 30,1996	AIR CONDITIONING	Installation Of Central Air	2 WILLIAMS STREET ONTKO, ROBERT	SEP 9,1997	H Assessable
7.01	4		1020-2005-053+A	SEP 20,2005	JUN 1,2006	POOL: ABOVE GROUND	new 15 X 30 Pool	2 WILLIAMS STREET ONTKO, GLORIA M	SEP 8,2006	H Not Assessable
7.01	4		1020-2005-053+B	NOV 2,2005		ELECTRICAL		2 WILLIAMS STREET ONTKO, GLORIA M		H Not Assessable
7.01	5		1020-1998-022	MAY 4,1998		WOOD DECK / CONCR PATIO	16 X 19	10 DAWN ROAD SCHEPENS, HENRY		H Assessable
7.01	5		1020-2002-077	NOV 1,2002	DEC 20,2002	MAINTENANCE:(roofing,etc)		10 DAWN ROAD SCHEPENS, HENRY		H Not Assessable
7.01	5		1020-2003-044	JUL 7,2003	SEP 9,2003	TANK REMOVAL		10 DAWN ROAD SCHEPENS, HENRY		H Not Assessable
7.01	5		1020-2004-069	SEP 24,2004	JUL 27,2005	POOL: ABOVE GROUND		10 DAWN ROAD SCHEPENS, HENRY		H Not Assessable
7.01	5		1020-2004-069+A	SEP 24,2004		ELECTRICAL		10 DAWN ROAD SCHEPENS, HENRY		H Not Assessable
7.01	6		1020-1997-056	OCT 31,1997	SEP 22,1998	MAINTENANCE:(roofing,etc)		20 DAWN ROAD PHILLIPS, MARY		H
7.01	7		1020-1993-001+H	MAY 7,1993	JUL 30,1993	WOOD DECK	DECK: 16X35	30 DAWN ROAD FELICE, GARY		H
7.01	7		1020-2002-036+A	MAY 13,2002		WOOD DECK	12 X 12 On Existing Pool	30 DAWN ROAD FELICE, GARY	SEP 22,2003	H Not Assessable
7.01	7		1020-2004-074	NOV 3,2004	JAN 26,2005	ADDITIONS: MAJOR / MINOR	Converted Garage Into Living Room	30 DAWN ROAD FELICE, GARY & PATRICIA A		H Assessable

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
7.01	8		1020-2006-003	JAN 12,2006		MISC ITEMS	Replace Damaged Insulation	4 WILLIAMS STREET AMATELLI, JOSEPH M		H Not Assessable
7.01	9		1020-1990-005	OCT 12,1990	DEC 30,1991	WOOD DECK / CONCR. PATIO	REPAIR EXISTING PORCH	11 DAWN ROAD FITCHETT, CRAIG G & SUSAN		H
7.01	9		1020-1993-003+A	JUN 24,1993		RADON SYSTEM	RADON REMEDIATION	11 DAWN ROAD FITCHETT, CRAIG G & SUSAN		H
7.01	9		1020-2001-002	JAN 8,2001	SEP 24,2003	ADDITIONS: MAJOR / MINOR	Can't Make Permit Out	11 DAWN ROAD FITCHETT, CRAIG G & SUSAN	SEP 27,2001	H Not Assessable
7.01	9		1020-2007-037	JUN 28,2007	JUL 13,2007	ELECTRICAL		11 DAWN ROAD FITCHETT, CRAIG G & SUSAN		H Not Assessable
7.01	10		1020-1997-024	MAY 9,1997	MAY 19,1997	ELECTRICAL	Replace Electrical Service	23 DAWN ROAD SHERMAN, WAYNE	SEP 8,1997	H
7.01	10		1020-1998-033	JUN 16,1998	JUN 16,1998	WATER SERVICE	Repair Water Service	23 DAWN ROAD SHERMAN, WAYNE		H
7.01	11		1020-1997-054	SEP 23,1997	SEP 22,1998	MAINTENANCE:(roofing,etc)		33 DAWN ROAD ANDREWS, ROBERT J		H
7.01	12		1020-2003-015	APR 4,2003	APR 15,2003	ELECTRICAL		43 DAWN ROAD MCDAID, DAVID & DONNA P		H Not Assessable
7.01	12		1020-2003-015+A	APR 15,2003		ELECTRICAL		43 DAWN ROAD MCDAID, DAVID & DONNA P		H Not Assessable
7.01	12		1020-2007-014	MAR 27,2007	APR 20,2007	HOT WATER HEATER		43 DAWN ROAD MCDAID, DAVID & DONNA P		H Not Assessable
7.01	12		1020-2007-035	JUN 22,2007	OCT 5,2007	ELECTRICAL	Kitchen Outlets, Range / Dishwasher	43 DAWN ROAD MCDAID, DAVID & DONNA P		H Not Assessable
7.01	12		1020-2007-045	JUL 26,2007	JAN 28,2008	PLUMBING WORK		43 DAWN ROAD MCDAID, DAVID & DONNA P		H Not Assessable
7.01	12		1020-2007-043+B	JUL 31,2007		ELECTRICAL		43 DAWN ROAD MCDAID, DAVID & DONNA P		H Not Assessable
7.01	14		1020-2003-067	SEP 17,2003	JAN 22,2004	RADON SYSTEM		61 DAWN ROAD MOSIELLO, LAURA		H Not Assessable
7.01	14		1020-2006-063	NOV 20,2006	APR 20,2007	ELECTRICAL		61 DAWN ROAD MOSIELLO, LAURA		H Not Assessable
7.01	14		1020-2006-063+A	DEC 27,2006		ELECTRICAL	Receptacle Relocation	61 DAWN ROAD MOSIELLO, LAURA		H Not Assessable
7.01	14		1020-2007-025	APR 30,2007	SEP 20,2007	ELECTRICAL		61 DAWN ROAD MOSIELLO, LAURA		H Not Assessable
7.01	16		1020-2001-012	MAR 2,2001	JUN 20,2001	ADDITIONS: MAJOR / MINOR	No Details	75 DAWN ROAD WEAN, RICK	SEP 27,2001	H Assessable
7.01	16		1020-2001-012+A	MAR 16,2001		ELECTRICAL		75 DAWN ROAD WEAN, RICK	NOV 1,2001	H Not Assessable
7.01	16		1020-2005-055	SEP 22,2005	DEC 14,2005	GARAGE: ATTACHED		75 DAWN ROAD WEAN, RICK	SEP 8,2006	H Assessable
7.01	16		1020-2005-055+A	NOV 1,2005	DEC 14,2005	ELECTRICAL		75 DAWN ROAD WEAN, RICK		H Not Assessable
7.01	17		1020-1996-027	MAY 14,1996	SEP 28,1996	SIDING: VINYL / WOOD		85 DAWN ROAD KERTESZ, JOSEPH	SEP 28,1996	H
7.01	17		1020-2005-021	MAY 24,2005	AUG 11,2005	TANK INSTALLED INTERIOR		85 DAWN ROAD KERTESZ, JOSEPH		H Not Assessable

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
7.01	17		1020-2008-059	OCT 17,2008		ROOFING	Re-Roofing	85 DAWN ROAD KERTESZ, JOSEPH		H Not Assessable
7.01	17		1020-2009-028	JUN 23,2009		AIR CONDITIONING	Replacement	85 DAWN ROAD KERTESZ, JOSEPH		H Not Assessable
7.01	18		1020-1997-009+A	MAR 17,1997	SEP 8,1997	RADON SYSTEM		95 DAWN ROAD HUTT, WILLIAM E & ELLEN S	SEP 8,1997	H
7.01	18		1020-2002-036	JUN 14,2002	FEB 25,2003	MAINTENANCE:(roofing,etc)		95 DAWN ROAD RADANO ANTHONY JR / LORI		H Not Assessable
7.01	19		1020-1994-004+E	OCT 4,1994		MAINTENANCE:(roofing,etc)		105 DAWN ROAD BURT, RAYMOND & JOANNE		H
7.01	19		1020-1996-003	JAN 23,1996	NOV 1,2006	RADON SYSTEM	Install Radon Vent System	105 DAWN ROAD BURT, RAYMOND & JOANNE		H
7.01	19		1020-2000-054	NOV 21,2000	JUN 22,2001	FIREPLACE / WOODSTOVE		105 DAWN ROAD BURT, RAYMOND & JOANNE	SEP 27,2001	H Not Assessable
7.01	19		1020-2008-001	JAN 7,2008		BASEMENT FINISHED	Owens Corning Finished Basement	105 DAWN ROAD BURT, RAYMOND & JOANNE		Assessable
7.01	19		1020-2008-002	JAN 10,2008		WOOD DECK	Repair 2nd Floor Deck	105 DAWN ROAD BURT, RAYMOND & JOANNE	SEP 3,2008	X Assessable
7.01	21		1020-1994-002	JUN 17,1994		WOOD DECK / CONCR. PATIO		121 DAWN ROAD MELTON, JAMES & KATHLEEN		H
7.01	21		1020-1994-002+A	AUG 9,1994	AUG 9,1994	WOOD DECK / CONCR. PATIO	Never received permit from state	121 DAWN ROAD MELTON, JAMES & KATHLEEN		H
7.01	21		1020-1997-041	JUL 23,1997	SEP 8,1997	MAINTENANCE:(roofing,etc)		121 DAWN ROAD MELTON, JAMES & KATHLEEN	SEP 8,1997	H
7.01	22		1020-2003-027	MAY 13,2003	MAY 3,2004	AIR CONDITIONING	Ductwork For Air Conditon / A/C	123 DAWN ROAD CONOVER, KEITH & JENNIFEI	SEP 3,2004	H Assessable
7.01	22		1020-2005-058	AUG 20,2005		ROOFING		123 DAWN ROAD CONOVER, KEITH & JENNIFEI		H Not Assessable
7.01	22		1020-2004-058	AUG 31,2004		ROOFING		123 DAWN ROAD CONOVER, KEITH & JENNIFEI		H Not Assessable
7.01	23		1020-1992-002+E	MAY 11,1992	MAY 11,1992	NOT ASSESSABLE IMPRVMENT	RADON	125 DAWN ROAD SAMPSON, CHARLES & ANTC		H
7.01	23		1020-2000-014	MAY 5,2000	SEP 21,2000	POOL: ABOVE GROUND		125 DAWN ROAD SAMPSON, CHARLES & ANTC		H Not Assessable
7.01	23		1020-2005-043	AUG 16,2005	JUN 4,2007	SUNROOM	Wood Deck Also	125 DAWN ROAD PIETRUCHA, RONALD J & ELA	SEP 8,2006	H Assessable
7.01	24		1020-2005-062	OCT 31,2005	NOV 29,2005	SIDING: VINYL / WOOD		120 DAWN ROAD BAUER, DORIS J	SEP 8,2006	H Assessable
7.01	24		1020-2009-002	JAN 21,2009	MAR 9,2009	RADON SYSTEM		120 DAWN ROAD JOHNSON, GARY & KAREN		H Not Assessable
7.01	25		1020-2005-068	NOV 18,2005	JAN 12,2006	SIDING: VINYL / WOOD		110 DAWN ROAD MCGOVERN, JOSEPH	SEP 8,2006	H Assessable
7.01	26		1020-2000-050+A	NOV 3,2000	JUN 30,2001	AIR CONDITIONING		100 DAWN ROAD MEAKER, DOUGLAS	SEP 27,2001	H Assessable
7.01	26		1020-2006-020	APR 4,2006	JUL 11,2007	ADDITIONS: MAJOR / MINOR	Move 2 Interio Walls Put Addition O	100 DAWN ROAD PATULLO, ALEXANDER M JR	AUG 28,2007	H Assessable
7.01	26		1020-2006-020+B	SEP 17,2006		ELECTRICAL	Space Heater / Dryer Receptacle	100 DAWN ROAD PATULLO, ALEXANDER M JR		H Not Assessable

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
7.01	26		1020-2006-020+A	OCT 3,2006		TANK INSTALLED INTERIOR		100 DAWN ROAD PATULLO, ALEXANDER M JR		H Not Assessable
7.01	26		1020-2007-020	FEB 8,2007	MAY 11,2007	ELECTRICAL		100 DAWN ROAD PATULLO, ALEXANDER M JR		H Not Assessable
7.01	26		1020-2007-020+B	JUL 12,2007		MISC ITEMS	For What?	100 DAWN ROAD PATULLO, ALEXANDER M JR		H Not Assessable
7.01	26		1020-2007-055	SEP 7,2007	SEP 11,2007	ELECTRICAL		100 DAWN ROAD FREDERICK, LEONARD A & EI		H Not Assessable
7.01	27		1020-1998-024	MAY 14,1998	JUN 22,1998	POOL: ABOVE GROUND		90 DAWN ROAD PONIATOWSKI, JUDY		H
7.01	27		1020-2001-087	DEC 21,2001	JAN 11,2002	ELECTRICAL		90 DAWN ROAD REERS, ERIK C & PATRICIA		H Not Assessable
7.01	27		1020-2002-023	APR 19,2002	JUL 1,2002	RENOVATIONS: MAJOR/SMALL	Stairs, Floor	90 DAWN ROAD REERS, ERIK C & PATRICIA	SEP 22,2003	H Not Assessable
7.01	28		1020-2000-006	MAR 27,2000	JUN 6,2000	RADON SYSTEM		80 DAWN ROAD HERRERA, MICHAEL J & KIMB		H Not Assessable
7.01	28		1020-2002-031	JUN 7,2002		ADDITIONS: MAJOR / MINOR	Rear Of House	80 DAWN ROAD HERRERA, MICHAEL J & KIMB	SEP 28,2002	H Assessable
7.01	31		1020-2005-063	NOV 2,2005	JUN 13,2006	AIR CONDITIONING	Separate	3 WILLIAMS STREET BUSH, PAMELYN P & RICHA	SEP 8,2006	H Assessable
7.01	31		1020-2008-012	MAR 28,2008		ELECTRICAL		3 WILLIAMS STREET BUSH, PAMELYN P & RICHA		H Not Assessable
7.01	32		1020-1993-002+D	JUN 8,1993	SEP 27,1993	SHEDS: LARGE / SMALL	WOOD SHED NO SIZE STATED	1 WILLIAMS STREET ROMEO GREGORY & TINA M/		H
7.01	32		1020-1993-047	SEP 21,1993	JUL 19,1995	ADDITIONS: MAJOR / MINOR	Addition to existing 1 family	1 WILLIAMS STREET ROMEO GREGORY & TINA M/	SEP 26,1995	H
7.01	32		1020-1996-906	SEP 28,1996	JUN 30,1996	WOOD DECK / CONCR. PATIO	Wood Deck Built W/O Permit	1 WILLIAMS STREET ROMEO GREGORY & TINA M/	SEP 28,1996	H
7.01	32		1020-1999-018+A	SEP 8,1999		ELECTRICAL		1 WILLIAMS STREET ROMEO GREGORY & TINA M/		H Not Assessable
7.01	32		1020-2003-021	APR 30,2003	AUG 19,2004	WOOD DECK / CONCR PATIO		1 WILLIAMS STREET ROMEO, GREGORY & TINA M	SEP 13,2005	H Assessable
7.01	32		1020-2004-014+A	MAR 8,2004	MAY 10,2005	AIR CONDITIONING	Air Conditioning	1 WILLIAMS STREET ROMEO, GREGORY & TINA M	SEP 3,2004	H Assessable
7.01	33		1020-2004-071	OCT 19,2004	DEC 8,2004	RADON SYSTEM		24 PHYLLIS LANE FEENEY, SHAWN & KIMBERL'		H Not Assessable
7.01	33		1020-2005-043+A	JUL 10,2005	JUN 4,2007	HOT TUB		24 PHYLLIS LANE FEENEY, SHAWN & KIMBERL'	AUG 28,2007	H Not Assessable
7.01	34		1020-2001-036	MAY 21,2001	JUN 20,2001	WOOD DECK / CONCR PATIO		26 PHYLLIS LANE HAFF, CHRISTOPHER D & JE/	SEP 27,2001	H Assessable
7.01	35		1020-2002-040	JUL 2,2002	OCT 4,2002	POOL: ABOVE GROUND		28 PHYLLIS LANE OSTERHOUT, JILL A		H Not Assessable
7.01	35		1020-2007-008	FEB 9,2007		BURGLAR ALARM		28 PHYLLIS LANE OSTERHOUT, JILL A		H Not Assessable
7.01	37		1020-1997-007	APR 3,1997	APR 3,1997	MAINTENANCE:(roofing,etc)		130 DAWN ROAD SNIFFIN, GEORGE A	SEP 8,1997	H
7.01	37		1020-2001-020	MAR 22,2001	JUN 20,2001	POLE BARN	Pole Barn Used As Garage	130 DAWN ROAD SNIFFIN, GEORGE A	SEP 27,2001	H Assessable

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
7.01	38		1020-1994-005+C	DEC 6,1994		MAINTENANCE:(roofing,etc)	.	129 DAWN ROAD HARTPENCE, SHIRLEY / REAS		H
Block	8									
8	1		1020-1992-003+E	SEP 23,1992		ELECTRICAL	Replace service entrance cable	60 MILL STREET SIGAFOOS, BENJAMIN & CAR		H
8	1		1020-2001-055	JUL 23,2001		HEATING	Replace Oil Fire Boiler	60 MILL STREET SIGAFOOS, CAROL J		H Not Assessable
8	2		1020-1992-038+B	MAR 13,1992	JUN 30,1992	SIDING: VINYL / WOOD	RE-ROOF AND SIDING	49 HILLSIDE AVENUE PHILLIPS, JOHN R		H
8	2		1020-2002-038	JUN 27,2002	JUL 12,2006	ADDITIONS: MAJOR / MINOR	No Complete As Of 11-4-03	49 HILLSIDE AVENUE PHILLIPS, JOHN R		H Assessable
8	2		1020-2002-028	MAY 22,2002	MAY 1,2003	RENOVATIONS: MAJOR/SMALL	Insulate Existing Porch, Wall Mater	49 HILLSIDE AVENUE PHILLIPS, JOHN R		H Assessable
8	3		1020-1999-010	MAY 6,1999	MAR 1,2000	SIDING: VINYL / WOOD		56 MILL STREET CORRIGAN, WILLIAM L	SEP 27,2000	H Assessable
8	4		1020-2000-036+A	AUG 21,2000		TANK INSTALLED INTERIOR		52 MILL STREET THOMPSON, THOMAS G & LIS		H Not Assessable
8	4		1020-2004-016	MAR 17,2004	APR 20,2004	ELECTRICAL		52 MILL STREET THOMPSON, THOMAS G & LIS		H Not Assessable
8	4		1020-2003-063	SEP 5,2003	OCT 7,2003	MAINTENANCE:(roofing,etc)		52 MILL STREET THOMPSON, THOMAS G & LIS		H Not Assessable
8	6		1020-1993-005	OCT 22,1993		RECORD ONLY !!!!	Installation of Weil-McLain	WATER STREET BOROUGH OF MILFORD		H
8	6		1020-1998-002	JAN 12,1998	SEP 22,1998	ELECTRICAL	?	WATER STREET BOROUGH OF MILFORD		H
8	6		1020-1998-047+A	JUL 28,1998	NOV 17,1998	TANK INSTALLED INTERIOR		WATER STREET BOROUGH OF MILFORD		H Not Assessable
8	6		1020-1999-040	SEP 17,1999	OCT 12,1999	MAINTENANCE:(roofing,etc)		WATER STREET BOROUGH OF MILFORD		H Not Assessable
8	6		1020-2003-002	JAN 15,2003	MAR 10,2003	FIRE / SMOKE DETECTOR	Install Fire Protection System	WATER STREET BOROUGH OF MILFORD		H Not Assessable
8	6		1020-2005-011	MAR 4,2005	JUN 28,2005	ELECTRICAL		WATER STREET BOROUGH OF MILFORD		H Not Assessable
8	6		1020-2005-011+A	APR 28,2005	JUN 28,2005	ELECTRICAL		WATER STREET BOROUGH OF MILFORD		H Not Assessable
8	6		1020-2005-027	JUN 8,2005		ELECTRICAL		WATER STREET BOROUGH OF MILFORD		H Not Assessable
8	7		1020-1994-004+B	SEP 23,1994		MAINTENANCE:(roofing,etc)	.	26 WATER STREET BOWKER, RUTH		H
8	7		1020-2001-023	APR 9,2001	JUL 9,2001	ADDITIONS: MAJOR / MINOR		26 WATER STREET BOWKER, RUTH	SEP 22,2003	H Assessable
8	7		1020-2001-023+A	MAY 15,2001		ELECTRICAL		26 WATER STREET BOWKER, RUTH		H Not Assessable
8	7		1020-2001-069	JUN 4,2001	JUL 20,2006	ELECTRICAL	Replace 70 Amp Service To 200 Amp	26 WATER STREET BOWKER, RUTH		H Not Assessable
8	7		1020-2002-014	MAR 4,2002	APR 4,2002	ROOFING / RE-ROOFING		26 WATER STREET BOWKER, RUTH		H Not Assessable

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
8	7		1020-2002-070+A	OCT 22,2002		MAINTENANCE:(roofing,etc)		26 WATER STREET BOWKER, RUTH		H Not Assessable
8	8		1020-1992-005	DEC 4,1992	JAN 25,1993	ADDITIONS: MAJOR / MINOR	Replace floor, toilet, heat	MILL STREET JANSSEN, SUSAN		H
8	8		1020-1993-002+C	MAY 18,1993	JUN 30,1993	HEATING	REPLACE HOT AIR FURNACE WITH	MILL STREET VALAN, MARGARET S		H
8	8		1020-2005-013	MAR 7,2005	APR 1,2005	TANK INSTALLED INTERIOR		36 WATER STREET JANSSEN, SUSAN		H Not Assessable
8	8		1020-2008-019	MAY 5,2008		PLUMBING WORK	Replace 4' Cast Iron Pipe	36 WATER STREET CLARK, ROBERT H		H Not Assessable
8	8		1020-2008-033	JUN 18,2008		ELECTRICAL	Upgrad To 200 Amp	36 WATER STREET CLARK, ROBERT H		H Not Assessable
8	8		1020-2008-033+A	JUN 18,2008		PLUMBING WORK		36 WATER STREET CLARK, ROBERT H		H Not Assessable
8	8		1020-2008-033+B	SEP 15,2008		RENOVATIONS: MAJOR/SMALL	Bearing Walls, Insulation, Sheetroc	36 WATER STREET CLARK, ROBERT H		Assessable
8	9		1020-2002-043	JUL 9,2002	DEC 2,2003	MAINTENANCE:(roofing,etc)		10 WATER STREET STEM, H CRAIG & ANDRA JOI		H Not Assessable
8	9		1020-2003-020+B	APR 30,2003	DEC 11,2003	COMMERCIAL BUILDING		10 WATER STREET STEM, H CRAIG & ANDRA JOI	SEP 3,2004	H Assessable
8	9		1020-2003-020+A	JUN 11,2003		TANK INSTALLED INTERIOR		WATER STREET STEM, H CRAIG & ANDRA JOI		H Not Assessable
8	9.01		1020-1995-034	MAR 20,1995	SEP 8,1997	MAINTENANCE:(roofing,etc)		111 BARRON ROAD SCHROTH, MARGARET L	SEP 8,1997	H
8	9.01		1020-2006-036	JUL 11,2006	SEP 28,2006	SIDING: VINYL / WOOD		111 BARRON ROAD SCHROTH, MARGARET L	AUG 28,2007	H Assessable
8	10		1020-2003-005	JAN 17,2003	FEB 13,2003	ELECTRICAL	Service Range Receptacle	20 WATER STREET HALL, DAVID & GLORIA ANN		H Not Assessable
8	11		1020-1993-004+F	AUG 13,1993	APR 1,1994	ASSESSMENT DATA REVIEW---		18 WATER STREET PIRATZKY, HENRY J & LISA		H
8	11		1020-1994-052	OCT 28,1994	OCT 30,2003	HEATING	HWBB	18 WATER STREET ENDLER, MADELINE M	SEP 26,1995	H
8	11		1020-2002-058+A	SEP 13,2002		MAINTENANCE:(roofing,etc)		18 WATER STREET ENDLER, MADELINE M		H Not Assessable
8	11		1020-2008-013	APR 7,2008	JUL 18,2008	ROOFING		18 WATER STREET ENDLER, MADELINE M		H Not Assessable
8	13		1020-2003-012	MAR 21,2003	MAY 21,2003	ELECTRICAL		34 MILL STREET BOWKER RUTH / A BRUCE SZ		H Not Assessable
Block	9									
9	1		1020-1993-002+F	JUN 11,1993	MAR 17,1994	ADDITIONS: MAJOR / MINOR	ADD 2 BEDROOMS AND 1 BATHROOM	28 HILLSIDE AVENUE SLATON, PETER R		H
9	1		1020-1996-032	MAY 31,1996	APR 30,1996	SHEDS: LARGE / SMALL		28 HILLSIDE AVENUE SLATON, PETER R		H
9	1		1020-1996-044	AUG 6,1996	SEP 28,1996	HEATING	Repl Boiler W/ Weil Mc Lein	28 HILLSIDE AVENUE SLATON, PETER R	SEP 28,1996	H
9	1		1020-2006-058	OCT 19,2006	DEC 27,2006	WOOD DECK	Hot Tub	28 HILLSIDE AVENUE SLATON, PETER R	AUG 28,2007	H Assessable

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
9	1		1020-2006-058+A	DEC 7,2006		ELECTRICAL		28 HILLSIDE AVENUE SLATON, PETER R		H Not Assessable
9	1		1020-2006-069	DEC 29,2006	JAN 25,2007	ELECTRICAL		28 HILLSIDE AVENUE SLATON, PETER R		H Not Assessable
9	2		1020-1999-028	JUN 28,1999	DEC 27,1999	RADON SYSTEM		22 HILLSIDE AVENUE BERTOLDO, JONATHAN D		H Not Assessable
9	2		1020-1999-018	MAY 21,1999	DEC 27,1999	ELECTRICAL		22 HILLSIDE AVENUE BERTOLDO, JONATHAN D		H Not Assessable
9	3		1020-2001-013	MAR 1,2001	NOV 20,2002	NEW---RESIDENCE	Single Family Dwelling	20 HILLSIDE AVENUE GABODA TIMOTHY / BRENDA	JAN 25,2003	H Assessable
9	3		1020-2003-046	JUL 14,2003	AUG 26,2003	WOOD DECK		20 HILLSIDE AVENUE GABODA TIMOTHY / BRENDA		H Assessable
Block	10									
10	1		1020-1993-005+A	OCT 22,1993		ASSESSMENT DATA REVIEW---	Re-roofing	41 VALLEY VIEW AVENUE SLOYER, HERBERT		H
10	1		1020-1997-029	MAY 23,1997	JUL 30,1997	POOL: ABOVE GROUND	Check Which Type	41 VALLEY VIEW AVENUE SLOYER, HERBERT	SEP 9,1997	H
10	1.01		1020-2000-007	MAR 28,2000	APR 24,2000	HEATING		40 HILLSIDE AVENUE PURSELL, WILLIAM P & BARB		H Not Assessable
10	1.01		1020-2007-020+A	APR 9,2007	MAY 11,2007	AIR CONDITIONING		40 HILLSIDE AVENUE PURSELL, WILLIAM P & BARB	AUG 28,2007	X Assessable
10	2		1020-1996-022	OCT 21,1996	OCT 21,1996	HEATING		36 HILLSIDE AVENUE FLECK, ESTHER A	SEP 8,1997	H
10	2		1020-1996-022+A	APR 30,1996	APR 30,1996	HEATING	Install New Warm Air Furnace	36 HILLSIDE AVENUE FLECK, ESTHER A		H
10	3		1020-1994-032	JUL 22,1994	SEP 27,1994	WOOD DECK / CONCR. PATIO	Replacement	39 VALLEY VIEW AVENUE CLARK, BARRY L & PAMELA C	SEP 26,1995	H
10	3		1020-2001-005	FEB 1,2001	MAY 16,2003	SIDING: VINYL / WOOD	Siding & Re-Roofing	39 VALLEY VIEW AVENUE CLARK, BARRY L & PAMELA C	SEP 27,2001	H Assessable
10	6		1020-1997-001	JAN 30,1997	APR 1,1997	RENOVATIONS: MAJOR/SMALL		26 HILLSIDE AVENUE STEVENS, NATALIE M / BERR	SEP 9,1997	H
10	6		1020-1998-047	JUL 30,1998		WOOD DECK / CONCR PATIO	12 X 24	26 HILLSIDE AVENUE STEVENS NATALIE M / BERR	SEP 23,1998	H Assessable
10	6		1020-1998-037	JUN 30,1998	JUN 30,1998	TANK INSTALLED INTERIOR		26 HILLSIDE AVENUE STEVENS NATALIE M / BERR		H
10	7		1020-2000-020	MAY 25,2000	FEB 25,2003	SIDING: VINYL / WOOD		17 VALLEY VIEW AVENUE KOLESAR, JOHN	SEP 22,2003	H Not Assessable
10	7		1020-2002-046	JUL 17,2002	AUG 28,2002	TANK REMOVAL		17 VALLEY VIEW AVENUE KOLESAR, JOHN		H Not Assessable
10	7		1020-2002-047	JUL 19,2002	AUG 28,2002	TANK INSTALLED INTERIOR		17 VALLEY VIEW AVENUE KOLESAR, JOHN		H Not Assessable
10	9		1020-1999-045	OCT 21,1999		TANK REMOVAL		53 LONG VIEW ROAD SZYMANSKI, SHANE M		H Not Assessable
10	9		1020-1999-048	NOV 12,1999	NOV 1,2006	ELECTRICAL		53 LONG VIEW ROAD SZYMANSKI, SHANE M		H Not Assessable
10	11		1020-2008-044+A	JUL 10,2008		ROOFING		14 HILLSIDE AVENUE MAGYAR PROPERTIES LLC		H Not Assessable

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
Block	11									
11	1		1020-1993-003+G	JUL 12,1993		RECORD ONLY !!!	REMOVAL OF GAS TANKS	11 FRENCHTOWN ROAD STEM BROTHERS		H
11	1		1020-1993-004+A	AUG 13,1993	AUG 10,1994	COMMERCIAL BUILDING	.	11 FRENCHTOWN ROAD STEM BROTHERS		H
11	1		1020-1993-004+B	SEP 7,1993	JUL 1,1994	COMMERCIAL BUILDING	New Citgo Station	11 FRENCHTOWN ROAD STEM BROTHERS		H
11	1		1020-1993-009	AUG 4,1993	JUL 1,1994	COMMERCIAL BUILDING	Per plans	11 FRENCHTOWN ROAD STEM BROTHERS		H
11	1		1020-1994-003+B	SEP 13,1994		ELECTRICAL	.	11 FRENCHTOWN ROAD STEM BROTHERS		H
11	1		1020-1996-024	MAY 1,1996	MAY 1,1996	ELECTRICAL	Install 1 Receptacle For Atm Machin	11 FRENCHTOWN ROAD STEM BROTHERS	SEP 27,1996	H
11	1		1020-1999-053	DEC 14,1999	JUL 13,2000	ELECTRICAL		11 FRENCHTOWN ROAD STEM BROTHERS		H Not Assessable
11	1		1020-2001-073	OCT 15,2001	AUG 4,2003	PLUMBING WORK	1 Under Sink Pump	11 FRENCHTOWN ROAD STEM BROTHERS		H Not Assessable
11	1		1020-2001-079	NOV 7,2001	NOV 20,2001	ELECTRICAL		11 FRENCHTOWN ROAD STEM BROTHERS		H Not Assessable
11	1		1020-2002-063	SEP 25,2002	DEC 20,2002	ELECTRICAL		11 FRENCHTOWN ROAD STEM BROTHERS		H Not Assessable
11	1		1020-2002-073	OCT 22,2002	DEC 20,2002	ELECTRICAL		11 FRENCHTOWN ROAD STEM BROTHERS		H Not Assessable
11	1		1020-2005-016	APR 7,2005	AUG 2,2005	MISC ITEMS		11 FRENCHTOWN ROAD STEM BROTHERS		H Not Assessable
11	2		1020-1995-038	AUG 4,1995	SEP 26,1995	POOL: ABOVE GROUND	24'	110 BARRON ROAD ZEITLER, ROBERT A & JUDIT	SEP 26,1995	H
11	2		1020-1995-038+A	AUG 10,1995	SEP 26,1995	WOOD DECK / CONCR. PATIO	.	110 BARRON ROAD ZEITLER, ROBERT A & JUDIT	SEP 26,1995	H
11	2		1020-1999-039	SEP 8,1999	SEP 21,1999	SHEDS: LARGE / SMALL		110 BARRON ROAD ZEITLER, ROBERT A & JUDIT		H Not Assessable
11	2		1020-2001-053	JUL 10,2001	OCT 16,2001	RENOVATIONS: MAJOR/SMALL	Re-Sheetrock And Cabinets	110 BARRON ROAD ADAMS, GREGORY	SEP 22,2003	H Not Assessable
11	2.01		1020-2008-055	SEP 19,2008	JAN 7,2009	RENOVATIONS: MAJOR/SMALL	Remove Existing Doors And Frames Fr	21 FRENCHTOWN ROAD MILFORD BOROUGH BOARD		H Not Assessable
11	2.01		1020-2009-024	JUN 15,2009		RENOVATIONS: MAJOR/SMALL	Re-Roof / Gutters	21 FRENCHTOWN ROAD MILFORD BOROUGH BOARD		H Not Assessable
11	2.01		1020-2009-026+A	JUN 17,2009		CONTRACTOR CHANGE	.	21 FRENCHTOWN ROAD MILFORD BOROUGH BOARD		H Not Assessable
11	2.01		1020-2009-026	JUN 17,2009		ELECTRICAL	Fire Alarm / Electrical Upgrades/	21 FRENCHTOWN ROAD MILFORD BOROUGH BOARD		H Not Assessable
11	3		1020-1994-002+C	JUN 10,1994		MAINTENANCE:(roofing,etc)	.	25 FRENCHTOWN ROAD MILFORD BOROUGH BOARD		H
11	3		1020-1994-003+D	JUL 26,1994		TANK REMOVAL	Install 10M gal tank	25 FRENCHTOWN ROAD MILFORD BOROUGH BOARD		H
11	3		1020-1996-047	AUG 22,1996	AUG 22,1996	RADON SYSTEM		25 FRENCHTOWN ROAD MILFORD BOROUGH BOARD	SEP 27,1996	H

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
11	3		1020-1998-042	JUL 18,1998	OCT 21,1998	MAINTENANCE:(roofing,etc)		25 FRENCHTOWN ROAD MILFORD BOROUGH BOARD		H Not Assessable
11	4		1020-2001-072	OCT 11,2001	NOV 20,2001	ROOFING / RE-ROOFING		54 LONG VIEW ROAD ANDRESEN, ROBERT & BEVE		H Not Assessable
11	4		1020-2005-061	OCT 26,2005	DEC 19,2005	MISC ITEMS	Replace Damages Sill Plages	54 LONG VIEW ROAD ANDRESEN, ROBERT & BEVE		H Not Assessable
11	4		1020-2008-038	JUL 7,2008	JAN 15,2009	TANK REMOVAL	1000 Gal Tank Removed	54 LONG VIEW ROAD ANDRESEN, ROBERT & BEVE		H Not Assessable
11	4		1020-2008-039	JUL 7,2008	SEP 11,2008	TANK INSTALLED INTERIOR	Tank Installed 275 Gallon In Bsmt	54 LONG VIEW ROAD ANDRESEN, ROBERT & BEVE		H Not Assessable
11	5		1020-2005-048	AUG 26,2005	AUG 5,2006	NEW----RESIDENCE	Single Family Dwelling	56 LONGVIEW ROAD ANDRESEN, ROBERT & BEVE	SEP 6,2006	H Assessable
11	5		1020-2006-004	JAN 26,2006	NOV 14,2006	BURGLAR ALARM		56 LONGVIEW ROAD ANDRESEN, ROBERT & BEVE	SEP 6,2006	H Assessable
11	5		1020-2005-048+A	JUL 31,2005		GAS PIPING		56 LONGVIEW ROAD ANDRESEN, ROBERT & BEVE		H Not Assessable
11	5		1020-2006-048+C	JUL 31,2006		ELECTRICAL		56 LONGVIEW ROAD ANDRESEN, ROBERT & BEVE		H Not Assessable
Block	12									
12	1		1020-2000-034	JUN 20,2000		TANK REMOVAL		CHURCH STREET LITTLE FALLS BANK		H Not Assessable
12	1		1020-2008-011+A	MAR 26,2008		ELECTRICAL		CHURCH STREET TD BANKNORTH FACILITIES M		H Not Assessable
12	2		1020-1999-036	AUG 6,1999	MAY 21,2001	WATER SERVICE		23 BRIDGE STREET DELAWARE RIVER PROPERT		H Not Assessable
12	2		1020-2000-011	APR 18,2000	DEC 5,2000	ADDITIONS: MAJOR / MINOR	Drop Ceiling, Open Doorway Etc	23 BRIDGE STREET DELAWARE RIVER PROPERT		H Assessable
12	2		1020-2000-011+A	MAY 24,2000		ELECTRICAL		23 BRIDGE STREET DELAWARE RIVER PROPERT		H Not Assessable
12	2		1020-2000-017	MAY 24,2000	MAY 18,2001	WOOD DECK / CONCR PATIO		23 BRIDGE STREET DELAWARE RIVER PROPERT		H Assessable
12	2		1020-2000-038	AUG 28,2000	OCT 26,2000	ELECTRICAL	Adding Outlets To Front Office	23 BRIDGE STREET DELAWARE RIVER PROPERT		H Not Assessable
12	2		1020-2001-029+A	JUL 18,2001		ELECTRICAL	Sub Panel	23 BRIDGE STREET DELAWARE RIVER PROPERT		H Not Assessable
12	2		1020-2002-002	JAN 4,2002	MAR 4,2003	HEATING		23 BRIDGE STREET DELAWARE RIVER PROPERT		H Not Assessable
12	2		1020-2006-027	MAY 17,2006	JUN 1,2006	SIGN		23 BRIDGE STREET DELAWARE RIVER PROPERT		H Not Assessable
12	3		1020-1992-002+F	MAY 14,1992	SEP 8,1992	ELECTRICAL	OUTLET FOR CASH REGISTER	17 BRIDGE STREET COCHRAN, JAMES & EDNA		H
12	3		1020-1993-0 +A	FEB 9,1993	SEP 28,1909	ADDITIONS: MAJOR / MINOR	Arbor: 195x13	17 BRIDGE STREET COCHRAN, JAMES & EDNA		H
12	3		1020-1999-024	JUN 10,1999	AUG 16,1999	WATER SERVICE		17 BRIDGE STREET COCHRAN, JAMES & EDNA		H Not Assessable
12	3		1020-2002-027	FEB 25,2002	FEB 25,2003	MAINTENANCE:(roofing,etc)		17 BRIDGE STREET COCHRAN, JAMES & EDNA		H Not Assessable

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
12	3		1020-2007-028	MAY 8,2007	JUL 5,2007	MISC ITEMS	Replace Refrigeration Unit	17 BRIDGE STREET COCHRAN, JAMES & EDNA		H Not Assessable
12	3		1020-2008-009	MAR 14,2008		FIRE DETECTOR		17 BRIDGE STREET COCHRAN, JAMES & EDNA		H Not Assessable
12	3		1020-2008-052	SEP 17,2008	OCT 27,2008	TANK REMOVAL	2 Underground 550 Gal Oil Tanks	17 BRIDGE STREET COCHRAN, JAMES & EDNA		H Not Assessable
12	3		1020-2008-053	SEP 17,2008	OCT 27,2008	TANK INSTALLED INTERIOR	Install 2 275 Gal Tanks Inside	17 BRIDGE STREET COCHRAN, JAMES & EDNA		H Not Assessable
12	3		1020-2009-012	APR 28,2009		HEATING	Replace Boiler Weil-Mclain Wtgo-2	17 BRIDGE STREET COCHRAN, JAMES & EDNA		H Not Assessable
12	5		1020-1990-002	JUL 23,1990	SEP 18,1992	COMMERCIAL BUILDING	RENOV STORE INTERIOR W/ BATH	9 BRIDGE STREET SPEZZANO, FRANK S & ETTO		H
12	5		1020-1999-026	JUN 16,1999	DEC 27,1999	WATER SERVICE		9 BRIDGE STREET 9-11 BRIDGE STREET INC		H Not Assessable
12	5		1020-2000-019	MAY 25,2000	SEP 1,2000	AIR CONDITIONING		9 BRIDGE STREET 9-11 BRIDGE STREET INC	SEP 27,2000	H Assessable
12	5		1020-2006-053	OCT 5,2006		TANK REMOVAL		9 BRIDGE STREET 9-11 BRIDGE STREET INC		H Not Assessable
12	5		1020-2006-054	OCT 5,2006	JAN 10,2007	TANK INSTALLED INTERIOR		9 BRIDGE STREET JANCY LLC		H Not Assessable
12	6		1020-1992-001+A	MAY 5,1992	SEP 18,1992	ADDITION: MINOR	ALTERATION	5 BRIDGE STREET MYERS, NANETTE H		H
12	6		1020-2004-059	AUG 23,2004	OCT 28,2004	TANK REMOVAL		5 BRIDGE STREET HANNA, DALE A & TAMMY L		H Not Assessable
12	6		1020-2004-072	OCT 7,2004	NOV 27,2006	RENOVATIONS: MAJOR/SMALL		5 BRIDGE STREET HANNA, DALE A & TAMMY L	SEP 12,2006	H Assessable
12	6		1020-2005-072	MAR 3,2005		ADDITIONS: MAJOR / MINOR		5 BRIDGE STREET HANNA, DALE A & TAMMY L	SEP 12,2006	H Assessable
12	7		1020-2000-023	JUN 7,2000	JUL 10,2000	ADDITIONS: MAJOR / MINOR	Roof / Skylites	63 CHURCH STREET CASTAGNA, ROBERT M & LIN	SEP 27,2000	H Assessable
12	7		1020-2000-035+A	AUG 15,2000		RENOVATIONS: MAJOR/SMALL	Update Existing Space Install Door	63 CHURCH STREET CASTAGNA, ROBERT M & LIN	SEP 27,2001	H Not Assessable
12	7		1020-2000-035+B	SEP 13,2000		ELECTRICAL		63 CHURCH STREET CASTAGNA, ROBERT M & LIN		H Not Assessable
12	7		1020-2002-003	JAN 8,2002	JAN 22,2003	WOOD DECK	Replace 2rd Floor Deck	63 CHURCH STREET CASTAGNA, ROBERT M & LIN		H Assessable
12	7		1020-2002-034+A	JUN 12,2002		PLUMBING WORK		63 CHURCH STREET CASTAGNA, ROBERT M & LIN		H Not Assessable
12	7		1020-2002-003+A	MAY 13,2002		MAINTENANCE:(roofing,etc)		63 CHURCH STREET CASTAGNA, ROBERT M & LIN		H Not Assessable
12	7		1020-2003-008	FEB 19,2003	JUL 10,2003	RENOVATIONS: MAJOR/SMALL	Bedroom In To A Bathroom?	63 CHURCH STREET CASTAGNA, ROBERT M & LIN		H Assessable
12	7		1020-2004-029	APR 29,2004		TANK REMOVAL		63 CHURCH STREET CASTAGNA, ROBERT M & LIN		H Not Assessable
12	7		1020-2004-030	APR 29,2004		TANK INSTALLED INTERIOR	2 330 Gal Oil Tanks	63 CHURCH STREET CASTAGNA, ROBERT M & LIN		H Not Assessable
12	7		1020-2005-012	MAR 4,2005	JUL 12,2006	KITCHEN		63 CHURCH STREET CASTAGNA, ROBERT M & LIN		H Assessable

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
12	7.01		1020-1997-050	AUG 25,1997	SEP 2,1998	MAINTENANCE:(roofing,etc)	Repair Existing Dock On River	ALONG DELAWARE RIVER CASTAGNA, ROBERT M & LIN		H Not Assessable
12	8		1020-1998-011	MAR 11,1998	MAR 1,1999	ADDITIONS: MAJOR / MINOR	Dormers	71 SPRING GARDEN STREET CASTAGNA, ROBERT & LINDA	SEP 14,1999	H Not Assessable
12	8		1020-2001-019+A	MAR 16,2001		PLUMBING WORK	Convert Bedroom To Bathroom	71 SPRING GARDEN STREET CASTAGNA, ROBERT M & LIN		H Assessable
12	9		1020-2001-084	DEC 4,2001	FEB 25,2003	ROOFING / RE-ROOFING		81 SPRING GARDEN STREET ECKERT, DONALD W & CARO		H Not Assessable
12	9		1020-2007-033	JUN 14,2007	JUL 9,2007	TANK REMOVAL		81 SPRING GARDEN STREET ECKERT, DONALD W & CARO		H Not Assessable
12	9		1020-2007-032	JUN 14,2007	JUL 9,2007	TANK INSTALLED INTERIOR		81 SPRING GARDEN STREET ECKERT, DONALD W & CARO		H Not Assessable
12	10		1020-1993-0 +C	JAN 6,1993	DEC 2,1993	ELECTRICAL	Time Clock	85 SPRING GARDEN STREET DONAHUE, DEBRAH E		H
12	10		1020-1995-001+B	APR 28,1995		MAINTENANCE:(roofing,etc)	Reroofing over one layer	85 SPRING GARDEN STREET DONAHUE, DEBRAH E		H
12	10		1020-1998-035	JUN 18,1998	DEC 6,1999	GARAGES: Attach / Detach	Also Air Condition	85 SPRING GARDEN STREET DONAHUE, DEBRAH E	SEP 23,1998	H Assessable
12	10		1020-1998-035+A	MAR 5,1998		ELECTRICAL		85 SPRING GARDEN STREET DONAHUE, DEBRAH E		H Not Assessable
12	11		1020-2001-018	MAR 13,2001	MAY 13,2003	HEATING		93 SPRING GARDEN STREET SCHUBERT, EVELYN L		H Not Assessable
12	11		1020-2003-016	APR 7,2003	MAY 13,2003	AIR CONDITIONING	Air Conditon Compressor	93 SPRING GARDEN STREET SCHUBERT, EVELYN L		H Assessable
12	12		1020-2006-062+A	NOV 17,2006		ROOFING		113 SPRING GARDEN STREET BARBELLA, ROSEMARIE		H Not Assessable
12	12		1020-2007-068	NOV 2,2007	OCT 30,2008	ADDITIONS: MAJOR / MINOR	.	113 SPRING GARDEN STREET BARBELLA, ROSEMARIE		Assessable
12	12		1020-2007-068+A	NOV 16,2007		ADDITIONS: MAJOR / MINOR		113 SPRING GARDEN STREET BARBELLA, ROSEMARIE		H Not Assessable
12	12		1020-2007-068+B	OCT 9,2007		AIR CONDITIONING	.	113 SPRING GARDEN STREET BARBELLA, ROSEMARIE		Assessable
12	13		1020-1994-004	OCT 7,1994	DEC 15,1994	ELECTRICAL	60 to 125 amp servcie	117 SPRING GARDEN STREET TRAUCH, GREGG A & BARBA		H
12	13		1020-1996-026	MAY 6,1996	MAY 6,1996	MAINTENANCE:(roofing,etc)		117 SPRING GARDEN STREET TRAUCH, GREGG A & BARBA	SEP 27,1996	H
12	13		1020-2008-040	JUL 7,2008		SIDING: VINYL / WOOD	Siding	117 SPRING GARDEN STREET TRAUCH, GREGG A & BARBA		Assessable
12	14		1020-2008-041	JUL 8,2008	OCT 30,2008	SIDING: VINYL / WOOD	.	119 SPRING GARDEN STREET HORVATH, JOSEPH G		Assessable
12	15		1020-1996-016+A	SEP 26,1996	SEP 8,1997	MAINTENANCE:(roofing,etc)		121 SPRING GARDEN STREET NELOWET, EDWARD J & SHIF	SEP 8,1997	H
12	15		1020-1996-016+B	JUN 21,1996	JUN 30,1996	ELECTRICAL		121 SPRING GARDEN STREET NELOWET, EDWARD J & SHIF		H
12	15		1020-1996-016+C	APR 16,1996	DEC 30,1996	RENOVATIONS: MAJOR/SMALL	Partial Renovation	121 SPRING GARDEN STREET NELOWET, EDWARD J & SHIF	SEP 9,1997	H
12	15		1020-1996-016+D	JUL 31,1996	SEP 8,1997	RENOVATIONS: MAJOR/SMALL	Renovations??	121 SPRING GARDEN STREET NELOWET, EDWARD J & SHIF	SEP 28,1996	H

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
12	15		1020-2001-075	OCT 18,2001	DEC 27,2001	ELECTRICAL	Wiring Of New Attached Garage	121 SPRING GARDEN STREET NELOWET, EDWARD J & SHIF		H Not Assessable
12	15		1020-2001-035	JAN 1,2001	OCT 17,2001	GARAGES: Attach / Detach		121 SPRING GARDEN STREET NELOWET, EDWARD J & SHIF		H Assessable
12	16		1020-1999-014	JUN 28,1999	JUN 28,1999	MAINTENANCE:(roofing,etc)		125 SPRING GARDEN STREET MATTHEWS, WILLIAM E		H Not Assessable
12	16		1020-1999-014+A	MAY 17,1999		MAINTENANCE:(roofing,etc)		125 SPRING GARDEN STREET MATTHEWS, WILLIAM E		H Not Assessable
12	16		1020-2002-041	JUL 8,2002	MAR 4,2003	SIDING: VINYL / WOOD		125 SPRING GARDEN STREET MATTHEWS, WILLIAM E		H
12	16		1020-2004-049+A	JUL 26,2004		ADDITIONS: MAJOR / MINOR		125 SPRING GARDEN STREET MATTHEWS, WILLIAM E & SU:		H Not Assessable
12	16		1020-2004-047	AUG 17,2004		ADDITIONS: MAJOR / MINOR		125 SPRING GARDEN STREET MATTHEWS, WILLIAM E & SU:	SEP 12,2006	H Assessable
12	16		1020-2004-049	AUG 20,2004		ELECTRICAL		125 SPRING GARDEN STREET MATTHEWS, WILLIAM E & SU:		H Not Assessable
12	16		1020-2005-049	APR 13,2005		ELECTRICAL		125 SPRING GARDEN STREET MATTHEWS, WILLIAM E & SU:		H Not Assessable
12	17.01		1020-2006-902	OCT 1,2006		WOOD DECK	Wood Deck Built W/O Permit	ALONG DELAWARE RIVER UNKNOWN		H Not Assessable
12	19.01		1020-1999-022	JUN 8,1999	DEC 27,1999	ELECTRICAL		1 BRIDGE STREET DELAWARE RIVER JOINT BRI		H Not Assessable
12	19.01		1020-2001-029	APR 19,2001	MAY 22,2001	ELECTRICAL		1 BRIDGE STREET DELAWARE RIVER JOINT BRI		H Not Assessable

Block **13**

13	1		1020-1997-009	APR 25,1997	OCT 14,2003	DEMOLITION OF BUILDING	Demolition Of Rear Wall	4 BRIDGE STREET MAPLE LAND INC	SEP 9,1997	H
13	1		1020-2002-004	JAN 11,2002	MAY 1,2003	DEMOLITION OF BUILDING	????	4 BRIDGE STREET MAPLE LAND INC		H Not Assessable
13	1.01		1020-2000-060+A	APR 24,2000		RENOVATIONS: MAJOR/SMALL	Renovation Of Structure	2 BRIDGE STREET BURNT ROCK ENTERPRISES	SEP 27,2001	H Assessable
13	1.01		1020-2000-060	DEC 22,2000	MAR 11,2002	ELECTRICAL		2 BRIDGE STREET BURNT ROCK ENTERPRISES		H Not Assessable
13	1.01		1020-2000-060+B	JUL 17,2000		PROPANE TANK INSTALLED	Installation Of Propane Tank	2 BRIDGE STREET BURNT ROCK ENTERPRISES		H Not Assessable
13	2		1020-1997-044	JUL 28,1997	SEP 8,1997	MAINTENANCE:(roofing,etc)		8 RAILROAD AVENUE BRYNILDSEN, CATHY	SEP 8,1997	H
13	6		1020-1994-0 +B	FEB 17,1994	APR 1,1994	COMMERCIAL BUILDING	Replace building	20 RAILROAD AVENUE ALFANO, CAROL		H
13	6		1020-1994-0 +C	JAN 25,1994	APR 1,1994	DEMOLITION OF BUILDING	Demolition of building	20 RAILROAD AVENUE ALFANO, CAROL		H
13	6		1020-1994-0 +D	MAR 11,1994	APR 1,1994	ELECTRICAL	Part of remodeling	20 RAILROAD AVENUE ALFANO, CAROL		H

Block **14**

14	2		1020-1993-001+A	MAR 23,1993	MAR 30,1993	ELECTRICAL	Inspect for electric motor cut in??	10 BRIDGE STREET HAHN, R DOUGLAS & JOANN		H
----	---	--	-----------------	-------------	-------------	------------	-------------------------------------	---	--	---

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
14	2		1020-2003-010	MAR 7,2003	JAN 6,2004	HEATING		10 BRIDGE STREET HAHN, JOANN FICK		H Not Assessable
14	2		1020-2003-089	DEC 12,2003	JAN 6,2004	ELECTRICAL		10 BRIDGE STREET HAHN, JOANN FICK		H Not Assessable
14	3		1020-1992-005+B	DEC 27,1992	DEC 8,1992	ELECTRICAL	Service upgrade	14 BRIDGE STREET NETZER, SIEGFRIED		H
14	3		1020-2001-077	OCT 24,2001	MAR 13,2002	HEATING		14 BRIDGE STREET PONIATOWSKI, MARY DEBOR		H Not Assessable
14	3		1020-2005-029	JUN 21,2005	FEB 15,2006	ROOFING		14 BRIDGE STREET PONIATOWSKI, MARY DEBOR		H Not Assessable
14	4		1020-1995-058	NOV 16,1995	SEP 27,1996	HEATING	Install New Heater And Connect	16 BRIDGE STREET BEANE, CAROL	SEP 27,1996	H
14	4		1020-2003-057	AUG 18,2003	SEP 23,2003	PORCH: ENCLOSED / OPEN	Check To See If Only Replacement	16 BRIDGE STREET BEANE, CAROL		H Assessable
14	4		1020-2006-035	JUN 29,2006	AUG 2,2006	ROOFING		16 BRIDGE STREET BEANE, CAROL		H Not Assessable
14	4		1020-2008-007	FEB 6,2008		FIRE DETECTOR		16 BRIDGE STREET BEANE, CAROL		H Not Assessable
14	4		1020-2008-042	JUL 10,2008	OCT 30,2008	SUNROOM	Sunroom	16 BRIDGE STREET BEANE, CAROL		Assessable
14	4		1020-2008-043	JUL 11,2008	OCT 30,2008	DEMOLITION OF BUILDING	Demo Exterior Stairs And Decks	16 BRIDGE STREET BEANE, CAROL		Assessable
14	4		1020-2009-006	FEB 13,2009	FEB 27,2009	ELECTRICAL		16 BRIDGE STREET BEANE, CAROL		H Not Assessable
14	5		1020-2001-071	OCT 10,2001	NOV 8,2004	ELECTRICAL		18 BRIDGE STREET DELAWARE RIVER CAPITAL F		H Not Assessable
14	5		1020-2002-071	OCT 31,2002	NOV 13,2002	ELECTRICAL		18 BRIDGE STREET DELAWARE RIVER CAPITAL F		H Not Assessable
14	5		1020-2004-055	AUG 11,2004	NOV 9,2004	ELECTRICAL		18 BRIDGE STREET DELAWARE RIVER CAPITAL F		H Not Assessable
14	6		1020-2005-005+A	JAN 3,2005		PLUMBING WORK		24 BRIDGE STREET MILFORD MARKET INC		H Not Assessable
14	7		1020-1995-047	SEP 5,1995	SEP 5,1995	TANK REMOVAL		26 BRIDGE STREET MILFORD MARKET INC		H
14	7		1020-2006-046	SEP 7,2006	DEC 27,2006	HOT WATER HEATER		26 BRIDGE STREET LITTLE KIDS NJ PARTNERSHI		H Not Assessable
14	7		1020-2006-051	SEP 21,2006	NOV 2,2006	GAS PIPING		26 BRIDGE STREET LITTLE KIDS NJ PARTNERSHI		H Not Assessable
14	7		1020-2008-006	FEB 1,2008	MAR 28,2008	SIDING: VINYL / WOOD	Replace Siding On Front Of Bldg	26 BRIDGE STREET LITTLE KIDS NJ PARTNERSHI		Assessable
14	8		1020-1995-002+B	JAN 3,1995	FEB 2,1995	HEATING		32 BRIDGE STREET MONINGHOFF, EST OF EMMA	SEP 26,1995	H
14	8		1020-2004-087	DEC 21,2004	MAY 9,2005	ROOFING		32 BRIDGE STREET BRUNING, THOMAS P & BARE		H Not Assessable
14	9		1020-1998-079	DEC 10,1998	FEB 5,1999	TANK INSTALLED INTERIOR		31 BRIDGE STREET LITTLE FALLS BANK		H Not Assessable
14	10		1020-2000-028	JUN 23,2000	JUN 21,2005	ELECTRICAL		16 CARPENTER STREET HELLER, RUSSELL D		H Not Assessable

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
14	11		1020-1995-046	SEP 5,1995	SEP 5,1995	TANK REMOVAL	.	31 GREEN STREET GRESS, RICHARD P & DARLE		H
14	11.01		1020-1994-001+E	APR 8,1994		RADON SYSTEM	Radon system	24 CARPENTER STREET BUFFA, ULISSE & NANCY		H
14	11.01		1020-1997-026	MAY 6,1997	JUL 8,1997	WOOD DECK / CONCR. PATIO	Rear Of House 10 X 23	24 CARPENTER STREET BUFFA, ULISSE & NANCY	SEP 9,1997	H
14	12		1020-1993-002+A	JUN 11,1993	SEP 27,1993	GARAGES: ATTACH / DETACH	CAN'T MAKE OUT PERMIT	25 GREEN STREET HELLER, ROBERT		H
14	12		1020-1993-004+D	SEP 28,1993	DEC 13,1993	HEATING	Warm Air furnace replacement	25 GREEN STREET HELLER, ROBERT		H
14	12		1020-2001-027	APR 12,2001	JUL 13,2001	ELECTRICAL		25 GREEN STREET HELLER, ROBERT W & CAROI		H Not Assessable
14	12		1020-2005-049+A	SEP 1,2005	SEP 26,2006	ROOFING		25 GREEN STREET HELLER, ROBERT W & CAROI		H Not Assessable
14	13		1020-1997-025	MAY 16,1997	MAY 22,1997	MAINTENANCE:(roofing,etc)		23 GREEN STREET HELLER, ROBERT	SEP 8,1997	H
14	13		1020-2001-008	FEB 13,2001	JUL 13,2001	ELECTRICAL		23 GREEN STREET HELLER, ROBERT W & CAROI		H Not Assessable
14	14		1020-1995-043+A	AUG 22,1995	SEP 25,1995	TANK REMOVAL	.	21 GREEN STREET GRONENTHAL, ANNA	SEP 26,1995	H
14	15		1020-2000-056	NOV 28,2000		WOOD DECK		17 GREEN STREET KROTH, RICHARD A & PATRIC		H Assessable
14	15		1020-2000-037	AUG 23,2000		HEATING	Replacement Of Boiler	17 GREEN STREET KROTH, RICHARD A & PATRIC		H Not Assessable
14	15		1020-2006-067	DEC 19,2006	JAN 26,2007	SOLAR PANELS	Solar	17 GREEN STREET KROTH, RICHARD A & PATRIC		H Not Assessable
14	16		1020-1991-013	JUL 22,1991	SEP 18,1992	RENOVATION; SMALL	SERVICE REPAIRS OF WHAT ?	8 RAILROAD AVENUE TODD P & M / WATSON D & D		H
14	16		1020-1997-065	DEC 18,1997	OCT 21,1998	MAINTENANCE:(roofing,etc)		8 RAILROAD AVENUE TODD P & M / WATSON D & D		H Not Assessable
14	16		1020-2005-001	JAN 3,2005	JAN 21,2005	PLUMBING WORK		8 RAILROAD AVENUE TODD, PHILIP J & MARO A &		H Not Assessable
Block	15									
15	1		1020-2002-022	APR 17,2002	MAY 25,2005	ELECTRICAL	200 Amp Service	10 GREEN STREET ARNOLD, WALTER C		H Not Assessable
15	1		1020-2007-115	DEC 20,2007		ELECTRICAL		10 GREEN STREET ARNOLD, WALTER C		H Not Assessable
15	2		1020-1993-003+I	JUL 2,1993	SEP 2,1993	SHEDS: LARGE / SMALL	SHED: 8 X 10	14 GREEN STREET MCHENRY, TRACEY J & KARE		H
15	3		1020-1994-002+B	JUN 16,1994		SHEDS: LARGE / SMALL	10 x 16	16 GREEN STREET MALHERBE, JOHN & PEGGY		H
15	3		1020-2006-021	APR 10,2006		HEATING	REPLACE	16 GREEN STREET GALLOS, MARGARET N		H Not Assessable
15	4		1020-1991-014	AUG 16,1991	SEP 18,1992	RENOVATION; SMALL	REPAIR CHIMEY	20 GREEN STREET OTOOLE, KEVIN MICHAEL &		H
15	4		1020-1996-050	SEP 20,1996	DEC 26,1996	MAINTENANCE:(roofing,etc)	Re-Roofin	20 GREEN STREET OTOOLE, KEVIN MICHAEL &	SEP 8,1997	H

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
15	4		1020-1999-001	FEB 17,1999	JAN 14,2004	MAINTENANCE:(roofing,etc)		20 GREEN STREET OTOOLE, KEVIN MICHAEL &		H Not Assessable
15	5		1020-2004-081	NOV 19,2004		TANK INSTALLED INTERIOR		24 GREEN STREET KAISER, MARK		H Not Assessable
15	5		1020-2004-082	NOV 19,2004	FEB 1,2005	TANK REMOVAL		24 GREEN STREET KAISER, MARK		H Not Assessable
15	5		1020-2006-031	JUN 13,2006	AUG 4,2006	DEMOLITION OF BUILDING	Demolition Of Porch / Laundry	24 GREEN STREET KAISER, MARK		H Not Assessable
15	5		1020-2006-032	JUN 13,2006		ADDITIONS: MAJOR / MINOR	Alteration Bedroom, Bathroom	24 GREEN STREET KAISER, MARK		Assessable
15	6		1020-1999-011	MAY 11,1999	JUL 2,1999	HEATING		32 GREEN STREET TIGAR, RAYMOND S & CAROL		H Not Assessable
15	6		1020-2001-011	MAR 2,2001	APR 2,2001	TANK INSTALLED INTERIOR		32 GREEN STREET TIGAR, RAYMOND S & CAROL		H Not Assessable
15	6		1020-2002-015	MAR 12,2002	JAN 3,2003	WOOD STOVE (PELLET)		32 GREEN STREET STOCKTON WILLIAM S & ANN		H Not Assessable
15	6		1020-2002-015+A	OCT 9,2002		PLUMBING WORK		32 GREEN STREET MCKIERNAN, MARY S		H Not Assessable
15	6		1020-2005-028	JUN 16,2005		FIREPLACE / WOODSTOVE		32 GREEN STREET STOCKTON WILLIAM S & ANN		H Not Assessable
15	6		1020-2005-040	JUL 29,2005	SEP 1,2005	ELECTRICAL		32 GREEN STREET STOCKTON WILLIAM S & ANN		H Not Assessable
15	6		1020-2006-050	SEP 4,2006	FEB 21,2006	ELECTRICAL		32 GREEN STREET STOCKTON WILLIAM S & ANN		H Not Assessable
15	6		1020-2005-054+A	SEP 20,2005	OCT 27,2006	PLUMBING WORK		32 GREEN STREET STOCKTON WILLIAM S & ANN		H Not Assessable
15	6		1020-2005-074	DEC 13,2005	AUG 4,2008	RENOVATIONS: MAJOR/SMALL		32 GREEN STREET STOCKTON WILLIAM S & ANN	SEP 6,2006	H Not Assessable
15	6		1020-2006-049	SEP 12,2006	OCT 24,2006	RENOVATIONS: MAJOR/SMALL	Close Door, Open Doorway	32 GREEN STREET STOCKTON WILLIAM S & ANN		H Not Assessable
15	6		1020-2006-065	DEC 15,2006		BATHROOM	On Second Floor	32 GREEN STREET STOCKTON WILLIAM S & ANN		H Not Assessable
15	6		1020-2007-021	APR 10,2007		BATHROOM	On Existing Finished 3rd Floor	32 GREEN STREET STOCKTON WILLIAM S & ANN		Assessable
15	6		1020-2007-026	MAY 13,2007	MAY 24,2007	WATER SERVICE		32 GREEN STREET STOCKTON WILLIAM S & ANN		H Not Assessable
15	6		1020-2008-029	MAY 29,2008		ELECTRICAL		32 GREEN STREET STOCKTON WILLIAM S & ANN		H Not Assessable
15	6		1020-2008-065	MAR 26,2008		FIRE DETECTOR		32 GREEN STREET STOCKTON WILLIAM S & ANN		H Not Assessable
15	7		1020-2005-014	MAR 11,2005		ELECTRICAL		31 MAPLE STREET JENKINS C DAVID/ELIZABETH		H Not Assessable
15	8		1020-1992-001+F	APR 24,1992	SEP 18,1992	HEATING	BOILER REPLACEMENT	25 MAPLE STREET ALLER, RICHARD E JR ETAL		H
15	8		1020-1994-004+D	OCT 4,1994	OCT 18,1994	ELECTRICAL		25 MAPLE STREET ALLER, RICHARD E JR ETAL		H
15	8		1020-2008-051	SEP 17,2008	OCT 16,2008	HEATING	Replace Boiler	23-25 MAPLE STREET ROETHEL, RICK W		H Not Assessable

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
15	9		1020-1992-018	MAY 5,1992	JUN 25,1999	ADDITIONS: MAJOR / MINOR	CLOSING IN PORCH	21 MAPLE STREET KNAPP, GARY L & MARIE B	SEP 26,1995	H
15	9		1020-1993-018	FEB 2,1993	DEC 1,1994	RENOVATIONS: MAJOR/SMALL	Renovate bathroom/laundry	21 MAPLE STREET KNAPP, GARY L & MARIE B	SEP 26,1995	H
Block	16									
16	1		1020-1993-002+E	MAY 24,1993	JUN 7,1993	RENOVATIONS: MAJOR/SMALL	REPLACE PORCH/ RAILING	66 CARPENTER STREET PURSELL, PETER		H
16	1		1020-1999-038	AUG 20,1999	NOV 9,1999	HEATING		66 CARPENTER STREET PURSELL, ROSEMARY		H Not Assessable
16	1		1020-2001-046	JUN 19,2001	JAN 4,2004	ELECTRICAL		66 CARPENTER STREET PURSELL, ROSEMARY		H Not Assessable
16	2		1020-2002-021	APR 10,2002	SEP 1,2005	ELECTRICAL		10 MAPLE STREET BETZ, JEFREY A & KATHERIN		H Not Assessable
16	3		1020-1997-027	MAY 20,1997	JUL 8,1997	Tank Installed Interior	In Basement	16 MAPLE STREET KELLER, JOHN L	SEP 8,1997	H
16	3		1020-2007-070	NOV 28,2007		FIREPLACE / WOODSTOVE		16 MAPLE STREET MORRIS CHRISTOPHER/ LEE,		H Not Assessable
16	4		1020-1999-015	MAY 18,1999	DEC 27,1999	HEATING		20 MAPLE STREET SNYDER, EARL		H Not Assessable
16	5		1020-2000-003	FEB 22,2000	MAR 15,2000	MAINTENANCE:(roofing,etc)		24 MAPLE STREET MCCARTY AMANDA P C/O KA1		H Not Assessable
16	5		1020-2001-033	MAY 15,2001	JUN 22,2001	ELECTRICAL	Service Upgrade	24 MAPLE STREET MCCARTY AMANDA P C/O KA1		H Not Assessable
16	5		1020-2001-074	OCT 17,2001	MAR 4,2003	HEATING		24 MAPLE STREET MCCARTY AMANDA P C/O JMI		H Not Assessable
16	5		1020-2004-043	JUN 25,2004	AUG 31,2005	ALTERATIONS		24 MAPLE STREET GORDON PETER / JESSICA G	SEP 13,2005	H Assessable
16	5		1020-2004-099	JUL 16,2004		ELECTRICAL		24 MAPLE STREET MCCARTY AMANDA P C/O JMI		H Not Assessable
16	5		1020-2004-048	JUL 26,2004	AUG 10,2004	ELECTRICAL		24 MAPLE STREET GORDON PETER / JESSICA G		H Not Assessable
16	5		1020-2004-060	AUG 27,2004		WATER SERVICE		24 MAPLE STREET GORDON PETER / JESSICA G		H Not Assessable
16	5		1020-2005-058+A	OCT 7,2005	JAN 18,2006	ROOFING		24 MAPLE STREET GORDON PETER / JESSICA G		H Not Assessable
16	5		1020-2006-026	MAY 12,2006	NOV 21,2006	RENOVATIONS: MAJOR/SMALL	Alterations Renovations	24 MAPLE STREET GORDON PETER / JESSICA G	AUG 28,2007	X Assessable
16	5		1020-2006-042	AUG 11,2006	FEB 26,2007	AIR CONDITIONING		24 MAPLE STREET GORDON PETER / JESSICA G	AUG 28,2007	H Assessable
16	5		1020-2007-501	AUG 29,2007		PORCH: ENCLOSED / OPEN	Enclosed Porch In Rear	24 MAPLE STREET GORDON PETER / JESSICA G		H Assessable
16	5		1020-2007-050	AUG 16,2007	NOV 21,2007	DEMOLITION OF BUILDING		24 MAPLE STREET GORDON PETER / JESSICA G		H Not Assessable
16	5		1020-2007-057	SEP 17,2007	FEB 11,2009	ADDITIONS: MAJOR / MINOR	Porch On Rear	24 MAPLE STREET GORDON PETER / JESSICA G		Assessable
16	5		1020-2007-057+A	SEP 19,2007	FEB 11,2009	ADDITIONS: MAJOR / MINOR	Plumbing	24 MAPLE STREET GORDON PETER / JESSICA G		H Not Assessable

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
16	5		1020-2007-057+B	OCT 2,2007	FEB 11,2009	MISC ITEMS		24 MAPLE STREET GORDON PETER / JESSICA G		H Not Assessable
16	5		1020-2007-057+C	OCT 10,2007	FEB 11,2009	ADDITIONS: MAJOR / MINOR		24 MAPLE STREET GORDON PETER / JESSICA G		H Not Assessable
16	5		1020-2008-065+A	DEC 1,2008		PELLET STOVE		24 MAPLE STREET GORDON PETER / JESSICA G		Assessable
16	6		1020-1998-010	MAR 10,1998	MAY 1,1998	TANK INSTALLED INTERIOR		28 MAPLE STREET GORDON, JANE		H
16	6		1020-2001-021	MAR 29,2001	APR 20,2001	DEMOLITION OF BUILDING		28 MAPLE STREET GORDON, JANE	SEP 2,2001	H Not Assessable
16	6		1020-2001-057	JUL 25,2001	OCT 17,2001	ELECTRICAL	Fan Receptacles	28 MAPLE STREET GORDON, JANE		H Not Assessable
16	6		1020-2002-020	APR 9,2002	MAY 22,2002	SIDING: VINYL / WOOD		28 MAPLE STREET GORDON, JANE	SEP 28,2002	H Assessable
16	6		1020-2007-004	JAN 30,2007	MAY 21,2007	BATHROOM	Powder Room First Floor For Senior	28 MAPLE STREET GORDON, JANE	AUG 28,2007	H Not Assessable
16	6		1020-2008-066	DEC 1,2008		PELLET STOVE		28 MAPLE STREET GORDON, JANE		Assessable
16	7		1020-2000-053	NOV 17,2000	DEC 26,2000	FIREPLACE / WOODSTOVE		32 MAPLE STREET HORTON, AGNES R	SEP 27,2001	H Not Assessable
16	7		1020-2007-010	MAR 13,2007	APR 3,2007	TANK INSTALLED INTERIOR		32 MAPLE STREET SCHUBACH, RICHARD P & DI/		H Not Assessable
16	7		1020-2007-016	MAR 28,2007	MAY 21,2007	TANK REMOVAL		32 MAPLE STREET SCHUBACH, RICHARD P & DI/		H Not Assessable
16	8		1020-2007-015	MAR 27,2007		SHED: LARGE		70 CARPENTER STREET NIECE, THOMAS	AUG 28,2007	X Assessable
16	9		1020-2001-059	JUL 30,2001	FEB 22,2002	RENOVATIONS: MAJOR/SMALL	Sheetrock, Etc	25 ORCHARD STREET CULBERSON, GREGORY P & I	SEP 27,2001	H Assessable
16	9		1020-2001-059+A	AUG 16,2001		ELECTRICAL		25 ORCHARD STREET CULBERSON, GREGORY P & I		H Not Assessable
16	9		1020-2001-059+B	OCT 16,2001		ELECTRICAL		25 ORCHARD STREET CULBERSON, GREGORY P & I		H Not Assessable
16	9		1020-2001-059+C	OCT 24,2001		PLUMBING WORK		25 ORCHARD STREET CULBERSON, GREGORY P & I		H Not Assessable
16	11		1020-2000-029	JUN 23,2000	DEC 8,2000	SIDING: VINYL / WOOD		15 ORCHARD STREET ENGLEHARDT, MARTIN E JR &	SEP 27,2000	H Not Assessable
16	11		1020-2002-048	JUL 19,2002	OCT 28,2004	WATER SERVICE		15 ORCHARD STREET ENGLEHARDT, MARTIN E JR &		H Not Assessable
16	12		1020-1992-0 +D	FEB 25,1992	JUN 30,1992	HEATING	HOT AIR FURNACE	11 ORCHARD STREET GRIMSHAW, JEFFREY & SUS/		H
16	12		1020-1995-022	MAY 26,1995	SEP 26,1995	RENOVATIONS: MAJOR/SMALL		11 ORCHARD STREET BROWN, SUSAN E	SEP 26,1995	H
Block	17									
17	1		1020-2007-058	SEP 19,2007	OCT 15,2007	HEATING		12 ORCHARD STREET PHILKILL, SUSAN		H Not Assessable
17	1		1020-2008-011	MAR 1,2008	APR 9,2008	ELECTRICAL		12 ORCHARD STREET PHILKILL, SUSAN		H Not Assessable

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
17	2		1020-1993-001+G	MAY 4,1993	FEB 24,1995	MAINTENANCE:(roofing,etc)	RE-ROOFING	20 ORCHARD STREET ANDRES, SPENCE		H
17	2		1020-2008-070	DEC 29,2008	MAR 18,2009	ELECTRICAL	100 Amp Subpanel Electrical Fixture	20 ORCHARD STREET BARNA, MICHAEL J II		H Not Assessable
17	3		1020-2003-051	JUL 25,2003	APR 20,2004	ELECTRICAL		26 ORCHARD STREET BERISHA, EDUARD & TAMAR/		H Not Assessable
17	3		1020-2003-068	SEP 6,2003	NOV 21,2003	MAINTENANCE:(roofing,etc)		26 ORCHARD STREET BERISHA, EDUARD & TAMAR/		H Not Assessable
17	3		1020-2003-072	OCT 15,2003	APR 20,2004	HEATING		26 ORCHARD STREET BERISHA, EDUARD & TAMAR/		H Not Assessable
17	3		1020-2005-018	MAY 4,2005		FIRE DETECTOR		26 ORCHARD STREET BERISHA, EDUARD & TAMAR/		H Not Assessable
17	4		1020-1994-801	FEB 4,1994	APR 1,1994	ELECTRICAL	Electrical Upgrade	32 ORCHARD STREET CYPHERS, DIANE S		H
17	4		1020-1999-043	OCT 7,1999	NOV 9,1999	MAINTENANCE:(roofing,etc)		32 ORCHARD STREET CYPHERS, DIANE S		H Not Assessable
17	5		1020-1997-046	JUL 30,1997	SEP 25,1998	RENOVATIONS: MAJOR/SMALL	Remove Existing Porch Replace W/	31-33 WALNUT STREET MAZZETTA, DOUGLAS F & BE	SEP 14,1999	H Assessable
17	5		1020-1998-029	JUN 11,1998	FEB 10,2000	RENOVATIONS: MAJOR/SMALL	Electric/Sheetrock, Etc	31-33 WALNUT STREET MAZZETTA, DOUGLAS F & BE	SEP 14,1999	H Assessable
17	5		1020-1998-030	JUN 11,1998	FEB 10,2000	RENOVATIONS: MAJOR/SMALL		31-33 WALNUT STREET MAZZETTA, DOUGLAS F & BE	SEP 14,1999	H Assessable
17	5		1020-1998-030+A	JUN 14,1998		WATER SERVICE		31-33 WALNUT STREET MAZZETTA, DOUGLAS F & BE		H Not Assessable
17	5		1020-1998-029+A	JUN 14,1998		WATER SERVICE		31-33 WALNUT STREET MAZZETTA, DOUGLAS F & BE		H Not Assessable
17	5		1020-2001-056	JUL 24,2001	JUN 23,2005	RENOVATIONS: MAJOR/SMALL	Cement Floor, Electric, Etc	31-33 WALNUT STREET MAZZETTA, DOUGLAS F & BE		H Assessable
17	6		1020-1993-003+E	JUL 20,1993	AUG 1,1993	RADON SYSTEM	PVC DUCTWORK THROUGH SLAB THROUGH	23 WALNUT STREET PIESLA, MICHAEL & ROBIN M		H
17	6		1020-1993-004+H	SEP 24,1993		ASSESSMENT DATA REVIEW---	Service/outlets	23 WALNUT STREET PIESLA, MICHAEL & ROBIN M		H
17	6		1020-1995-053	SEP 29,1995	OCT 19,2006	SIDING: VINYL / WOOD	.	23 WALNUT STREET PIESLA, MICHAEL & ROBIN M		H
17	6		1020-1996-053	OCT 22,1996	JUL 13,2000	MAINTENANCE:(roofing,etc)	Seal Off Basement Window	23 WALNUT STREET PIESLA, MICHAEL & ROBIN M	SEP 8,1997	H
17	7		1020-1993-002+H	MAY 25,1993	JUN 14,1993	MAINTENANCE:(roofing,etc)	ROOFING	19 WALNUT STREET PYATT, EUGENE GLENN & DC		H
17	7		1020-1995-802+A	MAR 16,1995		RADON SYSTEM	.	19 WALNUT STREET PYATT, EUGENE GLENN & DC		H
17	8		1020-1998-009	MAR 2,1998	MAY 22,1998	ELECTRICAL	150 Amp	11 WALNUT STREET BOSCHEN, GREGORY W		H
17	8		1020-2000-005	MAR 17,2000	MAY 18,2006	ADDITIONS: MAJOR / MINOR	Rebuild	11 WALNUT STREET BOSCHEN, GREGORY W		H Assessable
17	8		1020-2000-005+A	MAY 19,2000		ELECTRICAL		11 WALNUT STREET BOSCHEN, GREGORY W		H Not Assessable
17	8		1020-2000-005+B	MAY 22,2000		PLUMBING WORK		11 WALNUT STREET BOSCHEN, GREGORY W		H Not Assessable

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Apr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
17	9		1020-1998-053	AUG 12,1998	OCT 21,1998	MAINTENANCE:(roofing,etc)		25 RAILROAD AVENUE MOSEY, BARRY & LINDA		H Not Assessable
Block 18										
18	1		1020-1995-023	JUN 10,1995	SEP 11,1995	NEW---RESIDENCE	Duplex residence; never given	10 WALNUT STREET HAAG, JOHN B	SEP 27,1995	H
18	1		1020-1995-023+A	JUN 2,1995		NEW---RESIDENCE	2 Family Modular	10 WALNUT STREET HAAG, JOHN B		H
18	2		1020-2003-080	NOV 10,2003		MAINTENANCE:(roofing,etc)		18 WALNUT STREET TRAUCH, WILLIAM		H Not Assessable
18	2		1020-2004-057	AUG 18,2004		RADON SYSTEM		18 WALNUT STREET TRAUCH, WILLIAM		H Not Assessable
18	4		1020-2004-085	DEC 3,2004	APR 29,2004	RADON SYSTEM		26 WALNUT STREET HELLER, ROBERT W & CAROL		H Not Assessable
18	5		1020-2006-016	MAR 10,2006	SEP 26,2006	ROOFING		34 WALNUT STREET HUBERT, JOSEPH H & VIRGINIA		H Not Assessable
18	6		1020-1992-047	NOV 20,1992	SEP 27,1994	RENOVATIONS: MAJOR/SMALL	Walls / heater	120 CARPENTER STREET MILFORD PROPERTIES LLC	SEP 27,1995	H
18	6		1020-2000-041	SEP 22,2000	MAR 20,2001	COMMERCIAL BUILDING	Raise Roof New Wood Trusses	120 CARPENTER STREET MILFORD PROPERTIES LLC	SEP 27,2001	H Not Assessable
18	6.01		1020-1998-031	JUN 11,1998	OCT 21,1998	MAINTENANCE:(roofing,etc)		122 CARPENTER STREET MILFORD SEWERAGE DEPAR		H Not Assessable
18	6.01		1020-1998-031+A	OCT 1,1998	OCT 1,1998	MAINTENANCE:(roofing,etc)		122 CARPENTER STREET MILFORD SEWERAGE DEPAR		H Not Assessable
18	6.01		1020-2009-007	MAR 9,2009		REPAIRS	Repair 4 Rafters, Replace Damaged	122 CARPENTER STREET BOROUGH OF MILFORD		H Not Assessable
18	6.01		1020-2009-019	JUN 4,2009		MISC ITEMS	Construction Of Concrete EQ Tanks,	122 CARPENTER STREET BOROUGH OF MILFORD		Assessable
Block 19										
19	1		1020-1993-005+H	OCT 29,1993	NOV 23,1993	ASSESSMENT DATA REVIEW---	Re-roofing	40 BRIDGE STREET PARKES, HOWARD J		H
19	1		1020-2000-055	NOV 21,2000	JAN 10,2001	MAINTENANCE:(roofing,etc)		40 BRIDGE STREET PARKES, HOWARD J		H Not Assessable
19	1		1020-2002-011	FEB 6,2002	MAR 4,2003	ROOFING / RE-ROOFING		40 BRIDGE STREET PARKES, HOWARD J		H Not Assessable
19	1		1020-2004-051	JUL 9,2004	SEP 23,2004	TANK INSTALLED INTERIOR		40 BRIDGE STREET PARKES, HOWARD J		H Not Assessable
19	1		1020-2005-006	JAN 25,2005	FEB 15,2005	ELECTRICAL		40 BRIDGE STREET PARKES, HOWARD J		H Not Assessable
19	1		1020-2005-0006	JAN 25,2005		ELECTRICAL		40 BRIDGE STREET PARKES, HOWARD J		H Not Assessable
19	1		1020-2006-057+A	OCT 17,2006		HEATING		40 BRIDGE STREET PARKES, HOWARD J		H Not Assessable
19	2		1020-2004-014	JUN 30,2004		PLUMBING WORK		46 BRIDGE STREET BRIDGE STREET BUILDING A		H Not Assessable
19	2		1020-2005-039	JUL 20,2005	JAN 12,2006	RENOVATIONS: MAJOR/SMALL		46 BRIDGE STREET BRIDGE STREET BUILDING A		H Not Assessable

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
19	2		1020-2005-078	DEC 30,2005		ELECTRICAL		46 BRIDGE STREET BRIDGE STREET BUILDING A		H Not Assessable
19	2		1020-2007-007	FEB 9,2007		FIRE SURPRESSION SYSTEM		46 BRIDGE STREET BRIDGE STREET BUILDING A		H Not Assessable
19	2		1020-2007-037+B	SEP 13,2007		SECURITY SYSTEM		46 BRIDGE STREET BRIDGE STREET BUILDING A		H Not Assessable
19	3		1020-2007-009	MAR 7,2007	MAR 7,2007	ELECTRICAL		46-1/2 CARPENTER STREET METAXAS, WILLIAM S		H Not Assessable
19	3		1020-2008-010	MAR 20,2008		RENOVATIONS: MAJOR/SMALL	Renovations / Air Conditioning	46-1/2 CARPENTER STREET METAXAS, WILLIAM S		Assessable
19	4		1020-1992-002+I	MAY 19,1992	SEP 18,1992	COMMERCIAL BUILDING	Remodel store	50-A BRIDGE STREET BUFFA, SALVATORE & ROSAI		H
19	4		1020-1992-002+K	AUG 17,1992	SEP 28,1992	RENOVATION; SMALL	Exhaust Hood / ducts with suppressin	50-A BRIDGE STREET BUFFA, SALVATORE & ROSAI		H
19	4		1020-1993-0 +H	JAN 5,1993	JAN 15,1993	ELECTRICAL	Upgrade to 200 amp service	50-A BRIDGE STREET BUFFA, SALVATORE & ROSAI		H
19	4		1020-1997-008	APR 25,1997	JUL 2,1999	ELECTRICAL		50-A BRIDGE STREET BUFFA, SALVATORE & ROSAI	SEP 8,1997	H Not Assessable
19	4		1020-1997-008+A	MAR 5,1997	SEP 9,1997	PLUMBING WORK		50-A BRIDGE STREET BUFFA, SALVATORE & ROSAI	SEP 9,1997	H Not Assessable
19	4		1020-1998-008+C	NOV 6,1998		ELECTRICAL		50-A BRIDGE STREET BUFFA, SALVATORE & ROSAI		H Not Assessable
19	4		1020-1998-008+B	NOV 6,1998		RENOVATIONS: MAJOR/SMALL		50-A BRIDGE STREET BUFFA, SALVATORE & ROSAI	SEP 14,1999	H Not Assessable
19	4		1020-2004-009+A	FEB 18,2004		RENOVATIONS: MAJOR/SMALL	Redo Dwelling Due To Fire	50-A BRIDGE STREET BUFFA, SALVATORE & ROSAI	SEP 6,2005	H Assessable
19	4		1020-2004-012	MAR 3,2004	MAY 1,2006	PLUMBING WORK	Replace Plumbing Due To Fire	50-A BRIDGE STREET BUFFA, SALVATORE & ROSAI		H Not Assessable
19	4		1020-2004-009+B	MAR 22,2004	MAY 1,2006	RENOVATIONS: MAJOR/SMALL	Repair Of Fire Damage	50-A BRIDGE STREET BUFFA, SALVATORE & ROSAI		H Not Assessable
19	4		1020-2003-073	OCT 20,2003	MAY 1,2006	ELECTRICAL	Fire Damaged Building	50-A BRIDGE STREET BUFFA, SALVATORE & ROSAI		H Not Assessable
19	4		1020-2004-009	APR 7,2004	MAY 1,2006	RENOVATIONS: MAJOR/SMALL		50-A BRIDGE STREET BUFFA, SALVATORE & ROSAI	SEP 3,2004	H Not Assessable
19	4		1020-2004-002	JAN 8,2004	APR 20,2004	MAINTENANCE:(roofing,etc)	Fire Damged Building	50-A BRIDGE STREET BUFFA, SALVATORE & ROSAI		H Not Assessable
19	4		1020-2006-024	APR 27,2006	NOV 27,2006	FIRE SURPRESSION SYSTEM		50-A BRIDGE STREET DCEM PROPERTIES LLC		H Not Assessable
19	4		1020-2006-024+A	MAY 26,2006		ELECTRICAL		50-A BRIDGE STREET BUFFA, SALVATORE & ROSAI		H Not Assessable
19	4		1020-2008-067	DEC 10,2008		BURGLAR ALARM		50-A BRIDGE STREET DCEM PROPERTIES LLC		H Not Assessable
19	5		1020-1996-029+A	MAY 30,1996	SEP 28,1996	RENOVATIONS: MAJOR/SMALL	Electric / Building	58 BRIDGE STREET TOLOTTA, FRANK & JOANN	SEP 28,1996	H
19	5		1020-1997-033	JUN 24,1997	SEP 9,1997	RENOVATIONS: MAJOR/SMALL	Existing Laundry Facility Renovatio	58 BRIDGE STREET TOLOTTA, FRANK & JOANN	SEP 9,1997	H
19	5		1020-1997-037	JUL 15,1997	SEP 9,1997	HEATING		58 BRIDGE STREET TOLOTTA, FRANK & JOANN	SEP 9,1997	H

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
19	5		1020-1998-003	JAN 14,1998	SEP 23,1998	HEATING	Install Gas Fired Hanging Heater	58 BRIDGE STREET TOLOTTA, FRANK & JOANN	SEP 23,1998	H
19	5		1020-2000-043	SEP 27,2000	NOV 6,2000	PLUMBING WORK	Replace Hot Water Heater	58 BRIDGE STREET TOLOTTA, FRANK & JOANN		H Not Assessable
19	5		1020-2002-025	APR 30,2002	JUL 1,2002	HEATING		58 BRIDGE STREET TOLOTTA, FRANK & JOANN		H Not Assessable
19	5		1020-2007-053	AUG 29,2007	DEC 11,2007	SIDING: VINYL / WOOD		58 BRIDGE STREET TOLOTTA, FRANK & JOANN		Assessable
19	6		1020-1993-001+D	MAY 5,1993	JUN 30,1993	COMMERCIAL BUILDING	REPLACE ALUM/PLATE GLASS STORE FRONT	60 BRIDGE STREET ADAMS BAKERY CORPORATI		H
19	6		1020-1993-002	MAY 21,1993	JUN 30,1993	ADDITIONS: MAJOR / MINOR	AWNING ATTACHED TO HOUSE	60 BRIDGE STREET ADAMS BAKERY CORPORATI		H
19	6		1020-1993-005+F	OCT 21,1993	OCT 21,1993	ASSESSMENT DATA REVIEW---	Electric	60 BRIDGE STREET ADAMS BAKERY CORPORATI		H
19	6		1020-2000-050	JAN 18,2000	JUN 20,2000	PLUMBING WORK		60 BRIDGE STREET ADAMS BAKERY CORPORATI		H Not Assessable
19	6		1020-2008-027	MAY 19,2008		SECURITY SYSTEM		60 BRIDGE STREET THE BAKER ACQUISITION CO		H Not Assessable
19	6		1020-2008-069	DEC 23,2008	JAN 12,2009	ELEVATOR	Freight Elevator Alterations	60 BRIDGE STREET THE BAKER ACQUISITION CO		H Not Assessable
19	8		1020-2009-001	JAN 21,2009		RENOVATIONS: MAJOR/SMALL	Gutting Of Interior Walls / Ceiling	21 CARPENTER STREET 21 CAR LLC		Assessable
19	8		1020-2009-001+A	JUN 12,2009		RENOVATIONS: MAJOR/SMALL	No Detail	21 CARPENTER STREET 21 CAR LLC		H Not Assessable
19	9		1020-2001-041	JUN 8,2001	JUN 1,2002	TANK INSTALLED INTERIOR		27 CARPENTER STREET ADAMS BAKERY CORPORATI		H Not Assessable
19	9		1020-2001-041+A	JUN 15,2001		TANK INSTALLED INTERIOR		27 CARPENTER STREET ADAMS BAKERY CORPORATI		H Not Assessable
19	9		1020-2002-006	JAN 24,2002	SEP 10,2002	ELECTRICAL		27 CARPENTER STREET ADAMS BAKERY CORPORATI		H Not Assessable
19	9		1020-2002-006+A	JAN 29,2002		UNKNOWN: BLANK PERMIT		27 CARPENTER STREET ADAMS BAKERY CORPORATI	NOV 1,2002	H Not Assessable
19	9		1020-2002-045	JUL 10,2002		PLUMBING WORK		27 CARPENTER STREET ADAMS BAKERY CORPORATI		H Not Assessable
19	9		1020-2002-006+B	JUN 11,2002		ELECTRICAL		27 CARPENTER STREET ADAMS BAKERY CORPORATI		H Not Assessable
19	9		1020-2002-006+C	JUN 17,2002		AIR CONDITIONING		27 CARPENTER STREET ADAMS BAKERY CORPORATI	SEP 28,2002	H Assessable
19	9		1020-2002-081	NOV 18,2002		HEATING		27 CARPENTER STREET ADAMS BAKERY CORPORATI		H Not Assessable
19	10		1020-1995-036	JUL 31,1995	OCT 30,1996	BASEMENT FINISHED	REPLACE basement floor, drywall,	31 CARPENTER STREET RAUH, SCOTT & VALARIE	SEP 9,1997	H
19	10		1020-1996-036+A	MAR 8,1996	SEP 9,1997	ADDITIONS: MAJOR / MINOR	Addition To Existing Permit	31 CARPENTER STREET RAUH, SCOTT & VALARIE	SEP 9,1997	H
19	10		1020-1999-054	DEC 17,1999	SEP 1,2005	HEATING		31 CARPENTER STREET BERNOTAS, CAROL		H Not Assessable
19	10		1020-2001-083	DEC 3,2001	FEB 4,2003	RADON SYSTEM		31 CARPENTER STREET BERNOTAS, CAROL		H Not Assessable

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
19	10		1020-2002-037	JUN 24,2002	FEB 13,2003	MAINTENANCE:(roofing,etc)	Railings Only	31 CARPENTER STREET BERNOTAS, CAROL		H Not Assessable
19	11		1020-1994-004+C	OCT 7,1994	OCT 21,1994	TANK REMOVAL	basement	37 CARPENTER STREET SENA, PETER		H
19	11		1020-2002-066	OCT 16,2002	JAN 5,2004	RENOVATIONS: MAJOR/SMALL		37 CARPENTER STREET MUSTARDO, PETER & NORA I		H Assessable
19	11		2003-1020-0066	FEB 6,2003		ELECTRICAL	Exit And Emergency Lighting	37 CARPENTER STREET MUSTARDO, PETER & NORA I		H Not Assessable
19	11		1020-2003-021+A	FEB 6,2003		HEATING	Hot Water Boilers	37 CARPENTER STREET MUSTARDO, PETER & NORA I		H Not Assessable
19	11		1020-2003-066+A	JAN 31,2003		PLUMBING WORK		37 CARPENTER STREET MUSTARDO, PETER & NORA I		H Not Assessable
19	12		1020-1994-005+B	NOV 15,1994	MAR 1,1997	MAINTENANCE:(roofing,etc)	.	43 CARPENTER STREET PETRULLO, MICHAEL C & CHI		H
19	12		1020-1994-005+D	NOV 15,1994		MAINTENANCE:(roofing,etc)	.	43 CARPENTER STREET MCNALLY, JAMES B/ JAMES,		H
19	12		1020-1998-041	JUL 10,1998	OCT 1,1998	FIREPLACE / WOODSTOVE	Pellet Stove	43 CARPENTER STREET PETRULLO, MICHAEL C & CHI	SEP 23,1998	H Not Assessable
19	12		1020-2000-004	FEB 25,2000	MAR 15,2000	ELECTRICAL		43 CARPENTER STREET PETRULLO, MICHAEL C & CHI		H Not Assessable
19	12		1020-2000-002	FEB 2,2000	JUL 26,2000	SIDING: VINYL / WOOD		43 CARPENTER STREET PETRULLO, MICHAEL C & CHI	SEP 27,2000	H Not Assessable
19	12		2003-1020-0060	APR 25,2003		FIRE / SMOKE DETECTOR		43 CARPENTER STREET PETRULLO, MICHAEL C & CHI		H Not Assessable
19	12		1020-2003-010+B	APR 30,2003		ELECTRICAL		43 CARPENTER STREET PETRULLO, MICHAEL C & CHI		H Not Assessable
19	12		1020-2002-060	SEP 19,2002	APR 30,2003	RENOVATIONS: MAJOR/SMALL	Expand Enclosed Porch; 1/2 Bath,	43 CARPENTER STREET GITTLEMAN, DWIGHT & DEBC		H Assessable
19	12		1020-2005-064	NOV 3,2005	JUL 18,2006	WOOD DECK / CONCR PATIO	12 X 32	43 CARPENTER STREET GITTLEMAN, DWIGHT M	SEP 6,2006	H Assessable
19	13		1020-1992-004+F	NOV 24,1992	FEB 8,1993	ADDITIONS: MAJOR / MINOR	Adding room; (finishing storage	51 CARPENTER STREET GIRVIN, WILLIAM L & ALICE		H
19	13		1020-1997-012	MAR 26,1997	MAY 5,1997	MAINTENANCE:(roofing,etc)		51 CARPENTER STREET GIRVIN, WILLIAM L & ALICE	SEP 8,1997	H
19	13		1020-2003-033	JUN 5,2003	JUL 10,2003	TANK REMOVAL		51 CARPENTER STREET GIRVIN, MICHAEL J & KATHE		H Not Assessable
19	13		1020-2003-034	JUN 9,2003	JUL 10,2003	AIR CONDITIONING	Replace Heater And A/C	51 CARPENTER STREET GIRVIN, MICHAEL J & KATHE		H Assessable
19	13		1020-2003-035	JUN 13,2003		ELECTRICAL		51 CARPENTER STREET GIRVIN, MICHAEL J & KATHE		H Not Assessable
19	13		1020-2003-038	JUN 30,2003	FEB 2,2005	ELECTRICAL		51 CARPENTER STREET GIRVIN, MICHAEL J & KATHE		H Not Assessable
19	13		1020-2003-040	JUN 30,2003	JUL 10,2003	HEATING		51 CARPENTER STREET GIRVIN, MICHAEL J & KATHE		H Not Assessable
19	13		1020-2003-077	NOV 7,2003	JUN 9,2006	PLUMBING WORK		51 CARPENTER STREET GODLESKY, KATHERINE MAR		H Not Assessable
19	13		1020-2003-077+A	OCT 30,2003	JUN 6,2006	RENOVATIONS: MAJOR/SMALL		51 CARPENTER STREET GODLESKY, KATHERINE MAR	SEP 4,2008	X Assessable

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
19	14		1020-1999-044	OCT 13,1999	OCT 26,1999	RADON SYSTEM		63 CARPENTER STREET BROWN, SARAH R L		H Not Assessable
19	14		1020-2001-054	JUL 18,2001	DEC 12,2001	ROOFING / RE-ROOFING		63 CARPENTER STREET BROWN, SARAH R L	SEP 27,2001	H Not Assessable
19	15		1020-1996-054+A	OCT 15,1996	SEP 8,1997	HEATING	Repl Boiler Weil Mclain	67 CARPENTER STREET MAZIARZ, ELIZABETH	SEP 8,1997	H
19	15		1020-1998-069	NOV 2,1998	MAR 1,1999	ELECTRICAL		67 CARPENTER STREET ALVORD, LINDA		H Not Assessable
19	15		1020-1998-069+A	NOV 23,1998		RENOVATIONS: MAJOR/SMALL	Kitchen, Re-Do House Complete	67 CARPENTER STREET ALVORD, LINDA	SEP 27,2000	H Not Assessable
19	15		1020-1998-069+B	NOV 2,1998		ELECTRICAL		67 CARPENTER STREET ALVORD, LINDA		H Not Assessable
19	15		1020-1998-058	SEP 22,1998	JAN 11,1998	HEATING		67 CARPENTER STREET ALVORD, LINDA		H Not Assessable
19	15		1020-2001-065	SEP 4,2001	DEC 12,2001	SIDING: VINYL / WOOD		67 CARPENTER STREET ALVORD, LINDA	SEP 28,2002	H Assessable
19	16		1020-1997-048	AUG 14,1997		WOOD DECK / CONCR PATIO	Deck: 12 / 18	71 CARPENTER STREET NICHOLSON, JOEL D & CONN	SEP 27,2000	H Assessable
19	16		1020-1999-002	FEB 22,1999		RENOVATIONS: MAJOR/SMALL	Re-Sheetrock / Repl Cabinets	71 CARPENTER STREET NICHOLSON, JOEL D & CONN	SEP 27,2000	H Not Assessable
19	17.01	C0001	1020-2007-084	FEB 16,2007	OCT 1,2008	NEW----RESIDENCE	.	91 CARPENTER STREET CHOKOLA, ELLEN M		Assessable
19	17.01	C0002	1020-2007-084+A	FEB 16,2007	OCT 1,2008	NEW----RESIDENCE	.	91 CARPENTER STREET DAN-MAUR BUILDERS INC		Assessable
19	19		1020-1993-002+G	JUN 24,1993	OCT 18,1993	RECORD ONLY !!!	REPLACE 3000 GAL UG TANK WITH	70 BRIDGE STREET PRESBYTERIAN CHURCH		H
19	19		1020-1994-001+J	MAR 29,1994	MAR 29,1994	NOT ASSESSABLE IMPRVMENT..		70 BRIDGE STREET PRESBYTERIAN CHURCH		H
19	19		1020-1994-003	SEP 6,1994		HEATING		70 BRIDGE STREET PRESBYTERIAN CHURCH		H
19	19		1020-1997-010	NOV 1,1997	NOV 1,1996	MAINTENANCE:(roofing,etc)		70 BRIDGE STREET PRESBYTERIAN CHURCH	SEP 8,1997	H
19	19		1020-1996-008	MAR 19,1996	MAR 4,1999	ELECTRICAL	Hood For Gas Range	70 BRIDGE STREET PRESBYTERIAN CHURCH		H Not Assessable
19	19		1020-1996-025	MAY 2,1996	MAY 2,1996	ELECTRICAL	Electric For Dishwasher	70 BRIDGE STREET PRESBYTERIAN CHURCH		H
19	19		1020-1996-025+A	OCT 21,1996	OCT 21,1996	ELECTRICAL		70 BRIDGE STREET PRESBYTERIAN CHURCH	SEP 8,1997	H
19	19		1020-1997-010+A	MAR 20,1997	APR 9,1997	ASBESTOS REMOVAL		70 BRIDGE STREET PRESBYTERIAN CHURCH	SEP 8,1997	H
19	19		1020-1999-030	JUL 7,1999	JAN 14,2002	MAINTENANCE:(roofing,etc)		70 BRIDGE STREET PRESBYTERIAN CHURCH		H Not Assessable
19	19		1020-2005-044	AUG 19,2005	JAN 7,2009	MISC ITEMS		70 BRIDGE STREET PRESBYTERIAN CHURCH		H Not Assessable
19	19		1020-2005-044+A	OCT 25,2005	OCT 16,2007	BATHROOM	Remodel Bathroom 2 Water Closets /	70 BRIDGE STREET PRESBYTERIAN CHURCH		H Not Assessable
19	19		1020-2006-044	AUG 9,2006		BATHROOM		70 BRIDGE STREET PRESBYTERIAN CHURCH		H Not Assessable

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
19	19		1020-2006-044+C	AUG 18,2006		ELECTRICAL	Bathroom Fans, Paddle Fans	70 BRIDGE STREET PRESBYTERIAN CHURCH		H Not Assessable
19	19		1020-2008-044	FEB 5,2008		ROOFING	.	70 BRIDGE STREET PRESBYTERIAN CHURCH		H Not Assessable
19	20		1020-1994-049	OCT 7,1994	JUN 30,1995	WOOD DECK / CONCR. PATIO	12 x 10	30 FRENCHTOWN ROAD BALLIET, ROBERT T	SEP 27,1995	H
19	21		1020-1995-006	FEB 3,1995	SEP 8,1997	RENOVATIONS: MAJOR/SMALL	library renovation	40 FRENCHTOWN ROAD BOROUGH OF MILFORD	SEP 8,1997	H
19	21		1020-2001-038	JUN 4,2001	JUL 9,2001	HEATING		40 FRENCHTOWN ROAD BOROUGH OF MILFORD		H Not Assessable
19	22		1020-1995-908+D	FEB 3,1995		MAINTENANCE:(roofing,etc)	..	50 FRENCHTOWN ROAD BALLIET, ROBERT S & DIANA		H
19	22		1020-2004-013	MAR 4,2004	MAR 21,2006	MAINTENANCE:(roofing,etc)		50 FRENCHTOWN ROAD BALLIET, ROBERT S & DIANA		H Not Assessable
19	23		1020-1995-056	OCT 24,1995	OCT 24,1996	MAINTENANCE:(roofing,etc)	.	60 FRENCHTOWN ROAD BREITHOFF, CHARLES		H
19	23		1020-2005-024	JUN 2,2005		TANK REMOVAL		60 FRENCHTOWN ROAD BREITHOFF, CHARLES		H Not Assessable
19	23		1020-2005-031	JUN 23,2005	AUG 10,2005	TANK INSTALLED INTERIOR		60 FRENCHTOWN ROAD BREITHOFF, CHARLES		H Not Assessable
19	24		1020-2003-020	APR 30,2003	DEC 11,2003	PLUMBING WORK		70 FRENCHTOWN ROAD PURSELL, DONALD J & JANE		H Not Assessable
19	24.01		1020-2000-039	AUG 30,2000	OCT 24,2000	MAINTENANCE:(roofing,etc)		68 FRENCHTOWN ROAD CHARLES, WILLIAM		H Not Assessable
19	24.01		1020-2003-055	AUG 14,2003	OCT 23,2003	ELECTRICAL		68 FRENCHTOWN ROAD CHARLES, WILLIAM		H Not Assessable
19	24.01		1020-2008-060	OCT 30,2008	NOV 19,2008	HEATING	Replace Boiler	68 FRENCHTOWN ROAD CHARLES, WILLIAM		H Not Assessable
19	25		1020-1996-002	JAN 10,1996	JAN 19,1996	TANK REMOVAL	Replace 275 Gallon Tank	78 FRENCHTOWN ROAD BONHAM, ROSE ANN		H
19	26		1020-1997-020	APR 28,1997	SEP 8,1997	ELECTRICAL	Rewire Front Room	86 FRENCHTOWN ROAD TRAYNOR, FRANK F	SEP 8,1997	H
19	26		1020-2009-013	MAY 11,2009		SIDING: VINYL / WOOD	Siding & Roofing	86 FRENCHTOWN ROAD TRIMMER, KENNETH & JILL		Assessable
19	26		1020-2009-014	MAY 14,2009		DEMOLITION OF BUILDING	Demolition Of Sunroom	86 FRENCHTOWN ROAD TRIMMER, KENNETH & JILL		H Not Assessable
19	26		1020-2009-015	MAY 14,2009		SUNROOM	Replace Exisint Sunroom Use Present	86 FRENCHTOWN ROAD TRIMMER, KENNETH & JILL		Assessable
19	27.01		1020-2004-066	SEP 14,2004	JUL 22,2005	ELECTRICAL		94 FRENCHTOWN ROAD ARNOLD, WALTER C		H Not Assessable
19	28		1020-1996-059	NOV 1,1996	DEC 6,1996	PORCH: ENCLOSED / OPEN	Unheated Porch 10 X 12	114 FRENCHTOWN ROAD WISMER, GEORGE R & LOIS J	SEP 9,1997	H
19	28		1020-2008-050	SEP 10,2008	OCT 16,2008	RENOVATIONS: MAJOR/SMALL	Interior Rafters Shingles	114 FRENCHTOWN ROAD WISMER, GEORGE R & LOIS J		Assessable
19	32		1020-1993-005+G	OCT 15,1993		ASSESSMENT DATA REVIEW---	Re-roofing	156 FRENCHTOWN ROAD HILL, MARY T		H
19	32		1020-2004-056	AUG 11,2004	DEC 10,2004	ELECTRICAL		156 FRENCHTOWN ROAD GOLDBERG, NORMAN J & DIA		H Not Assessable

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
19	33		1020-2002-059	SEP 19,2002	OCT 10,2002	WOOD DECK		164 FRENCHTOWN ROAD ROE, VALERIE K		H Assessable
19	34		1020-1992-002+J	JUN 1,1992	SEP 18,1992	RECORD ONLY !!!	Radon Mitigation System	178 FRENCHTOWN ROAD RAUCH, MARK D & RENEE D		H
19	34		1020-1997-023	MAY 6,1997	SEP 21,2000	ADDITIONS: MAJOR / MINOR		178 FRENCHTOWN ROAD RAUCH, MARK D & RENEE D	SEP 23,1998	H Assessable
19	34		1020-2000-035	AUG 9,2000	SEP 21,2000	ELECTRICAL		178 FRENCHTOWN ROAD RAUCH, MARK D & RENEE D		H Not Assessable
19	34		1020-2002-035	JUN 14,2002	MAY 1,2003	CARPORTS: ATTACH / DETACH	20 X 24	178 FRENCHTOWN ROAD RAUCH, MARK D & RENEE D		H Assessable
19	34		1020-2002-075	DEC 20,2002	MAY 14,2003	PLUMBING WORK	Install 1/2 Bath	178 FRENCHTOWN ROAD RAUCH, MARK D & RENEE D		H Assessable
19	34		1020-2008-036	JUN 30,2008	JUL 31,2008	ROOFING		178 FRENCHTOWN ROAD RAUCH, MARK D & RENEE D		H Not Assessable
19	35		1020-2008-022	MAY 9,2008	JAN 26,2009	HEATING		184 FRENCHTOWN ROAD RAUCH MARK & RENEE/ MAT		H Not Assessable
19	35		1020-2008-023	MAY 9,2008		DEMOLITION OF BUILDING		184 FRENCHTOWN ROAD RAUCH MARK & RENEE/ MAT		Assessable
19	36		1020-1992-005+A	DEC 1,1992		ELECTRICAL	Upgrade to 100 amp service	79 RAVINE ROAD BURKE, ARLEEN P		H
19	36		1020-1997-014	APR 8,1997	APR 15,1997	SIDING: VINYL / WOOD	Install Front Door	79 RAVINE ROAD BURKE, ARLEEN P	SEP 9,1997	H
19	36		1020-2001-078	OCT 29,2001	DEC 10,2001	ROOFING / RE-ROOFING		79 RAVINE ROAD BIANCONI, ARTHUR R		H Not Assessable
19	36		1020-2001-088	DEC 27,2001		ELECTRICAL		79 RAVINE ROAD BIANCONI, ARTHUR R		H Not Assessable
19	42		1020-2009-025	JUN 17,2009		HEATING	Replace Furnace W; Thermo Pride	204 DELAWARE AVENUE WILLIAMS, THOMAS J & SHIR		H Not Assessable
19	43		1020-1995-806+B	JAN 10,1995	JAN 25,1995	ELECTRICAL	install 100 amp service	206 DELAWARE AVENUE MCCONNELL, PATRICK W & K		H
19	43		1020-1998-038	JUL 6,1998	SEP 30,1998	WOOD DECK / CONCR PATIO		206 DELAWARE AVENUE MCCONNELL, PATRICK W & K	SEP 23,1998	H Assessable
19	43		1020-1999-033	JUL 21,1999	MAR 10,2003	ELECTRICAL		206 DELAWARE AVENUE MCCONNELL, PATRICK W & K		H Not Assessable
19	43		1020-2005-071	DEC 6,2005		ELECTRICAL		206 DELAWARE AVENUE MCCONNELL, KANDI KAY		H Not Assessable
19	43		1020-2006-015	MAR 6,2006	APR 25,2006	HEATING		206 DELAWARE AVENUE MCCONNELL, KANDI KAY		H Not Assessable
19	44		1020-2001-069+A	OCT 5,2001		TANK INSTALLED INTERIOR		208 DELAWARE AVENUE APGAR, CHRISTOPHER J & TI		H Not Assessable
19	44		1020-2009-008	APR 17,2009		WOOD DECK	20 X 14	208 DELAWARE AVENUE SCHAEFER, ERIC & MARGARI		Assessable
19	45		1020-2009-009	APR 20,2009		WOOD DECK	20 X 14	210 DELAWARE AVENUE HUNT, ROBERT H JONATHAN		Assessable
19	46		1020-1996-033	JUN 4,1996	JUN 4,1996	MAINTENANCE:(roofing,etc)		212 DELAWARE AVENUE IRELAND, LYNDA M	SEP 8,1997	H
19	46		1020-2003-026	MAY 13,2003	SEP 1,2005	HEATING	Replace Hot Water Heater	212 DELAWARE AVENUE PAULMIER, BRIGITTE LEILI		H Not Assessable

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
19	46		1020-2009-027	JUN 22,2009		ROOFING	.	212 DELAWARE AVENUE PAULMIER, BRIGITTE LEILI		H Not Assessable
19	47		1020-1995-020	MAY 16,1995	SEP 26,1995	HEATING	Weil-McLean boiler	214 DELAWARE AVENUE WHITMAN, CINDY L/ MITCHEL	SEP 26,1995	H
19	47		1020-1996-031	MAY 31,1996	MAY 31,1996	MAINTENANCE:(roofing,etc)		214 DELAWARE AVENUE WHITMAN, CINDY L/ MITCHEL		H
19	48		1020-1992-003+A	JUL 20,1992		POOL: ABOVE GROUND	check for wood deck	216 DELAWARE AVENUE BOURNIAS, FRANK P & BETT'		H
19	48		1020-2001-032	MAY 10,2001	JUN 20,2001	WOOD DECK / CONCR PATIO	Replace Wood Deck	216 DELAWARE AVENUE BOURNIAS, FRANK P & BETT'	SEP 28,2002	H Assessable
19	49		1020-2002-062	SEP 23,2002	NOV 13,2002	ELECTRICAL		218 DELAWARE AVENUE STARKE, JAMES C		H Not Assessable
19	49		1020-2002-068	OCT 18,2002	SEP 21,2005	ADDITIONS: MAJOR / MINOR	Add Kneewall Over Existing Wall	218 DELAWARE AVENUE STARKE, JAMES C		H Assessable
19	49		1020-2002-068+A	OCT 25,2002		FIRE / SMOKE DETECTOR		218 DELAWARE AVENUE STARKE, JAMES C		H Not Assessable
19	49		1020-2002-068+B	DEC 9,2002		AIR CONDITIONING	A C Drain / Fuel Pipe ?????	218 DELAWARE AVENUE STARKE, JAMES C		H Assessable
19	50		1020-1992-003	AUG 9,1992	DEC 30,1992	WOOD DECK / CONCR. PATIO	Patio Deck w/BBQ	220 DELAWARE AVENUE AUSTIN, JEFFREY R & KATHL		H
19	50		1020-1992-003+C	SEP 18,1992	NOV 6,1992	RENOVATIONS: MAJOR/SMALL	Replace windows,	220 DELAWARE AVENUE AUSTIN, JEFFREY R & KATHL		H
19	50		1020-1992-004+C	NOV 11,1992	SEP 23,1993	ELECTRICAL	Install 2 electrical outlets	220 DELAWARE AVENUE AUSTIN, JEFFREY R & KATHL		H
19	50		1020-2000-046	OCT 12,2000	DEC 8,2000	MAINTENANCE:(roofing,etc)		220 DELAWARE AVENUE AUSTIN, JEFFREY R & KATHL		H Not Assessable
19	51		1020-1989-013	APR 19,1989	DEC 5,1990	COMMERCIAL BUILDING	SKY CABLE INSTALLATION	FRENCHTOWN ROAD CROWN PAPER CO		H
19	51		1020-1989-015	JUN 9,1989	DEC 5,1990	DEMOLITION OF BUILDING	DEMOLISH 3-STORY BUILDINGS	FRENCHTOWN ROAD CROWN PAPER CO		H
19	51		1020-1991-011+A	MAY 17,1991		COMMERCIAL BUILDING	PROCESSING ROOM IN PLANT	FRENCHTOWN ROAD CROWN PAPER CO		H
19	51		1020-1991-013+C	AUG 9,1991		MAINTENANCE:(roofing,etc)	ELECTRICAL MORTORS/SERVICE	FRENCHTOWN ROAD CROWN PAPER CO		H
19	51		1020-1991-015+A	AUG 20,1991		AIR CONDITIONING	A/C UNIT ROOF	FRENCHTOWN ROAD CROWN PAPER CO		H
19	51		1020-1991-015+C	AUG 20,1991		HEATING	VENTILATION SYSTEM FOR PROCESS	FRENCHTOWN ROAD CROWN PAPER CO		H
19	51		1020-1992-002+G	JUN 10,1992	JUN 10,1992	MAINTENANCE: (roofing)	Roof removal and reinstallation	FRENCHTOWN ROAD CROWN PAPER CO		H
19	51		1020-1994-004+A	OCT 7,1994	FEB 24,1995	MAINTENANCE:(roofing,etc)	.	FRENCHTOWN ROAD CROWN PAPER CO		H
19	51		1020-1995-801	MAR 23,1995		ELECTRICAL	.	FRENCHTOWN ROAD ROYAL BLUE PAPERS INC		H
19	51		1020-1995-907+C	FEB 27,1995		ELECTRICAL	1 30 amp 120 v pole mounted service	FRENCHTOWN ROAD ROYAL BLUE PAPERS INC		H
19	51		1020-1996-004	FEB 7,1996	MAR 6,1996	MAINT: (Roofing, etc)	Changing Sprinkler System	FRENCHTOWN ROAD CROWN PAPER CO		H

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
19	51		1020-1996-057	OCT 31,1996	SEP 8,1997	ELECTRICAL	Receptacles/ Heaters	FRENCHTOWN ROAD CROWN PAPER CO	SEP 8,1997	H
19	51		1020-1998-066	NOV 1,1998	JAN 21,1999	DEMOLITION OF BUILDING		FRENCHTOWN ROAD CROWN PAPER CO		H Not Assessable
19	51		1020-1998-067	OCT 30,1998	JAN 21,1999	DEMOLITION OF BUILDING		FRENCHTOWN ROAD CROWN PAPER CO		H Not Assessable
19	51		1020-2003-062	AUG 29,2003	NOV 21,2003	MAINTENANCE:(roofing,etc)		FRENCHTOWN ROAD ROYAL BLUE PAPERS INC		H Not Assessable
19	51		1020-2003-014	OCT 23,2003		COMMERCIAL BUILDING	Install Att Wireless Antennas On	FRENCHTOWN ROAD ROYAL BLUE PAPERS INC	SEP 6,2005	H Assessable
19	51		1020-2005-020	MAY 10,2005		ELECTRICAL		FRENCHTOWN ROAD ROYAL BLUE PAPERS INC		H Not Assessable
19	51		1020-2005-030	JUN 22,2005		DEMOLITION OF BUILDING	Demolition Of Machinery	FRENCHTOWN ROAD ROYAL BLUE PAPERS INC		H Not Assessable
19	51		1020-2005-033	JUN 28,2005		MISC ITEMS		FRENCHTOWN ROAD ROYAL BLUE PAPERS INC		H Not Assessable
19	51		1020-2007-040	JUN 29,2007		ELECTRICAL	Temp Service / Subpanel	FRENCHTOWN ROAD ROYAL BLUE PAPERS INC		H Not Assessable
19	51		1020-2008-028	MAY 21,2008		ELECTRICAL		FRENCHTOWN ROAD ROYAL BLUE PAPERS INC		H Not Assessable
19	51.01		1020-1999-003	MAR 1,1999	APR 13,1999	MAINTENANCE:(roofing,etc)		200 FRENCHTOWN ROAD HUNTERDON MEDICAL CTR F		H Not Assessable
19	51.01		1020-2004-076	NOV 10,2004		RENOVATIONS: MAJOR/SMALL		200 FRENCHTOWN ROAD HUNTERDON MEDICAL CTR F	SEP 13,2005	H Not Assessable
19	51.01		1020-2005-076	FEB 24,2005	FEB 23,2007	FIRE DETECTOR		200 FRENCHTOWN ROAD HUNTERDON MEDICAL CTR F		H Not Assessable
19	52		1020-1994-030	JUL 15,1994	SEP 26,1995	POOL: ABOVE GROUND	.	113 CARPENTER STREET CLARK, KATHLEEN C	SEP 26,1995	H
19	54		1020-2006-010	FEB 16,2006		AIR CONDITIONING	Install 2 New Heat Pumps In Attic /	99 CARPENTER STREET ZABOWSKI, ALAN & JILL	AUG 28,2007	X Assessable
19	54		1020-2005-072+A	DEC 6,2005		ELECTRICAL		99 CARPENTER STREET ZABOWSKI, ALAN & JILL		H Not Assessable
19	54		1020-2006-047	SEP 7,2006	SEP 5,2006	ELECTRICAL		99 CARPENTER STREET ZABOWSKI, ALAN & JILL		H Not Assessable
19	54		1020-2008-031	MAY 30,2008	JUL 14,2008	GARAGE: DETACHED	Concrete Floor Only In Barn Existin	99 CARPENTER STREET ZABOWSKI, ALAN & JILL	SEP 4,2008	H Assessable
19	54		1020-2008-031+A	MAY 30,2008		WOOD STOVE	No Fireplace Assessed	99 CARPENTER STREET ZABOWSKI, ALAN & JILL	SEP 4,2008	H Assessable
Block	20									
20	1		1020-2009-022	JUN 8,2009		ROOFING	.	55 FRENCHTOWN ROAD MILFORD UNION CEMETERY ,		H Not Assessable
20	2.01		1020-2003-086	DEC 5,2003	AUG 10,2004	NEW----RESIDENCE	Single Family Dwelling	9 CROSSFIELD COURT O'CONNELL, SEAMUS P & EM	SEP 3,2004	H Assessable
20	2.01		1020-2007-047	SEP 6,2007	DEC 6,2007	GENERATOR		9 CROSSFIELD COURT O'CONNELL, SEAMUS P & EM		H Not Assessable
20	2.02		1020-2003-081	NOV 13,2003	JAN 13,2005	NEW----RESIDENCE	Single Family Dwelling	15 CROSSFIELD COURT BACHRACH, RICHARD & HELI	SEP 6,2005	H Assessable

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
20	2.02		1020-2006-034	JUN 20,2006		WOOD DECK / CONCR PATIO		15 CROSSFIELD COURT BACHRACH, RICHARD & HELI		Assessable
20	2.03		1020-2003-084	DEC 1,2003	AUG 10,2004	NEW----RESIDENCE	Oakridge Elev 1	17 CROSSFIELD COURT WEST, RICHARD B JR & SHEI	SEP 3,2004	H Assessable
20	2.03		1020-2005-084	AUG 10,2005		ELECTRICAL		17 CROSSFIELD COURT WEST, RICHARD B JR & SHEI		H Not Assessable
20	2.03		1020-2005-015	MAR 22,2005		BASEMENT FINISHED		17 CROSSFIELD COURT WEST, RICHARD B JR & SHEI		Assessable
20	2.03		1020-2005-065	NOV 7,2005	NOV 21,2006	FIREPLACE / WOODSTOVE		17 CROSSFIELD COURT WEST, RICHARD B JR & SHEI		H Not Assessable
20	2.03		1020-2007-029	JUN 4,2007	DEC 31,2007	SHED: SMALL (< 200 SF)	12	17 CROSSFIELD COURT WEST, RICHARD B JR & SHEI		H Not Assessable
20	2.04		1020-2003-088	DEC 5,2003	SEP 27,2004	NEW----RESIDENCE	Single Family Dwelling	20 CROSSFIELD COURT MICHELETTI, JOSEPH M & EL	SEP 6,2005	H Assessable
20	2.04		1020-2005-007	JAN 26,2005	OCT 6,2005	BASEMENT FINISHED		20 CROSSFIELD COURT MICHELETTI, JOSEPH M & EL	SEP 6,2005	H Assessable
20	2.04		1020-2006-044+A	AUG 22,2006		WOOD DECK		20 CROSSFIELD COURT MICHELETTI, JOSEPH M & EL	SEP 3,2008	X Assessable
20	2.05		1020-2004-006	FEB 9,2004	OCT 28,2004	NEW----RESIDENCE	Single Family Dwelling	16 CROSSFIELD COURT SATTLER ROLAND A / NANCY	SEP 6,2005	H Assessable
20	2.05		1020-2004-060+A	FEB 9,2004		PLUMBING WORK		16 CROSSFIELD COURT SATTLER ROLAND A / NANCY		H Assessable
20	2.06		1020-2003-087	DEC 5,2003	SEP 24,2004	NEW----RESIDENCE	Single Family Dwelling	12 CROSSFIELD COURT RADANO, MICHAEL G & JENN	SEP 6,2005	H Assessable
20	2.06		1020-2005-019	MAY 6,2005	AUG 30,2005	WOOD DECK / CONCR PATIO	SIZE: 34 X14	12 CROSSFIELD COURT RADANO, MICHAEL G & JENN	SEP 6,2005	H Assessable
20	2.07		1020-2004-003	JAN 13,2004	DEC 21,2004	NEW----RESIDENCE		8 CROSSFIELD COURT CIPRIANO, JAMES & SHERI	SEP 6,2005	H Assessable
20	2.07		1020-2007-061	SEP 28,2007		SHED: SMALL (< 200 SF)	With Electric And Lights	8 CROSSFIELD COURT CIPRIANO, JAMES & SHERI		H Assessable
20	2.07		1020-2007-062	SEP 28,2007		WOOD DECK	W/ Stairs	8 CROSSFIELD COURT CIPRIANO, JAMES & SHERI		Assessable
20	3		1020-1997-051	SEP 11,1997	SEP 18,1998	WATER SERVICE		124 MILFORD-MT PLEA ROAD RULE, RAYMOND E JR & LIND		H
20	4		1020-1996-021	APR 26,1996	MAR 12,1999	FIREPLACE / WOODSTOVE	Reline Existing Chimney Install	124 MILFORD-MT PLEA ROAD RULE, RAYMOND E JR & LIND	SEP 27,1996	H Not Assessable
20	4		1020-1997-016	APR 16,1997	APR 24,1997	MAINTENANCE:(roofing,etc)	See 97-056	124 MILFORD-MT PLEA ROAD FISHER, LINDA	SEP 8,1997	H
20	4		1020-1997-016+A	APR 11,1997	SEP 8,1997	ELECTRICAL		124 MILFORD-MT PLEA ROAD FISHER, LINDA	SEP 8,1997	H
20	4		1020-1997-016+B	APR 11,1997	APR 24,1997	POOL: ABOVE GROUND	Installation Of Swimming Pool	124 MILFORD-MT PLEA ROAD FISHER, LINDA	SEP 9,1997	H
20	4		1020-2000-042	SEP 22,2000	JAN 26,2001	MAINTENANCE:(roofing,etc)		124 MILFORD-MT PLEA ROAD RULE, RAYMOND E JR & LIND		H Not Assessable
20	5		1020-2004-067	SEP 17,2004	DEC 30,2004	NEW----RESIDENCE		123 HILLCREST DRIVE LANKFORD, JAMES C & EILEE	SEP 6,2005	H Assessable
20	5		1020-2004-067+A	OCT 12,2004		GARAGES: Attach / Detach		123 HILLCREST DRIVE LANKFORD, JAMES C & EILEE	SEP 6,2005	H Assessable

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
20	5		1020-2004-067+B	DEC 7,2004		PLUMBING WORK		123 HILLCREST DRIVE LANKFORD, JAMES C & EILEE		H Not Assessable
20	6		1020-1996-006	MAR 5,1996	APR 1,1996	TANK REMOVAL		155 HILLCREST DRIVE SZWEC, BRONISLAUS & AGNI		H
20	6		1020-2003-013	MAR 28,2003	FEB 2,2005	SHEDS: LARGE / SMALL	10 X 16	155 HILLCREST DRIVE SZWEC, BRONISLAUS & AGNI		H Not Assessable
20	7		1020-1996-036	JUN 14,1996	JUL 25,1997	SIDING: VINYL / WOOD	Roofing, Siding, Windows, Railing	135 HILLCREST DRIVE SZWEC, BRONISLAW	SEP 28,1996	H
Block	21									
21	2		1020-1994-022	MAY 20,1994	SEP 26,1995	WOOD DECK / CONCR. PATIO	repairs to existing deck	230 MILFORD-MT PLEA ROAD BUTLER, GEORGE F & ELIZAE	SEP 26,1995	H
21	3		1020-2007-018	APR 5,2007	MAR 4,2009	TANK INSTALLED INTERIOR	Basement	232 MILFORD-MT PLEA ROAD MILLER, KEITH		H Not Assessable
21	3		1020-2007-019	APR 5,2007	FEB 18,2009	TANK REMOVAL	.	232 MILFORD-MT PLEA ROAD MILLER, KEITH		H Not Assessable
21	4		1020-2006-064	NOV 28,2006	DEC 27,2006	ROOFING		12 STOVER AVENUE ALLER, HAZEL H		H Not Assessable
21	5.01		1020-2002-072	OCT 22,2002	JUN 8,2004	MAINTENANCE:(roofing,etc)		5 NORTH RIDGE COURT MILLWOOD BUILDERS INC		H Not Assessable
21	5.01		1020-2004-007+A	FEB 9,2004	OCT 1,2004	NEW----RESIDENCE	Single Family Dwelling	5 NORTH RIDGE COURT PORTLAND, SCOTT M & KELL	SEP 6,2005	H Assessable
21	5.01		1020-2004-007	MAR 24,2004	OCT 29,2004	NEW----RESIDENCE UPDATE		5 NORTH RIDGE COURT PORTLAND, SCOTT M & KELL		H Not Assessable
21	5.02		1020-2003-048	JUL 17,2003	AUG 10,2004	NEW----RESIDENCE	Model: Windbrook Elev 3	9 NORTH RIDGE COURT MORRISON, PHILIP J & CHRI	SEP 4,2004	H Assessable
21	5.02		1020-2003-048+A	DEC 22,2003		ELECTRICAL		9 NORTH RIDGE COURT MORRISON, PHILIP J & CHRI		H Not Assessable
21	5.02		1020-2006-901	SEP 6,2006		PATIO	Patio In Rear Of Property	9 NORTH RIDGE COURT MORRISON, PHILIP J & CHRI	SEP 8,2006	H Assessable
21	5.02		1020-2006-040	AUG 7,2006	SEP 5,2006	ELECTRICAL	Rain Sensor	9 NORTH RIDGE COURT MORRISON, PHILIP J & CHRI		H Not Assessable
21	5.03		1020-2004-063	SEP 13,2004	OCT 24,2005	NEW----RESIDENCE	Single Family Dwelling Proto	15 NORTH RIDGE COURT REVELL, ALAN J & AIDA L	SEP 6,2006	H Assessable
21	5.03		1020-2004-063+A	FEB 9,2004		PLUMBING WORK		15 NORTH RIDGE COURT REVELL, ALAN J & AIDA L		H Assessable
21	5.03		1020-2005-304	OCT 14,2005		PLUMBING WORK		15 NORTH RIDGE COURT REVELL, ALAN J & AIDA L		H Assessable
21	5.03		1020-2006-023	APR 21,2006	MAY 2,2006	HOT TUB		15 NORTH RIDGE COURT REVELL, ALAN J & AIDA L		H Not Assessable
21	5.03		1020-2006-038	MAY 1,2006	AUG 3,2006	SOLAR PANELS		15 NORTH RIDGE COURT REVELL, ALAN J & AIDA L		H Not Assessable
21	5.04		1020-2004-038+B	MAY 14,2004	APR 7,2005	NEW----RESIDENCE		17 NORTH RIDGE COURT HILKE, JOHN E & MICHELLE		H Not Assessable
21	5.04		1020-2004-038	AUG 30,2004	APR 7,2005	NEW----RESIDENCE	Model: ??	17 NORTH RIDGE COURT HILKE, JOHN E & MICHELLE	SEP 6,2005	H Assessable
21	5.04		1020-2004-038+A	NOV 1,2004	APR 7,2005	ADDITIONS: MAJOR / MINOR		17 NORTH RIDGE COURT HILKE, JOHN E & MICHELLE		H Assessable

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
21	5.04		1020-2008-014	APR 11,2008		WOOD DECK	660 Sf Of Deck	17 NORTH RIDGE COURT HILKE, JOHN E & MICHELLE	SEP 3,2008	H Assessable
21	5.04		1020-2009-003	FEB 9,2009		BASEMENT FINISHED	.	17 NORTH RIDGE COURT HILKE, JOHN E & MICHELLE		Assessable
21	5.05		1020-2004-004	JAN 13,2004	DEC 22,2004	NEW----RESIDENCE	Single Family Dwelling	21 NORTH RIDGE COURT TORREY, TIMOTHY A & MERE	SEP 6,2005	H Assessable
21	5.05		1020-2004-004+A	DEC 22,2004	DEC 22,2004	PLUMBING WORK	First Floor Shower	21 NORTH RIDGE COURT TORREY, TIMOTHY A & MERE		H Assessable
21	5.05		1020-2006-029	MAY 22,2006	OCT 27,2006	WOOD DECK	Check This One Owner Says Not Final	21 NORTH RIDGE COURT TORREY, TIMOTHY A & MERE	SEP 6,2006	H Assessable
21	5.06		1020-2004-064	SEP 13,2004	AUG 18,2005	NEW----RESIDENCE	Proto?	25 NORTH RIDGE COURT SCHAEFER, SCOTT E & JENN	SEP 6,2005	H Assessable
21	5.06		1020-2007-027	MAY 7,2007	JAN 7,2009	WOOD DECK	16 X 24	25 NORTH RIDGE COURT SCHAEFER, SCOTT E & JENN	SEP 3,2008	H Assessable
21	6		1020-1995-044	AUG 31,1995	SEP 27,1996	SHEDS: LARGE / SMALL	Size: 12x 12	245 HILLCREST DRIVE SEWAK, DOLORES/ WILLIAM	SEP 27,1996	H
21	6		1020-2002-016	MAR 13,2002	MAR 4,2003	ROOFING / RE-ROOFING		245 HILLCREST DRIVE SEWAK, DOLORES		H Not Assessable
21	6		1020-2002-064	OCT 10,2002	FEB 25,2003	SIDING: VINYL / WOOD		245 HILLCREST DRIVE SEWAK, DOLORES	SEP 22,2003	H Not Assessable
21	6		1020-2007-048	AUG 1,2007	OCT 16,2007	AIR CONDITIONING		245 HILLCREST DRIVE SEWAK, DOLORES	SEP 3,2008	H Assessable
21	6		1020-2007-054+A	SEP 6,2007		TANK REMOVAL		245 HILLCREST DRIVE SEWAK, DOLORES		H Not Assessable
21	6		1020-2007-056	SEP 11,2007	OCT 15,2007	TANK INSTALLED INTERIOR	275 Gal Tank	245 HILLCREST DRIVE SEWAK, DOLORES		H Not Assessable
21	7		1020-1994-051	OCT 28,1994	NOV 17,1994	HEATING	warm air furnace	235 HILLCREST DRIVE BECHTEL, STEVEN C & DEBC		H
21	7		1020-1995-032	JUL 13,1995	DEC 30,1996	AIR CONDITIONING		235 HILLCREST DRIVE BECHTEL, STEVEN C & DEBC	SEP 9,1997	H
21	7		1020-1998-046	JUL 27,1998	JUL 27,1998	TANK INSTALLED INTERIOR		235 HILLCREST DRIVE BECHTEL, STEVEN C & DEBC		H
21	8		1020-2007-041	JUL 5,2007	JUL 30,2007	HOT WATER HEATER		233 HILLCREST DRIVE BIGLEY, VINCENT		H Not Assessable
21	9		1020-1998-015	MAR 27,1998	MAR 27,1998	TANK INSTALLED INTERIOR		215 HILLCREST DRIVE RULE, RAYMOND		H
21	9		1020-1999-017	MAY 21,1999	AUG 11,1999	MAINTENANCE:(roofing,etc)		215 HILLCREST DRIVE RULE, RAYMOND		H Not Assessable
21	9		1020-2004-023	APR 21,2004		HEATING		215 HILLCREST DRIVE RULE, RAYMOND		H Not Assessable
21	10		1020-2001-007	FEB 8,2001	MAY 23,2005	AIR CONDITIONING	Install 6 Ton Air Condition	203 HILLCREST DRIVE SLOFF, SANDRA	SEP 27,2001	H Assessable
21	10		1020-2000-058	DEC 12,2000	FEB 27,2001	PORCH: ENCLOSED / OPEN	10 X 16	203 HILLCREST DRIVE SLOFF, RICHARD	SEP 27,2001	H Assessable
21	10		1020-2006-039	AUG 3,2006	OCT 24,2006	ROOFING		203 HILLCREST DRIVE SLOFF, SANDRA		H Not Assessable
21	11		1020-2003-050	JUL 21,2003	APR 20,2004	SIDING: VINYL / WOOD	Still Doing Work Inside; Bathroom T	199 HILLCREST DRIVE LUTZ, CHARLES	SEP 8,2006	H Assessable

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
Block	22									
22	1		1020-1995-013	APR 11,1995	MAY 10,1995	AIR CONDITIONING	add on	266 MILFORD-MT PLEA ROAD BLEW, BENJAMIN C & KAREN	SEP 26,1995	H
22	1		1020-1995-018	MAY 10,1995	SEP 26,1995	SIDING: VINYL / WOOD	.	266 MILFORD-MT PLEA ROAD BLEW, BENJAMIN C & KAREN	SEP 26,1995	H
22	2		1020-1993-003+F	JUL 21,1993	AUG 1,1993	AIR CONDITIONING	INSTALL CENTRAL AIR CONDITIONING	272 MILFORD-MT PLEA ROAD FATULA, TROY & BETTY		H
22	2		1020-2006-022	APR 1,2006		RENOVATIONS: MAJOR/SMALL	Addition / Alteration	272 MILFORD-MT PLEA ROAD FATULA, TROY & BETTY	SEP 3,2008	H Assessable
22	2		1020-2006-022+A	SEP 18,2006		ELECTRICAL	Sub Panel	272 MILFORD-MT PLEA ROAD FATULA, TROY & BETTY		H Not Assessable
22	4		1020-2001-050	JUL 9,2001	FEB 25,2003	SHEDS: LARGE / SMALL		31 STOVER AVENUE WOOLF, KIMBERLY R & EDW/	JUL 22,2002	H Assessable
22	4		1020-2007-017	MAR 29,2007		SIDING: VINYL / WOOD		31 STOVER AVENUE WOOLF, KIMBERLY R & EDW/		Assessable
22	6		1020-1995-001	JAN 3,1995	JAN 17,1995	HEATING	.	278 MILFORD-MT PLEA ROAD LEOPOLD, STEVE L & JOAN M	SEP 26,1995	H
22	6		1020-2007-049	AUG 16,2007	AUG 30,2007	RADON SYSTEM		278 MILFORD-MT PLEA ROAD LEOPOLD, STEVEN L & MELIS		H Not Assessable
22	7		1020-1995-037	AUG 3,1995	SEP 26,1995	SHEDS: LARGE / SMALL	.	284 MILFORD-MT PLEA ROAD QUINN, ROBERT L & DONNA S	SEP 26,1995	H
22	7		1020-1998-036	JUN 16,1998		ADDITIONS: MAJOR / MINOR	Addition	284 MILFORD-MT PLEA ROAD QUINN, ROBERT L & DONNA S		H Assessable
22	7		1020-1998-034	JUN 16,1998		ADDITIONS: MAJOR / MINOR		284 MILFORD-MT PLEA ROAD QUINN, ROBERT L & DONNA S		H Not Assessable
22	7		1020-2001-098	JUL 12,2001		WOOD DECK / CONCR PATIO		284 MILFORD-MT PLEA ROAD QUINN, ROBERT L & DONNA S		H Assessable
22	7		1020-2005-034	MAY 26,2005		ELECTRICAL		284 MILFORD-MT PLEA ROAD QUINN, ROBERT L & DONNA S		H Not Assessable
22	7		1020-2005-034+A	JUN 21,2005		AIR CONDITIONING	Owner Call Inspect What?	284 MILFORD-MT PLEA ROAD LAVOIE, KEVIN & KATHLEEN	SEP 4,2008	Assessable
22	7		1020-2007-030	JUN 21,2007	JAN 31,2008	SHED: LARGE	Shed 12 X 24	284 MILFORD-MT PLEA ROAD LAVOIE, KEVIN & KATHLEEN	SEP 4,2008	X Assessable
22	8		1020-1999-047	NOV 12,1999		ALTERATIONS	Sheet Rock / Plumbing	290 MILFORD-MT PLEA ROAD KUGELMAN, THOMAS	SEP 27,2000	H Not Assessable
22	8		1020-2002-065	OCT 16,2002	MAR 4,2003	MAINTENANCE:(roofing,etc)		290 MILFORD-MT PLEA ROAD LYNCH, ROBERT		H Not Assessable
22	8		1020-2009-016	MAY 18,2009		POOL: ABOVE GROUND	.	290 MILFORD-MT PLEA ROAD LYNCH, ROBERT		H Not Assessable
22	8		1020-2009-017	MAY 18,2009		HOT WATER HEATER	Install Hot Water Boiler Wtgo-4	290 MILFORD-MT PLEA ROAD LYNCH, ROBERT		H Not Assessable
22	9		1020-2001-039	JUN 5,2001	JUL 6,2001	RENOVATIONS: MAJOR/SMALL	Repairs To Existing Balcony Damage	295 HILLCREST DRIVE HUNT, WILLIAM & SUSAN		H Not Assessable
22	9		1020-2003-009	MAR 4,2003	APR 16,2003	MAINTENANCE:(roofing,etc)		293-295 HILLCREST DRIVE HUNT, WILLIAM & SUSAN		H Not Assessable
22	10		1020-2005-032	JUN 27,2005	SEP 1,2005	HOT WATER HEATER		289 HILLCREST DRIVE DRAKE, JAMES P & TANYA M		H Not Assessable

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
22	12		1020-1995-014	APR 18,1995	NOV 14,1996	MAINTENANCE:(roofing,etc)	.	287 HILLCREST DRIVE SWIATKOWSKI, JOAN		H
Block	23									
23	1		1020-1994-020	MAY 10,1994	SEP 27,1994	HEATING	Install Boch 32-E oil fired hot	386 MILFORD-MT PLEA ROAD MADISON, JEAN M	SEP 26,1995	H
23	1		1020-2003-069	SEP 22,2003	MAR 4,2005	WOOD DECK / CONCR PATIO	Repair...Check	386 MILFORD-MT PLEA ROAD KENDIG, BRETT K		H Assessable
23	1		1020-2007-054	JUN 22,2007		ELECTRICAL		386 MILFORD-MT PLEA ROAD KENDIG, BRETT K		H Not Assessable
23	1		1020-2007-034	MAY 1,2007	JUL 5,2007	ELECTRICAL		386 MILFORD-MT PLEA ROAD KENDIG, BRETT K		H Not Assessable
23	1		1020-2008-008	FEB 27,2008	JUN 2,2008	ADDITIONS: MAJOR / MINOR	2nd Floor Addition Includes 3 Bedro	386 MILFORD-MT PLEA ROAD HEALY, BRETT K & CONNOR		H Assessable
23	2		1020-1993-001+B	MAY 13,1993	MAR 3,1995	MAINTENANCE:(roofing,etc)	REPLACE ROOFING	380 MILFORD-MT PLEA ROAD JACOB, ROBERT K		H
23	3		1020-1992-003+K	SEP 25,1992	SEP 27,1993	MAINTENANCE:(roofing,etc)	Re-Roofing	374 MILFORD-MT PLEA ROAD WILLIAMS, DONALD & VIOLET		H
23	3		1020-1993-001+J	MAY 7,1993	JUL 30,1993	ADDITIONS: MAJOR / MINOR	ROOF PLACED OVER REAR PORCH	374 MILFORD-MT PLEA ROAD WILLIAMS, DONALD & VIOLET		H
23	3		1020-1995-052	SEP 19,1995	OCT 30,1995	SIDING: VINYL / WOOD	.	374 MILFORD-MT PLEA ROAD WILLIAMS, DONALD & VIOLET		H
23	5		1020-1997-018	APR 7,1997	APR 24,1997	ELECTRICAL		360 MILFORD-MT PLEA ROAD LANCE, JAY K	SEP 8,1997	H
23	5.01		1020-1993-005+E	OCT 26,1993	MAR 18,1994	GARAGES: ATTACH / DETACH	Construct detached 2-car garage	350 MILFORD-MT PLEA ROAD PHILKILL, GERALD D		H
23	5.01		1020-1993-005+J	NOV 17,1993	MAR 18,1994	ELECTRICAL	electric in detached garage additin	350 MILFORD-MT PLEA ROAD PHILKILL, GERALD D		H
23	5.01		1020-1994-008	FEB 22,1994	JUL 30,1994	ADDITIONS: MAJOR / MINOR	Kitchen, Laundry room	350 MILFORD-MT PLEA ROAD COOPER, RAYMOND H & SHA	SEP 27,1995	H
23	5.01		1020-2004-040	JUN 11,2004	AUG 10,2004	WATER SERVICE		350 MILFORD-MT PLEA ROAD PARENTE, BRUNO		H Not Assessable
23	5.01		1020-2004-062	AUG 27,2004	JUN 22,2007	POOLS INGROUND: F / G / V	16 X 32 VINYL	350 MILFORD-MT PLEA ROAD PARENTE, BRUNO	SEP 13,2005	H Assessable
23	5.02		1020-2000-032	JUL 11,2000	NOV 21,2000	NEW----RESIDENCE		340 MILFORD-MT PLEA ROAD ZUR, CHRISTOPHER & LONA	SEP 27,2001	H Assessable
23	5.02		1020-2001-061	FEB 1,2001		NEW----RESIDENCE UPDATE	Interior Wall	340 MILFORD-MT PLEA ROAD ZUR, CHRISTOPHER & LONA		H Not Assessable
23	5.02		1020-2000-061	DEC 29,2000	AUG 28,2008	ELECTRICAL	.	340 MILFORD-MT PLEA ROAD BRADBURY, LONA		H Not Assessable
23	5.02		1020-2000-032+A	OCT 4,2000		NEW----RESIDENCE UPDATE		340 MILFORD-MT PLEA ROAD ZUR, CHRISTOPHER & LONA		H Assessable
23	5.02		1020-2000-036	OCT 11,2000	OCT 24,2000	ELECTRICAL		340 MILFORD-MT PLEA ROAD ZUR, CHRISTOPHER & LONA		H Not Assessable
23	5.02		1020-2000-032+B	NOV 15,2000		PLUMBING WORK		340 MILFORD-MT PLEA ROAD ZUR, CHRISTOPHER & LONA		H Not Assessable
23	5.02		1020-2002-074	OCT 24,2002	MAR 12,2003	PLUMBING WORK		340 MILFORD-MT PLEA ROAD ZUR, CHRISTOPHER & LONA		H Not Assessable

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
23	5.02		1020-2002-079	NOV 4,2002	APR 20,2004	WOOD DECK	15 X 10	340 MILFORD-MT PLEA ROAD ZUR, CHRISTOPHER & LONA		H Assessable
23	5.02		1020-2004-015	MAR 8,2004		BASEMENT FINISHED	Finished Only Walls W/ Insulation	340 MILFORD-MT PLEA ROAD ZUR, CHRISTOPHER & LONA		H Not Assessable
23	6		1020-2001-022	MAR 30,2001	AUG 30,2001	AIR CONDITIONING		7 POND LANE MCCRACKEN, TIMOTHY & ELI	SEP 27,2001	H Assessable
23	6		1020-2005-037	JUL 19,2005	APR 6,2006	TANK INSTALLED INTERIOR		7 POND LANE MCCRACKEN, TIMOTHY & ELI		H Not Assessable
23	6		1020-2005-038	JUL 19,2005	JAN 26,2007	TANK REMOVAL		7 POND LANE MCCRACKEN, TIMOTHY & ELI		H Not Assessable
23	6		1020-2007-042	JUL 5,2007		SUNROOM		7 POND LANE MCCRACKEN, TIMOTHY & ELI	SEP 3,2008	H Assessable
23	6		1020-2008-037	JUL 7,2008	OCT 16,2008	WOOD DECK	Wood Decks	7 POND LANE MCCRACKEN, ELIZABETH	SEP 3,2008	H Assessable
23	7		2004-1020-0080	APR 17,2004		MAINTENANCE:(roofing,etc)		294 HILLCREST DRIVE SCHUYLER, PHILIP G & DEBR		H Not Assessable
23	8		1020-1992-004+A	OCT 28,1992		MAINTENANCE:(roofing,etc)	ReRoofing/Vent	312 MILFORD-MT PLEA ROAD BERNHARDT, KARL W & KATI		H
23	8		1020-2006-066	DEC 15,2006	MAY 21,2007	SIDING: VINYL / WOOD		312 MILFORD-MT PLEA ROAD BERNHARDT, KARL W & KATI	AUG 28,2007	X Assessable
23	8		1020-2006-068	DEC 21,2006	JAN 16,2007	ADDITIONS: MAJOR / MINOR	Replac Existing Flat Fram Dormer Wi	312 MILFORD-MT PLEA ROAD BERNHARDT, KARL W & KATI	AUG 28,2007	H Assessable
23	8.01		1020-2006-018	MAR 14,2006	MAY 15,2006	SEWER CONNECTION	Replace Exsiting Sewer Line	322-324 MILF-DT PLEA RD UBEL, JAMES & HEIDI		H Not Assessable
23	9		1020-1998-072	NOV 9,1998	JAN 5,2000	RENOVATIONS: MAJOR/SMALL		298 HILLCREST DRIVE KLAPPER, RICHARD & TERES	SEP 27,2000	H Not Assessable
23	9		1020-2002-051	JUL 23,2002	JAN 16,2003	ELECTRICAL		298 HILLCREST DRIVE KLAPPER, RICHARD & TERES		H Not Assessable
23	9		1020-2006-061	NOV 17,2006	DEC 28,2006	ROOFING		298 HILLCREST DRIVE KLAPPER, RICHARD & TERES		H Not Assessable
23	10		1020-1992-002+D	JUL 10,1992	SEP 18,1992	POOL INGROUND: VINYL	? Above ground or not?	302 MILFORD-MT PLEA ROAD STYS, JOHN JR & NANCY		H
Block	24									
24	1		1020-2005-046	AUG 25,2005	SEP 20,2005	RADON SYSTEM		290 HILLCREST DRIVE SMITH CHRISTOPHER / KATH		H Not Assessable
24	1.01		1020-2008-034	JUN 19,2008	JAN 13,2009	SHED: SMALL (< 200 SF)	Shed 10 X 18	2 POND LANE PONIATOWSKI, JUDY		H Not Assessable
24	1.01		1020-2009-010	APR 27,2009		TANK REMOVAL	Removal Of Underground 550 Gal Oil T	2 POND LANE PONIATOWSKI, JUDY		H Not Assessable
24	1.01		1020-2009-011	APR 27,2009		TANK INSTALLED INTERIOR	Install 275 Gal Interio Oil Tank	2 POND LANE PONIATOWSKI, JUDY		H Not Assessable
24	2		1020-2004-065	SEP 15,2004	MAY 13,2005	HEATING		35 FAIRVIEW AVENUE STANLEY, MARK & IRENE DEI		H Not Assessable
24	5		1020-1995-017	MAY 2,1995	SEP 26,1995	HEATING	Install weil-Mclean	11 MYRTLE AVENUE STELLE, LEROY E	SEP 26,1995	H
24	5		1020-1996-010	MAR 26,1996	JUL 30,1996	GARAGES: ATTACH / DETACH	24 X 40 Garage	11 MYRTLE AVENUE STELLE, LEROY E	SEP 28,1996	H

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
24	5.01		1020-2002-070	JUL 2,2002	FEB 4,2003	HEATING		13 MYRTLE AVENUE MAIER, RUTH		H Not Assessable
24	6		1020-1995-002	MAY 19,1995	MAY 26,1995	RADON SYSTEM		41 FAIRVIEW AVENUE GAUDELLI, WILLIAM III & C		H
24	6		1020-1995-026	JUN 12,1995	JUN 12,1995	ELECTRICAL	Circuits Inside House	41 FAIRVIEW AVENUE GAUDELLI, WILLIAM III & C		H
24	6		1020-1996-056	OCT 31,1996	SEP 8,1997	ELECTRICAL		41 FAIRVIEW AVENUE GAUDELLI, WILLIAM III & C	SEP 8,1997	H
24	6		1020-2001-047	JUN 22,2001	AUG 1,2002	MAINTENANCE:(roofing,etc)		41 FAIRVIEW AVENUE WELSH, SUSAN C		H Not Assessable
24	6		1020-2002-050	JUL 1,2002		TANK INSTALLED INTERIOR		41 FAIRVIEW AVENUE WELSH, SUSAN C		H Not Assessable
24	6		1020-2003-059	AUG 22,2003	JAN 6,2004	HEATING	Replacement	41 FAIRVIEW AVENUE WELSH, SUSAN C		H Not Assessable

Block **25**

25	1		1020-1998-032	JUN 15,1998		AIR CONDITIONING	Pro Loc 16 Myrtle Ave	16 FAIRVIEW AVENUE HOPKINS, ROBERT E JR & JE	SEP 23,1998	H Assessable
25	1		1020-2001-063+A	NOV 8,2001		ELECTRICAL		16 MYRTLE AVENUE HOPKINS, ROBERT E JR & JE		H Not Assessable
25	1		1020-2003-080+A	MAR 20,2003	JAN 9,2004	ELECTRICAL		16 MYRTLE AVENUE HOPKINS, ROBERT E JR & JE		H Not Assessable
25	1		1020-2002-080	NOV 14,2002	OCT 3,2003	POOLS INGROUND: F / G / V	23 X 38 Vinly	16 MYRTLE AVENUE HOPKINS, ROBERT E JR & JE	SEP 3,2004	H Assessable
25	5		1020-1998-070	NOV 6,1998	APR 26,1999	GARAGES: Attach / Detach		49 FAIRVIEW AVENUE PURSELL, DOUGLAS R	SEP 14,1999	H Assessable
25	5		1020-2001-010	FEB 26,2001	MAR 1,2002	ELECTRICAL	Replace Service Cables Etc	49 FAIRVIEW AVENUE PURSELL, DOUGLAS R		H Not Assessable
25	5		1020-2002-085	DEC 11,2002	DEC 2,2003	SIDING: VINYL / WOOD		49 FAIRVIEW AVENUE PURSELL, DOUGLAS R	SEP 3,2004	H Assessable
25	5		1020-2004-011+A	FEB 23,2004	APR 20,2004	TANK INSTALLED INTERIOR		49 FAIRVIEW AVENUE PURSELL, DOUGLAS R		H Not Assessable
25	5		2004-1020-0011.A	FEB 23,2004		TANK REMOVAL		49 FAIRVIEW AVENUE PURSELL, DOUGLAS R		H Not Assessable
25	6		1020-1999-035	AUG 2,1999	AUG 16,1999	ELECTRICAL		10 MYRTLE AVENUE SANTANIELLO, PHILIP III &		H Not Assessable
25	7		1020-1991-011	MAY 28,1991	JUL 30,1991	WOOD DECK / CONCR. PATIO	REBUILD DECK	12 MYRTLE AVENUE MYERS, DOLORES O & WAYN		H
25	7		1020-1992-007	OCT 27,1992		MAINTENANCE: (roofing)	Re-Roofing	12 MYRTLE AVENUE MYERS, DOLORES O & WAYN		H
25	7		1020-2005-090	MAR 2,2005		ELECTRICAL		12 MYRTLE AVENUE MYERS, DOLORES O & WAYN		H Not Assessable
25	7		1020-2005-009	MAR 11,2005	APR 4,2005	ELECTRICAL		12 MYRTLE AVENUE MYERS, DOLORES O & WAYN		H Not Assessable

Block **26**

26	1		1020-1997-031	JUN 9,1997	SEP 8,1997	RADON SYSTEM		63 FAIRVIEW AVENUE COLE ANDREW J / HEATHER	SEP 8,1997	H
----	---	--	---------------	------------	------------	--------------	--	---	------------	---

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
26	1		1020-2001-063	AUG 17,2001	JAN 1,2002	GARAGES: Attach / Detach	2 Car Garage & Storage Bldg	63 FAIRVIEW AVENUE COLE, ANDREW J & HEATHEF	SEP 28,2002	H Assessable
26	1		1020-2004-017	MAR 25,2004	MAY 13,2005	ADDITIONS: MAJOR / MINOR	Cc-1s-S W/ 2 Skylites	63 FAIRVIEW AVENUE COLE, ANDREW J & HEATHEF	SEP 13,2005	H Assessable
26	1		1020-2004-017+A	JUL 20,2004		MAINTENANCE:(roofing,etc)		63 FAIRVIEW AVENUE COLE, ANDREW J & HEATHEF		H Not Assessable
26	3		1020-1995-048	SEP 8,1995	OCT 12,1995	AIR CONDITIONING	.	23 EAST SIDE STREET HUBER, DOUGLAS A & JANET	SEP 28,1996	H
26	4		1020-1992-001	APR 21,1992	SEP 18,1992	RENOVATION; SMALL	KITCHEN REMODELING NEW CABINET	71 FAIRVIEW AVENUE FENWICK, JOHN D III & LIS		H
26	4		1020-2005-036	JUL 19,2005	JAN 30,2006	RADON SYSTEM		71 FAIRVIEW AVENUE ZAMBRANO, FERNANDO		H Not Assessable
Block	27									
27	1.01		1020-2001-034	MAY 16,2001	MAR 11,2002	NEW----RESIDENCE	Modular House	81 FAIRVIEW AVENUE WISCHNER, KENNETH	SEP 28,2002	H Assessable
27	1.01		1020-2001-034+A	SEP 12,2001		WOOD DECK	18 X 12	81 FAIRVIEW AVENUE WISCHNER, KENNETH	SEP 28,2002	H Assessable
27	1.01		1020-2002-034	FEB 11,2002		ELECTRICAL		81 FAIRVIEW AVENUE WISCHNER, KENNETH		H Not Assessable
27	1.02		1020-2001-085	DEC 10,2001	FEB 26,2003	NEW----RESIDENCE		83 FAIRVIEW AVENUE WINCHOCK, JOSEPH	APR 1,2003	H Assessable
27	1.02		1020-2004-035	MAY 12,2004	OCT 28,2004	POOL: ABOVE GROUND		83 FAIRVIEW AVENUE WINCHOCK, JOSEPH		H Not Assessable
27	1.02		1020-2007-063	SEP 28,2007	OCT 27,2008	BATHROOM	Rough In Present	83 FAIRVIEW AVENUE WINCHOCK, JOSEPH		Assessable
27	2		1020-1998-071	NOV 6,1998	DEC 8,1998	MAINTENANCE:(roofing,etc)		77 FAIRVIEW AVENUE HAMPTON, FRANK R		H Not Assessable
27	2		1020-2002-007	JAN 24,2002		CARPORTS: ATTACH / DETACH		77 FAIRVIEW AVENUE HAMPTON, FRANK R		H Assessable
27	2		1020-2006-006	FEB 3,2006	APR 28,2006	RADON SYSTEM		77 FAIRVIEW AVENUE MATTIOLI, JOSEPH		H Not Assessable
27	2		1020-2006-007	FEB 8,2006	MAY 4,2006	ROOFING		77 FAIRVIEW AVENUE MATTIOLI, JOSEPH		H Not Assessable
27	2		1020-2006-008	FEB 9,2006	APR 27,2006	SIDING: VINYL / WOOD		77 FAIRVIEW AVENUE MATTIOLI, JOSEPH	SEP 8,2006	H Assessable
27	2		1020-2006-002	FEB 17,2006	JAN 16,2007	ELECTRICAL	Switch For Furnace	77 FAIRVIEW AVENUE MATTIOLI, JOSEPH		H Not Assessable
27	2		1020-2006-008+A	FEB 21,2006		PENALTY		77 FAIRVIEW AVENUE MATTIOLI, JOSEPH		H Not Assessable
27	2		1020-2006-002+A	JAN 11,2006	JAN 16,2007	ELECTRICAL		77 FAIRVIEW AVENUE MATTIOLI, JOSEPH		H Not Assessable
27	2		1020-2006-062	MAR 17,2006	JAN 4,2007	ELECTRICAL		77 FAIRVIEW AVENUE MATTIOLI, JOSEPH		H Not Assessable
27	2		1020-2007-069	NOV 8,2007	JAN 24,2008	MISC ITEMS		77 FAIRVIEW AVENUE WALCK, JEANINE M		H Not Assessable
27	2		1020-2007-067	OCT 12,2007		WOOD DECK		77 FAIRVIEW AVENUE WALCK, JEANINE M	SEP 3,2008	X Assessable

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
27	3		1020-2000-021	JUL 5,2000	JUL 5,2000	FIRE / SMOKE DETECTOR		24 EAST SIDE STREET GOOD, RAYMOND		H Not Assessable
27	3		1020-2006-014	MAR 3,2006	APR 20,2007	HOT WATER HEATER		24 EAST SIDE STREET GOOD, RAYMOND W & ELEAN		H Not Assessable
Block 28										
28	1		1020-1993-006+C	SEP 17,1993	FEB 28,1995	ASSESSMENT DATA REVIEW---	Review assessment	200 HILLCREST DRIVE SLOFF, RICHARD & SANDRA		H
28	1		1020-2002-001	JAN 3,2002	FEB 4,2002	WOOD STOVE (PELLET)		203 HILLCREST DRIVE APPELLO, PATRICK II & MAR		H Not Assessable
28	1		1020-2005-070	NOV 21,2005	JAN 23,2007	ELECTRICAL		200 HILLCREST DRIVE HENDRY, CHRISTIAN W		H Not Assessable
28	2		1020-1993-004+E	AUG 10,1993	SEP 15,1993	AIR CONDITIONING		220 HILLCREST DRIVE KINNEY, DORIS M		H
28	2		1020-1993-004+G	AUG 1,1993	SEP 15,1993	AIR CONDITIONING		220 HILLCREST DRIVE KINNEY, DORIS M		H
28	2		1020-2006-019	MAR 21,2006		SIDING: VINYL / WOOD		220 HILLCREST DRIVE HITCHCOCK BRIAN / ALLISON	AUG 28,2007	X Assessable
28	3		1020-1993-001+C	MAR 18,1993	SEP 27,1994	MAINTENANCE:(roofing,etc)	Radon	230 HILLCREST DRIVE CHIOFFE, HARRY R JR & PAT		H
28	3		1020-1994-001+K	APR 23,1994	SEP 27,1994	SHEDS: LARGE / SMALL	Shed	230 HILLCREST DRIVE CHIOFFE, HARRY R JR & PAT		H
28	3		1020-2003-030	MAY 30,2003		AIR CONDITIONING	Air Conditioner	230 HILLCREST DRIVE CHIOFFE, HARRY R JR & PAT	SEP 22,2003	H Assessable
28	3		1020-2003-029	MAY 30,2003	JUL 11,2005	ELECTRICAL		230 HILLCREST DRIVE MAYERSKY, JEFFREY S & DA'		H Not Assessable
28	3		1020-2004-021	APR 19,2004	JUL 7,2004	TANK INSTALLED INTERIOR		230 HILLCREST DRIVE MAYERSKY, JEFFREY S & DA'		H Not Assessable
28	3		1020-2004-022	APR 19,2004	JUN 21,2004	TANK REMOVAL		230 HILLCREST DRIVE MAYERSKY, JEFFREY S & DA'		H Not Assessable
28	4		1020-2002-010	JAN 31,2002	MAR 1,2002	ELECTRICAL		238 HILLCREST DRIVE POLINSKI, RICHARD E		H Not Assessable
28	5		1020-1994-001+D	MAR 30,1994	APR 1,1994	ASSESSMENT DATA REVIEW---	Reshingle roof w/ dimensional	244 HILLCREST DRIVE LEILI, MARTIN J & GLORIA		H
28	5		1020-1997-064	DEC 16,1997	SEP 23,1998	SIDING: VINYL / WOOD	Siding / Gutters	244 HILLCREST DRIVE LEILI, MARTIN J & GLORIA	SEP 23,1998	H
28	5		1020-1998-001	JAN 6,1998	SEP 22,1998	TANK INSTALLED INTERIOR	Replace Basement Home Heating	244 HILLCREST DRIVE LEILI, MARTIN J & GLORIA		H
28	5		1020-2005-042	AUG 5,2005	SEP 1,2005	ELECTRICAL		244 HILLCREST DRIVE LEILI, MARTIN J & GLORIA		H Not Assessable
28	9		1020-1994-802+A	JAN 14,1994	JAN 25,1994	ELECTRICAL	electrical upgrade	266 HILLCREST DRIVE DEZZI, DIANE M		H
28	9		1020-1998-075	NOV 19,1998	MAR 19,1999	SHEDS: LARGE / SMALL		266 HILLCREST DRIVE DEZZI, DIANE M	SEP 14,1999	H Not Assessable
28	10		1020-2007-011	MAR 14,2007		ELECTRICAL	Water Heater, Whirlpool Tub Recetp	36 FAIRVIEW AVENUE VAN ESS, DAVID L		H Not Assessable
28	10		1020-2008-047	AUG 20,2008	NOV 6,2008	AIR CONDITIONING	Heater / Air Conditioner Replacemen	36 FAIRVIEW AVENUE STANIELS, CARRIE & CHARLE	SEP 3,2008	H Assessable

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
28	12		1020-1994-005+A	DEC 5,1994	DEC 19,1994	MAINTENANCE:(roofing,etc)	.	50 FAIRVIEW AVENUE RIKER, JAMES M / SAMMOND.		H
28	12		1020-1996-017	APR 17,1996	SEP 27,1996	SHEDS: LARGE / SMALL	Construct Shed 16x10	50 FAIRVIEW AVENUE RIKER, JAMES M / SAMMOND.	SEP 27,1996	H
28	12		1020-1999-025	JUN 14,1999		ADDITIONS: MAJOR / MINOR	2nd Floor Addition	50 FAIRVIEW AVENUE RIKER JAMES M / SAMMOND I		H Assessable
28	12		1020-2000-028+A	SEP 8,2000		ADDITIONS: MAJOR / MINOR	2nd Floor Addition	50 FAIRVIEW AVENUE RIKER JAMES M / SAMMOND I		H Assessable
28	12		1020-2002-025+A	JUN 12,2002		PORCH: ENCLOSED / OPEN	Same Size?	50 FAIRVIEW AVENUE RIKER JAMES M / SAMMOND I		H Assessable
28	12		1020-2003-0078	OCT 30,2003		HEATING		50 FAIRVIEW AVENUE RIKER JAMES M / SAMMOND I		H Not Assessable
28	13		1020-1991-014+A	AUG 30,1991	SEP 18,1992	SHED: SMALL	SHED: SIZE ?	36 BRIAN STREET GREENE, VINCENT R		H
28	13		1020-1992-002+A	JUL 17,1992	SEP 18,1992	HEATING	Replace OHW Boiler	36 BRIAN STREET GREENE, VINCENT R		H
28	13		1020-1992-002+H	JUL 17,1992	SEP 18,1992	HEATING	Replace OHW Boiler	36 BRIAN STREET GREENE, VINCENT R		H
28	14		1020-1994-050	OCT 11,1994	JAN 27,1995	HEATING	Replace HWBB heater	32 BRIAN STREET FIEBIG, J DOUGLAS & LAURI	SEP 26,1995	H
28	14		1020-2000-047	OCT 20,2000	DEC 5,2000	MAINTENANCE:(roofing,etc)		32 BRIAN STREET FIEBIG, J DOUGLAS & LAURI		H Not Assessable
28	14		1020-2001-016	MAR 12,2001	APR 20,2001	TANK INSTALLED INTERIOR		32 BRIAN STREET FIEBIG, J DOUGLAS & LAURI		H Not Assessable
28	14		1020-2001-042	JUN 8,2001	JAN 21,2005	ADDITIONS: MAJOR / MINOR		32 BRIAN STREET FIEBIG, LAURIE A	SEP 27,2001	H Assessable
28	14		1020-2002-042	JUL 8,2002		POOL: ABOVE GROUND		32 BRIAN STREET FIEBIG, J DOUGLAS & LAURI		H Not Assessable
28	14		1020-2003-053	AUG 11,2003	SEP 4,2003	ELECTRICAL		32 BRIAN STREET FIEBIG, J DOUGLAS & LAURI		H Not Assessable
28	15		1020-2005-0034	JUN 30,2005		ADDITIONS: MAJOR / MINOR	No Detail On Permit Who Knows What	28 BRIAN STREET O'GURKIS, MARK J & KELLY		H Not Assessable
28	16		1020-1992-002+B	JUN 15,1992	AUG 30,1992	WOOD DECK / CONCR. PATIO	Pressure treated deck with 10x18	24 BRIAN STREET BRENNAN, WILLIAM F JR & M		H
28	16		1020-2000-010	APR 10,2000	JUL 12,2000	AIR CONDITIONING		24 BRIAN STREET BRENNAN, WILLIAM F JR & M	SEP 27,2000	H Assessable
28	16		1020-2002-058	SEP 17,2002	JAN 21,2005	MAINTENANCE:(roofing,etc)		24 BRIAN STREET HUNTER ALYSON / JOSEPH P		H Not Assessable
28	16		1020-2004-045	JUL 7,2004	OCT 1,2004	ELECTRICAL		24 BRIAN STREET HUNTER ALYSON / JOSEPH P		H Not Assessable
28	17		1020-1992-001+D	APR 24,1992	SEP 19,1992	MAINTENANCE: (roofing)	Replace shingles on roof of house	20 BRIAN STREET COLE, DANNY E		H
28	17		1020-1996-034	JUN 7,1996	JUL 15,1999	AIR CONDITIONING	Air Conditioning	20 BRIAN STREET COLE, DANNY E	SEP 28,1996	H Assessable
28	17		1020-1998-036+A	JUN 25,1998	JUN 25,1998	HEATING		20 BRIAN STREET COLE, DANNY E		H

Block **28.01**

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
28.01	1		1020-2007-103	JUN 6,2007		ELECTRICAL	Update Subpanel	58 FAIRVIEW AVENUE SINKUS, JOSEPH F II		H Not Assessable
28.01	2		1020-1992-004+D	NOV 20,1992	JUN 30,1993	WOOD DECK / CONCR. PATIO	Deck	62 FAIRVIEW AVENUE SUNDAY, DOUGLAS M		H
28.01	2		1020-1996-063	DEC 9,1996	SEP 8,1997	HEATING	Thermo Pride Furnace	62 FAIRVIEW AVENUE SUNDAY, DOUGLAS M	SEP 8,1997	H
28.01	3		1020-1995-901	JUN 1,1995		ASSESSMENT DATA REVIEW---	check 1 story w/ fin attic	66 FAIRVIEW AVENUE BOLMER, CHARLES	SEP 26,1995	H
28.01	3		1020-2008-048	SEP 5,2008		SIDING: VINYL / WOOD	.	66 FAIRVIEW AVENUE BOLMER EST MARGERY C/O.		Assessable
28.01	5		1020-2008-003	JAN 25,2008	FEB 18,2009	TANK REMOVAL	.	78 FAIRVIEW AVENUE WHITMAN, HARRY		H Not Assessable
28.01	5		1020-2008-004	JAN 28,2008		TANK INSTALLED INTERIOR		78 FAIRVIEW AVENUE WHITMAN, HARRY		H Not Assessable
28.01	6		1020-1995-012	APR 10,1995	AUG 30,1995	GARAGES: ATTACH / DETACH	.	FAIRVIEW AVENUE WHITMAN, HARRY & ETHEL	SEP 26,1995	H
28.01	6		1020-1995-012+A	DEC 26,1995		ELECTRICAL	Receptacles / Service Change	FAIRVIEW AVENUE WHITMAN, HARRY & ETHEL		H
28.01	7		1020-2003-047	JUL 15,2003	NOV 29,2005	HEATING	Replace Hot Water Heater	86 FAIRVIEW AVENUE WEINSTEIN, STEPHEN J & MA		H Not Assessable
28.01	8		1020-2003-024	MAY 2,2003	APR 19,2004	ADDITIONS: MAJOR / MINOR	Wood Deck To Come	21 JOHN LELO AVENUE CANTILINA, JEREMY & EMILY	SEP 13,2005	H Assessable
28.01	8		1020-2007-039	JUN 28,2007	OCT 2,2007	TANK INSTALLED INTERIOR		21 JOHN LELO AVENUE CANTILINA, JEREMY & EMILY		H Not Assessable
28.01	8		1020-2007-038	JUN 28,2007	JAN 7,2008	TANK REMOVAL		21 JOHN LELO AVENUE CANTILINA, JEREMY & EMILY		H Not Assessable
28.01	8		1020-2008-018	MAY 1,2008		BATHROOM	1/2 Bathroom, Laundry Room	21 JOHN LELO AVENUE CANTILINA, JEREMY & EMILY		Assessable
28.01	9		1020-2000-031	JUN 29,2000	AUG 18,2000	HEATING		17 JOHN LELO AVENUE HORSTMANN, LELAND C & LII		H Not Assessable
28.01	9		1020-2003-001	OCT 9,2003	JUL 5,2007	BASEMENT FINISHED	Basement Finished Into Bedroom &	17 JOHN LELO AVENUE HORSTMANN, LELAND C & LII		H Assessable
28.01	10		1020-1994-0 +E	FEB 14,1994	MAR 29,1994	HEATING	.	13 JOHN LELO AVENUE FLECK, WILLIAM		H
28.01	10		1020-2002-076	OCT 29,2002	DEC 20,2002	MAINTENANCE:(roofing,etc)		13 JOHN LELO AVENUE FLECK, WILLIAM		H Not Assessable
28.01	11		1020-1993-003+H	JUN 28,1993	AUG 30,1993	PATIO	PATIO W/ FOUNDATION 17 X 20	9 JOHN LELO AVENUE MUSCHLITZ, PATRICIA		H
28.01	11		1020-1995-010	MAR 17,1995	APR 11,1995	PLUMBING WORK	replace 3 bath fixtures	9 JOHN LELO AVENUE MUSCHLITZ, PATRICIA	SEP 26,1995	H
28.01	14		1020-2005-060	OCT 13,2005	MAY 11,2006	RADON SYSTEM		27 BRIAN STREET KIEFFER, TIMOTHY S & KELL		H Not Assessable
28.01	15		1020-1993-001+I	APR 20,1993	JUL 30,1993	PORCH: ENCLOSED / OPEN	Screen in ??	4 JOHN LELO AVENUE FRICK, CARL F & DEBBE J		H
28.01	15		1020-1999-016	JUN 1,1999	JUN 28,1999	MAINTENANCE:(roofing,etc)		4 JOHN LELO AVENUE FRICK, CARL F & DEBBE J		H Not Assessable
28.01	15		1020-2001-014	MAR 9,2001	APR 2,2001	TANK INSTALLED INTERIOR		4 JOHN LELO AVENUE ROYE, JEFFREY D & KATHLEI		H Not Assessable

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
28.01	16		1020-1998-004	JAN 27,1998	SEP 22,1998	HEATING	Replace Boiler W/Weil Mclain	8 JOHN LELO AVENUE PETRO, PAUL		H
28.01	16		1020-2000-033	AUG 4,2000	AUG 8,2001	AIR CONDITIONING	Install 2.5 Central Air Condition	8 JOHN LELO AVENUE PETRO, PAUL	SEP 27,2001	H Assessable
28.01	17		1020-1993-0 +G	JAN 26,1993		HEATING	Replace Boiler and water heater	12 JOHN LELO AVENUE CAPPEL, EUGENE F		H
28.01	17		1020-2006-009	FEB 15,2006	SEP 28,2006	ELECTRICAL	Hot Tub	12 JOHN LELO AVENUE GALLO, MICHAEL		H Not Assessable
28.01	17		1020-2007-001	JAN 1,2007	JAN 25,2007	PLUMBING WORK	Hot Tub On Existing Deck	12 JOHN LELO AVENUE GALLO, MICHAEL		H Not Assessable
28.01	20		1020-2001-043	JUN 12,2001	SEP 10,2002	POOL: ABOVE GROUND		24 JOHN LELO AVENUE CORRIGAN, MICHAEL & NORE		H Not Assessable
28.01	20		1020-2001-043+A	AUG 14,2001		ELECTRICAL		24 JOHN LELO AVENUE CORRIGAN, MICHAEL & NORE		H Not Assessable
28.01	20		1020-2002-043+A	MAY 10,2002		POOL: ABOVE GROUND	Wood Deck 11 X 12	24 JOHN LELO AVENUE CORRIGAN, MICHAEL & NORE	SEP 22,2003	H Not Assessable
28.01	20		1020-2002-071+A	OCT 22,2002		MAINTENANCE:(roofing,etc)		24 JOHN LELO AVENUE CORRIGAN, MICHAEL & NORE		H Not Assessable
28.01	22		1020-2002-044	JUL 10,2002		HEATING		17 BRIAN STREET SASSAMAN, KATHLEEN	NOV 1,2002	H Not Assessable
28.01	22		1020-2004-070	OCT 15,2004	JAN 5,2005	RADON SYSTEM		17 BRIAN STREET SASSAMAN, KATHLEEN		H Not Assessable
28.01	22		1020-2008-017	APR 24,2008	MAY 14,2008	ROOFING		17 BRIAN STREET SASSAMAN, KATHLEEN		H Not Assessable
28.01	23		1020-1991-010	MAY 22,1991	JUN 30,1991	AIR CONDITIONING	AIR CONDITIONING	23 BRIAN STREET JACANGELO, ANNIS N		H
28.01	23		1020-1998-025	JUN 2,1998	JUN 2,1998	WATER SERVICE	Repair Water Line	23 BRIAN STREET JACANGELO, ANNIS N		H
Block	29									
29	1		1020-1992-033	SEP 1,1992	MAR 8,2001	RENOVATIONS: MAJOR/SMALL	Replace flat roof w/ pitch roof	60 POND LANE SAAM, FRANK S & ANTOINET	SEP 26,1995	H Assessable
29	1		1020-2006-005	FEB 3,2006	FEB 23,2006	ELECTRICAL		60 POND LANE SAAM, FRANK S & ANTOINET		H Not Assessable
29	1		1020-2006-013	FEB 27,2006	APR 2,2007	ELECTRICAL	Generator Transfer Switch	60 POND LANE SAAM, FRANK S & ANTOINET		H Not Assessable
29	1.01		1020-2004-027	MAR 29,2004	JUN 2,2004	TANK REMOVAL		104 HILLCREST DRIVE GOMBOSI, ELMER A & FRANCO		H Not Assessable
29	1.01		1020-2004-028	MAR 29,2004	MAY 12,2004	TANK INSTALLED INTERIOR		104 HILLCREST DRIVE GOMBOSI, ELMER A & FRANCO		H Not Assessable
29	2		1020-1993-901+B	MAR 10,1993	JUL 22,1993	NEW----RESIDENCE	Single Family dwelling	91 FAIRVIEW AVENUE REZES, JOHN W & SHANNON	SEP 25,1993	H Assessable
29	2		1020-1993-002+B	JUN 10,1993	JUL 22,1993	WOOD DECK / CONCR. PATIO	WOOD DECK AND SHED	91 FAIRVIEW AVENUE BECKER, EDWARD & GLORIA		H
29	2		1020-2000-016	MAY 14,2000	APR 20,2001	POOL: ABOVE GROUND		91 FAIRVIEW AVENUE REZES, JOHN W & SHANNON		H Not Assessable
29	2		1020-2002-083	DEC 9,2002	SEP 21,2005	ADDITIONS: MAJOR / MINOR	Bedroom Addition	91 FAIRVIEW AVENUE REZES, JOHN W & SHANNON	SEP 8,2006	H Assessable

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
29	2		1020-2005-083	SEP 12,2005		ELECTRICAL		91 FAIRVIEW AVENUE REZES, JOHN W & SHANNON		H Not Assessable
29	2.01		1020-1994-021	MAY 19,1994	OCT 5,1995	NEW---RESIDENCE		101 FAIRVIEW AVENUE BRUNING, THOMAS P & BARE	SEP 28,1996	H
29	2.01		1020-1994-021+A	MAY 19,1994	OCT 5,1995	PRIOR ASSESSMENT RECORD		101 FAIRVIEW AVENUE BRUNING, THOMAS P & BARE		H
29	2.01		1020-1994-094+A	DEC 12,1994	SEP 25,1995	ELECTRICAL		101 FAIRVIEW AVENUE BRUNING, THOMAS P & BARE	SEP 27,1995	H
29	2.01		1020-1997-030	MAY 29,1997	DEC 30,1997	PORCH: ENCLOSED / OPEN	Enclosed Porch	101 FAIRVIEW AVENUE BRUNING, THOMAS P & BARE		H Not Assessable
29	2.01		1020-1998-048	JUL 30,1998	JAN 6,1999	MAINTENANCE:(roofing,etc)		101 FAIRVIEW AVENUE BRUNING, THOMAS P & BARE		H Not Assessable
29	2.01		1020-2004-018	MAR 29,2004		TANK INSTALLED INTERIOR		101 FAIRVIEW AVENUE BRUNING, THOMAS P & BARE		H Not Assessable
29	2.01		1020-2008-025	MAY 14,2008		HEATING		101 FAIRVIEW AVENUE MURRAY, ROBERT M & DOLO		H Not Assessable
29	2.02		1020-1998-012	MAR 18,1998	AUG 16,1999	ADDITIONS: MAJOR / MINOR	Glazed Porch	111 FAIRVIEW AVENUE SETCAVAGE, THOMAS M & DI	SEP 23,1998	H Assessable
29	2.03		1020-2001-135	OCT 1,2001	JAN 14,2002	WOOD DECK		121 FAIRVIEW AVENUE HUZAR SEAN M / MELISSA M	SEP 28,2002	H Not Assessable
29	2.04		1020-2007-052	AUG 22,2007	OCT 16,2007	AIR CONDITIONING		110 FAIRVIEW AVENUE HENRY, JAMES IV & PATRICI		H Not Assessable
29	2.04		1020-2008-068	DEC 18,2008	JAN 12,2009	HEATING	Replace Gas Hot Air Furnace	110 FAIRVIEW AVENUE HENRY, JAMES IV & PATRICI		H Not Assessable
29	2.06		1020-1999-046	NOV 10,1999	SEP 1,2000	POOL: ABOVE GROUND	Wood Deck	120 FAIRVIEW AVENUE VILLAS, MARK E AND ELISA	SEP 27,2000	H Assessable
29	3		1020-1995-051	SEP 19,1995	NOV 14,1995	MAINTENANCE:(roofing,etc)		106 HILLCREST DRIVE RIDDLE, ARTHUR		H
29	4		1020-1993-001	APR 23,1993	SEP 27,1993	SHEDS: LARGE / SMALL	Shed: 8 x 10	110 HILLCREST DRIVE WOOLF, DOROTHY P		H
29	4		1020-1994-026	JUN 16,1994	SEP 13,1994	AIR CONDITIONING		110 HILLCREST DRIVE WOOLF, DOROTHY P	SEP 26,1995	H
29	4		1020-2002-029	MAY 28,2002	MAY 10,2006	ELECTRICAL		110 HILLCREST DRIVE WOOLF, KENT & ROBIN		H Not Assessable
29	5		1020-1991-013+B	AUG 13,1991	SEP 18,1992	RENOVATION; SMALL	NEW BATHROOM; FIXTURES, ETC	128 HILLCREST DRIVE REHL, RONALD R & DENISE M		H
29	5		1020-2000-025	JUN 13,2000		AIR CONDITIONING		128 HILLCREST DRIVE REHL, RONALD R & DENISE M	SEP 27,2000	H Assessable
29	5		1020-2000-044+A	SEP 29,2000		WOOD DECK / CONCR PATIO		128 HILLCREST DRIVE REHL, RONALD R & DENISE M	SEP 27,2001	H Assessable
29	5		1020-2006-030	MAY 24,2006	JUL 12,2006	ROOFING		128 HILLCREST DRIVE REHL, RONALD R & DENISE M		H Not Assessable
29	5		1020-2007-013	MAR 19,2007	MAR 29,2007	SIDING: VINYL / WOOD		128 HILLCREST DRIVE REHL, RONALD R & DENISE M	AUG 28,2007	X Assessable
29	6		1020-1995-029	JUL 19,1995	JUL 19,1995	MAINTENANCE:(roofing,etc)		132 HILLCREST DRIVE SHAW DIANE / PHILLIPS MER	SEP 26,1995	H
29	6		1020-1995-029+A	JUN 20,1995		MAINT: (Roofing, etc)		132 HILLCREST DRIVE SHAW, DIANE / PHILLIPS, M		H

Block	Lot	Qual	Permit #	Permit Date	Cert of Occ Date OR Cert of Appr Date	Type of Permit	Description of work	Location Owner	Assessor Inspected	History File
29	6		1020-2004-046	JUL 15,2004	SEP 20,2004	TANK INSTALLED INTERIOR		132 HILLCREST DRIVE APPELLO, PATRICK II & MAR		H Not Assessable
29	6		1020-2004-047+A	JUL 15,2004	SEP 9,2004	TANK REMOVAL		132 HILLCREST DRIVE APPELLO, PATRICK II & MAR		H Not Assessable
29	6.01		1020-1996-045	AUG 6,1996	JUL 14,1997	MAINTENANCE:(roofing,etc)		130 HILLCREST DRIVE DZURY, RICHARD J		H
29	6.02		1020-1999-049	NOV 19,1999	MAR 1,2000	MAINTENANCE:(roofing,etc)		191 FRENCHTOWN ROAD SLAWSON, RONDA J		H Not Assessable
29	7		1020-2005-022	MAY 24,2005		PLUMBING WORK		117 HILLCREST DRIVE SARA, KEITH D & LORI-JEAN	SEP 13,2005	H Assessable
29	7		1020-2008-026	MAY 16,2008		ADDITIONS: MAJOR / MINOR		117 HILLCREST DRIVE SARA, KEITH D & LORI-JEAN		Assessable
29	7		1020-2008-026+A	OCT 6,2008		GAS PIPING		117 HILLCREST DRIVE SARA, KEITH D & LORI-JEAN		H Not Assessable
29	7		1020-2008-058	OCT 14,2008		TANK INSTALLED INTERIOR	Install 1 1000 Gal Oil Tank Undergr	117 HILLCREST DRIVE SARA, KEITH D & LORI-JEAN		H Not Assessable
29	7.01		1020-1997-011	MAR 19,1997	SEP 8,1997	MAINTENANCE:(roofing,etc)		187 FRENCHTOWN ROAD JIM'S AUTO BODY	SEP 8,1997	H
29	7.02		1020-1991-014+C	SEP 20,1991	SEP 18,1992	RENOVATION; SMALL	REPAIR ????	115 HILLCREST DRIVE EARLY, WILLIAM A & BEVERL		H
29	7.02		1020-1996-058	OCT 31,1996	MAR 12,1999	RADON SYSTEM		115 HILLCREST DRIVE EARLY, WILLIAM A & BEVERL	SEP 8,1997	H Not Assessable
29	7.02		1020-2007-064	OCT 2,2007	JAN 7,2009	SHED: LARGE		115 HILLCREST DRIVE EARLY, WILLIAM A & BEVERL	SEP 3,2008	H Assessable
29	8		1020-1992-003+B	SEP 11,1992	FEB 8,1993	HEATING	Replace D H W boiler	111 HILLCREST DRIVE PURSELL, FRANCIS		H
29	8		1020-2001-031	MAY 4,2001	MAR 10,2003	MAINTENANCE:(roofing,etc)		111 HILLCREST DRIVE PURSELL, FRANCIS		H Not Assessable
29	8		1020-2006-048	SEP 8,2006	SEP 14,2006	ELECTRICAL		111 HILLCREST DRIVE PURSELL, FRANCIS		H Not Assessable
29	9		1020-2002-012	FEB 21,2002	DEC 20,2002	HEATING		119-121 HILLCREST DRIVE COVINO, DAVID G & CYNTHIA		H Not Assessable
29	9		1020-2003-004	JAN 17,2003	FEB 10,2003	FIREPLACE / WOODSTOVE	Vermont Casting Wood Stove	119-121 HILLCREST DRIVE COVINO, DAVID G & CYNTHIA	SEP 22,2003	H Assessable
29	9.01		1020-1998-049	AUG 4,1998	OCT 21,1998	TANK INSTALLED INTERIOR		HILLCREST DRIVE MCNALLY, JOHN B		H Not Assessable
29	9.01		1020-2002-049	JUL 19,2002	NOV 13,2002	AIR CONDITIONING		101 HILLCREST DRIVE MCNALLY, JOHN B	JUL 15,2002	H Assessable
29	9.01		1020-2005-069	NOV 21,2005	APR 12,2006	ROOFING		101 HILLCREST DRIVE MCNALLY, JOHN B		H Not Assessable

of Permits: 1,404